

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		8		8		8			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044	1	6	1	6	1	6			
	Total	606	3055	1	17	1	17	1	17	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	4	1	4	1	4			
3	MDK	107	933									
4	SDPT			2	11	2	11	2	11			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	15	4	15	4	15	0	0	
	Grand Total	1082	6468	5	32	5	32	5	32	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Manthathi	33kv	Nagarkurnool	17.24	19.10	01.46	E/L	Insulator Failed at Desi Itikyala(V)	Manthathi	-
1	NLG	Ramapuram	Thogarrai	33kv	Huzurnagar	04.00	08.30	04.30	EL	Due to 33kv insulator failure	Thogarrai	-
1	SDPT	CHALDAPUR	Jakkapur	33kv	SIDDIPET	09.36	09.36	02.00		B/D due to gale & wind	Jakkapur	-
2		DUDEEDA	Bandaram	33kv	GAJWEL	04.19	12.28	02.34		Due to 33kv insulator failure	Bandaram	-
1	HYD C	132KV Patigadda	Indira Park (PTR-3,1&2)	33kv	Saifabad	13.10	13.20	00.10	OL-Yph	Tripped on OL	Indira Park (PTR-3,1&2)	Loads transferred onto 132KV Chilalguda - Indira Park

TSSPDCL - LMRC / Corporate office

Date: 12.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Ananthagiri	V.R.Puram	11kv	Huzurnagar	03.40	06.45	03.05	EL	Due to insulator failure	-
2		Kalmalcheruvu	Kalmalcheruvu	11kv	Huzurnagar	04.55	08.00	03.05	EL	Due to 11Kv jumper cutted	-
3		N.B.Gudem	Redlakunta	11kv	Huzurnagar	10.00	13.00	03.00	EL/OI	Due to insulator failure	-
4		Mukundapuram	Chandupatla	11kv	Suryapeta	06.00	08.45	02.45	EL	Insulator failed	-
1	SDPT	Husnabad	Pandilla	11kv	SIDDIPET	00.00	08.30	08.30		Insulator failure same rectified	-
2		Potharam	Keshawapoor	11kv	SIDDIPET	07.40	11.20	03.40		11KV line snapped, same rectified	-
3		Gouravelly	Gouravelly Town	11kv	SIDDIPET	04.00	12.30	08.30		Insulator failure same rectified	-
4		Ramchandrapur	Vinjalpally	11kv	SIDDIPET	14.05	14.30	00.25		Gale and Wind	-
5		Ramchandrapur	Ramchandrapur Rural	11kv	SIDDIPET	15.20	16.40	01.20		11KV line snapped, same rectified	-
6		Ramchandrapur	Varikolu	11kv	SIDDIPET	15.00	18.20	03.20		Insulator failure same rectified	-
7		Koheda	Cannal	11kv	SIDDIPET	11.00	17.05	06.05		Insulator failure same rectified	-
8		Koheda	Sriramulapally	11kv	SIDDIPET	11.00	13.30	02.30		Insulator failure same rectified	-
9		Nagapuri	Nagapuri	11kv	SIDDIPET	00.00	08.40	08.40		Insulator failure same rectified	-
10		Dhoolmitta	Jalapally	11kv	SIDDIPET	00.00	10.00	10.00		Insulator failure same rectified	-
11		Marmamula	Marmamula	11kv	SIDDIPET	07.08	10.00	02.52		Insulator failure same rectified	-
1	RR S	KPHB	JNTU	11kv	Kondapur	20.05	21.25	01.20		11kv Jumper cut at MRO Office	-
1	RR N	Vijaynagar	Shanthinagar	11kv	Kukatpally	16.00	17.00	01.00	EL	Due to Hevy Rain	-
2		Jeedimetla-IV	Tagoure	11kv	Jeedimetla	15.50	18.00	02.10	OL	11kv line AB Cable Endkit failure at Plastic Company , Tagoure Comapany	-
3		Aleap	Doctores Colony Cable	11kv	Jeedimetla	16.40	19.00	02.20	EL/OL	Tree Branchesh Fallen the 11kv line at Pragathi Nagar X Road	-
4		Aleap	Panchavati	11kv	Jeedimetla	16.40	18.00	01.20	EL	Jumper cut & Fallen the 11kv line at plot:271, Lekwey Colony	-
5		UMCC	RM Nagar	11kv	Medchal	04.20	04.55	00.35	OL	100KVA T/F AB Cable failed at NTR Nagar	-
6		Athiwelly	Dabeerpur	11kv	Medchal	18.10	18.45	00.35	EL	Tree fallen on the 11KV Line at Lingapur Village	-
7		Gowdawelly	Basaragadi	11kv	Medchal	09.30	11.00	01.30	EL/OL	11KV Pin Insulator failed at Nadanavanam, Basaragadi	-
8		Ravalkole	IDA Ganapathi	11kv	Medchal	16.30	17.30	01.00	EL/OL	Tree fallen on the 11KV Line at Sathoor Company	-
1	RR E	Mallapur-2	Surya Nagar	11kv	Habsiguda	14.47	16.24	01.37		11KV Disc failed near Sanjeeva Park	-
2		Nagaram	P S Rao Nagar	11kv	Keesara	07.30	10.14	02.44		11KV Jumper cut at Vikas Nagar & 11KV Brass patti cut at Water Plant	-
1	HYD N	Bansilalpet	Botany School	11kv	V	07.41	09.07	01.26	All Indication	R.M.U Cable fault near Railway Bridge	Arranged B/F on 11KV Gas Mandi feeder
2		Nehru Nagar	Contonment	11kv	C-VI	09.03	10.41	01.38	EL,OL-Bph	UG Cable fault at beside Court	Arranged B/F on 11KV West Marredpally fdr
3		Pragatools	L&T	11kv	VI	16.10	17.25	01.15	EL	No Visible Fault (due to Heavy Rain)	-----
4	Hyd S	Devi Bagh	Siddique Gulshan	11kv	III	16.59	19.00	02.01	EL	Conductor snapped near SS (due to Truck dashed to Pole)	-----
5		Jiyaguda	Dolphin Hotel	11kv	IX	23.23	00.27	01.04	EL,OL	Insulator flash over at Durga Nagar	-----
6	HYD C	Fever Hospital	Tourist Hotel	11kv	II	23.45	01.05	01.20	EL,OL-Rph	Disc flash over Sony Appartment	-----