

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		3		3		3			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		3		3				
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>3</b>	<b>3</b>	<b>3</b>	<b>3</b>	<b>3</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 15.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33KV	Narayanapet	13.52	15.57	02.05	E/L	Pin Insulator Replacment	Vepoor	-
2		Amanagl	Talakondapally	33KV	Shadnagar	11.10	12.10	01.00	O/L	Tree Fallen on the Line	Talakondapally	-
3		Kodangal	Hamsanpally	33KV	Vikarabad	17.20	22.10	04.50	E/L	Pin Insulator Replacement at Line	Hamsanpally	-

## TSSPDCL - LMRC / Corporate office

Date: 15.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	G.T Giri	Thirumalagiri Agl	11KV	Suryapeta	04.30	07.20	02.50	EL	Conductor snapped	-
2		N.B.Gudem	Redlakunta	11KV	Huzurnagar	07.15	10.20	03.05	EL/OL	Due to 11Kv Jumper cutted	-
3		Koyyalagudem	Thummalagudem	11KV	Choutuppal	06.00	10.00	04.00	EL/OL	11KV Line Snapped	-
1	RR N	UMCC	Mini Industry	11KV	Medchal	16.50	17.20	00.30	BD	11KV Line cut at Mini Industry Gate	-
2		Jeedimetl-II	Apuropacolony	11KV	Jeedimetla	11.42	12.50	01.08	BD	Tree branch fall on the 11 KV line & 3 nos poles broken at SRC N Nagar	-
3		Kandlakoya	KV Reddy Nagar	11KV	Medchal	14.50	15.25	00.35	BD	Tree fallen on the 11KV Line at Bio Sakshi Dhabha	-
1	RR E	Nacharam	Nile	11KV	Habsiguda	04.50	06.10	01.20		11KV Line snapped near Road No.08 at SS Yard outside	-
2		Uppal	Adarsha Nagar	11KV	Habsiguda	07.50	08.35	00.45		Bird fallen on 11kv Tower line at Chilaka Nagar Petrol Bunk	-
3		Yadgarpally	Cheryala	11KV	Keesara	13.40	15.40	02.00		11KV disk fail at Mangali Bhavi	-
1	HYD N	I.D.P.L.	Shivalayam	11KV	VI	01.10	03.00	01.50	EL,OL-Bph	AB Cable fault at Nala	Arranged B/F on 11KV Samatha Ngr fdr
1	HYD S	Devi Bagh	Rama Talkies	11KV	III	10.14	11.30	01.16	EL,OL-Bph	Conductor snapped at Rama Talkies	-
2		Falaknuma	Guntalsha Darga	11KV	III	19.23	20.40	01.17	EL	Lizard fallen on Pole at Govt .School	-