

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1	7	1	7	1	7			
	Total	606	3055	1	11	1	11	1	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	19	1	19	1	19			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	21	1	21	1	21	0	0	
	Grand Total	1082	6468	2	32	2	32	2	32	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.10.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	132KV Wadapally	A.D.Pally	33KV	Miryalaguda	11:45	16:45	5:00	EL/OL	Jumper cut at Irkigudem	A.D.Pally	No
1	HYD N	132KV Madhapur	Raheja (PTR-2)	33KV	Kalyan Ngr	10.50	11.05	00.15	EL,OL-Rph	Cable damaged by Master Plan near Shilparamam	Raheja (PTR-2)	Loads transferred onto 132KV Madhapur SS via 33KV Trion Properties for

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Donoor	Singamdoddi	11KV	Jadcherla	00.00	08.10	08.10		11KV Insulator failed near Singamdoddi (V)	No
1	NLG	Arlagaddagudem	Arlagaddagudem	11KV	Nalgonda	15:30	16:50	1:20	EL	11KV Jumper cut	No
2		Cherkupally	Thungaturthy	11KV	Nalgonda	05.30	11.55	06.25	EL	11KV Disc failed at Bheemaram Road	No
3		Pamulapad	Kalwalpalem	11KV	Miryalaguda	14.00	19.15	05.15	EL	Tree branch fallen on the line	No
4		Kamareddygudem	Pusalpad	11KV	Miryalaguda	13.50	16.15	02.25	EL	Disc failed	No
5		Kamareddygudem	Kamareddygudem	11KV	Miryalaguda	16.15	17.35	01.20	EL	Jumper cut at Kamareddygudam	No
6		Peddavura	Thungathurthy	11KV	Miryalaguda	03.25	09.30	06.05	EL	DTR failed at Lingampally	No
7		Athmakur(S)	Naseempeta	11KV	Suryapet	05.30	09.00	03.30	E/L	Conductor snapped	No
8		Penpahad	Potlapahad	11KV	Suryapet	15.45	17.30	01.45	E/L	Tree branch fallen on the line	No
9		Palakaveedu	Nagireddigudam	11KV	Huzurnagar	02.30	05.30	03.00	EL	Due to 11KV Jumper cut	No
10		Huzurnagar	Burugadda	11KV	Huzurnagar	13.55	16.30	02.35	EL	Due to 11KV line snapped	No
11		Y.Singaram	Y.Singaram	11KV	Huzurnagar	15.20	17.20	02.00	EL	Due to 11KV Line cut	No
12		Bheelya Naik thanda	Vardapuram	11KV	Huzurnagar	14.00	16.40	02.40	EL	Due to 11KV line snapped	No
13		Mattapally	Sulthanpuram	11KV	Huzurnagar	13.30	15.47	02.17	EL	Due to 11KV Jumper cut	No
14		Gudimalkapuram	Thammaram	11KV	Huzurnagar	13.10	16.00	02.50	OL	Due to tree branch fall on the 11Kv line	No
15		Thogarrai	Thogarrai	11KV	Huzurnagar	13.20	16.00	02.40	EL	Due to 11KV Jumper cut	No
16		Nadigudem	Lift	11KV	Huzurnagar	14.15	17.00	02.45	EL	Due to tree branch fall on the 11Kv line	No
17		Mamillagudem	Vibula puram	11KV	Huzurnagar	15.30	17.00	01.30	EL	Due to 11KV Jumper cut	No
18		Nemaragommula	Jameelapeta	11KV	Bhongir	04.00	10.10	06.10	EL	11KV Disc failed near Nemaragommula Village.	No
19		Vemulakonda	Chitthapuram	11KV	Choutuppal	11:20	13:10	1:50	EL/OL	11KV Line snapped near Madhure Thota Chitthapuram Village	No
1	MDK	SOL	BMF	11KV	Patancheru	17:10	18:15	1:05		Jumper cut	No
1	RR N	Ravalkole	IDA Ganapathi	11KV	Medchal	11:05	11:40	0:35		Tree Branch fallen on the 11KV line	No
2		GP Pally	Neighbourhood	11KV	Medchal	15.50	16.50	01.00		No visible fault	No
3		GP Pally	Malla Reddy	11KV	Medchal	16.30	17.45	01.15		11KV Disc failed and replaced at Malla reddy college backside	No
1	RR E	Malkajiri	IN Nagar	11KV	Sainikpuri	15:20	16:28	1:08		11KV Pin insultaor failed	No
1	HYD N	Marredpally	Military Hospital	11KV	C-VI	21.40	22.55	01.15	EL,OL-Bph	Tree branches fallen on lines at Military Hospital	No
2		H.A.L.	Lokesh Machine	11KV	VI	22:02	23:06	1:04	EL,OL	Cable fault	Arranged B/F on 11KV T.C. Bala Nagar for
1	HYD S	Hyderguda	Jana Priya AB Cable	11KV	III	16.50	18.15	01.25	EL,OL	No Visible Fault	No
1	HYD C	Vittalwadi	Basanth Colony	11KV	II	15.20	17.16	01.56	EL,OL-Bph	Pin Insulator flash over at Nrupathunga College	No
2		Asif Nagar	Hakimpet	11KV	VII	15.33	17.18	01.45	EL	Pin Insulator flash over at Kendriya Vidyalaya & Post type Insulator flash over at Military Gate	No
3		Z.P Office	Ram Leela Maidan	11KV	I	15.35	16.45	01.10	EL	Disc Insulator flash over at Ram Leela Maidan	Arranged B/F on 11KV Golconda Hotel feeder
4		Asif Nagar	Military	11KV	VII	16:18	17:25	1:07	EL	Tree branches fallen on lines at Military Area	No