

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		7		7		7			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	11	0	11	0	11	0	0	
	Grand Total	1082	6468	0	13	0	13	0	13	0	0	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thatipamula	Sriram thanda	11KV	Suryapeta	4:30	7:50	3:20	EL	Disc flah over	No
2		Mukundapuram	Somaram	11KV	Huzurnagar	03.00	06.30	03.30	EL	11KV Line snapped	No
3		Akupamula	Akupamula	11KV	Huzurnagar	06.00	09.15	03.15	EL	11KV Insulator failed	No
4		Keethavarigudem	Laxmipuram	11KV	Huzurnagar	05.30	07.30	02.00	EL	11KV Line snapped	No
5		Thurkapally	Hydalapoor	11KV	Nalgonda	12.40	13.57	01.17	EL	11KV Jumper cut	No
6		Tripuraram	Mukundapuram	11KV	Miryalaguda	13.20	15.55	02.35	EL	11KV Jumper cut	No
7		Peddaravlapally	Indireyala	11KV	Choutupal	10:52	11:42	0:50	EL	11KV Disc Failed	No
1	SDPT	Koheda	Theegalakuntapally	11KV	Husnabad	10:00	11:50	1:50		Tree branch fallen on the line	No
2		Koheda	Sriramulapally	11KV	Husnabad	10.00	11.00	01.00		Tree branch fallen on the line	No
3		Komuravelly	Peddarajupeta	11KV	Husnabad	12.02	15.50	03.48		Tree branch fallen on the line	No
4		Komuravelly	Kistampet	11KV	Husnabad	12.02	17.32	05.30		Insulator failure	No
1	RR E	Cherlapally-III	Gail	11KV	Sainikpuri	8:24	9:10	0:46		3HG fuse cut at Gail Company & CTBT problem	No
2		Janapriya	Vampuguda	11KV	Sainikpuri	12.20	13.35	01.15		11KV 9.1 Mtr Pole broken at Saral Venture	Back feeding from Santhosh Nagar feeder