

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044	1	1	1	1	1	1			
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	19	1	19	1	19			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	21	2	21	2	21	0	0	
	Grand Total	1082	6468	3	24	3	24	3	24	0	0	

TSSPDCL - LMRC / Corporate office

Date: 19.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kodangal	Peddanandigama	33kv	Vikarabad	00.50	07.30	06.40	EL	Tree follen on the line	Peddanandigama	-
1	NLG	220KV Miryalguda	Reddy's Lab	33kv	Miryalaguda	08.35	12.05	03.30		Snake touches to two Phases at near Reddy Lab	Reddy's Lab	-
1	HYD S	220KV Ch' Gutta - Santosh Nagar Ckt-1	Yakuthpura	33kv	Asmangadh	00.08	00.15	00.07	EL	Cable damated by HMWS Department at Almond Hotel	Yakuthpura	-

TSSPDCL - LMRC / Corporate office

Date: 19.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Urumadla	Yelikatte	11kv	Nalgonda	14.00	15.45	01.45	EL	11 KV Line Jumper Cut	-
2		Palem	Ogodu	11kv	Nalgonda	13.40	17.20	03.40	EL	11 KV Line Jumper Cut	
3		Koppole K	Bhemaram	11kv	Nalgonda	06.00	08.30	02.30	EL	11 KV Line Jumper Cut	
4		Chandampeta	Mudidandla	11kv	Devarakonda	05.00	09.30	04.30	EL	1-PH DTR Faild at Mudidandal Village	
5		Angadipeta	P.A.Pally Rural	11kv	Devarakonda	06.35	10.15	03.40	EL	11KV Insulator Failed	
6		Angadipeta	Gudipally	11kv	Devarakonda	09.00	11.00	02.00	EL	Tree Flowan	
7		Nampally	Peddapuram	11kv	Devarakonda	08.30	14.15	05.45	EL	11 KV Insulator Failed & Jumper Cutt	
8		Tekumatla	Pillalamarry	11kv	Suryapet	03.00	06.30	03.30	EL	Conductor snapped	
9		Bopparam	M.K Kothagudem	11kv	Suryapet	03.40	06.30	02.50	EL	Insulator flashover	
10		Alingapuram	Raghavapuram	11kv	Huzurnagar	06.00	08.55	02.55	EL	Due to 11Kv Disk failure	
11		Mellacheruvu	Mellacheruvu	11kv	Huzurnagar	06.00	09.00	03.00	EL	Due to 11Kv insulator failure	
12		Kodad Town	Komarabanda Agl	11kv	Huzurnagar	03.10	06.00	02.50	EL	Due to 11Kv Disk failure	
13		Chanupally	Tripuravaram	11kv	Huzurnagar	06.15	09.00	02.45	EL	Due to 11Kv insulator failure	
14		Nandanam	Nagireddypally	11kv	Bhongir	03.00	06.20	03.20	EL	11 kv Insulator Failed & 11 kv Line Snapped	
15		NG.Bandal	Konapur	11kv	Bhongir	06.40	10.30	03.50	EL	11 kv Disc Failed	-
16		Paladugu	Dattappagudem	11kv	Bhongir	07.00	10.15	03.15	EL	11 KV Disc Failed & 11 KV Line Snapped	-
17		Pallerla	Kurella	11kv	Bhongir	06.15	10.00	03.45	EL	11 kv Insulator Failed	-
18		Yennaram	Palliwada	11kv	Choutuppal	03.55	08.35	04.40	EL	11 kv Insulator Failed	-
19		Laxmapuram	Laxmapuram	11kv	Choutuppal	00.00	04.00	04.00	EL	11 kv Insulator Failed	-
1	SDPT	Guruvannapet	Guruvannapet	11kv	Husnabad	00.00	09.45	09.45		B/D due to Tree branches fallen on line	-
2		Nagapuri	Pothireddypalli	11kv	Husnabad	00.00	06.50	06.50		B/D due to 11 kV line cut	-
1	RR E	IDA Uppal	LN nagar	11kv	Habsiguda	16.46	17.20	00.34		Tree fallen on 11kv line at TV colony	-
2		Anandbagh	Vinayak Nagar	11kv	Sainikpuri	12.47	13.30	00.43		Ground Petrolling don but no Visible foul found	-
1	HYD N	Marredpally	Tagore Home	11kv	Clocktower	18.35	19.57	01.22	EL	No Visible Fault	Arranged B/F on 11KV Hanuman Temple fdr