

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	4	1	4	1	4			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	1	9	1	9	1	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988	1	5	1	5	1	5			
3	MDK	107	933		3		3		3			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	11	1	11	1	11	0	0	
	Grand Total	1082	6468	2	20	2	20	2	20	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.10.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Suryapet	M.J.R	33KV	Suryapet	11:50	15:00	3:10	E/L	Bird fallen on the line	M.J.R	No
1	RR N	Shameerpet	Leo Meridian	33KV	Medchal	5:50	7:00	1:10		No visible fault	Leo Meridian	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Nawabpet	Kondapur	11KV	Jadcherla	03.00	09.00	06.00		11KV Disc failed near kondapur.	No
2		Nawabpet	Gurukunta	11KV	Jadcherla	03.14	07.50	04.36		11KV Insulator failed near Gurukunta.	No
1	NLG	Ravulapally	Thurpugudem	11KV	Suryapet	12:00	15:30	3:30	E/L	Insulator failed	No
2		Burugadda	Gopalapuram	11KV	Huzurnagar	14.00	15.00	01.00	E/L	Insulator failed	No
3		Motakondur	Motakondur	11KV	Bhongir	04.00	10.00	05.00	E/L	11KV Disc failed	No
4		Panthangi	Panthangir Agl	11KV	Choutuppal	02.30	07.00	04.30	E/L	11KV Disc failed	No
5		Juloor	Juloor	11KV	Choutuppal	0:00	8:30	8:30	E/L	11KV Pole damaged near Gopal Well near Juloor Village	No
1	MDK	Gundla Machnoor	Industrial	11KV	Patancheru	13:50	15:40	1:50		Insulator failed	No
2		Patancheru Town	Shanthinagar	11KV	Patancheru	13.15	13.55	00.40		Tree branch fallen on the line	No
3		Ismailkhan Pet	Industrial	11KV	Sangareddy	13.23	15.23	02.00		Insulator failed	No
1	SDPT	Guruvannapet	Guruvannapet	11KV	Husnabad	7:40	10:50	3:10		Insulator failed	No
1	RR N	UMCC	Crusher	11KV	Medchal	19:50	20:20	0:30		Kite fallen on 11KV Line	No
2		Aleap	RGK	11KV	Jeedimetl	13.05	15.20	02.15		11KV Pin insulator failed at Bachupally Main Road	No
3		Nuthankal	Bharathi	11KV	Medchal	09.20	09.50	00.30		Tree fallen on 11KV line	No
4		Shameerpet	Nalsar	11KV	Medchal	18.05	18.40	00.35		11KV Pin Insulator failed	No
1	RR E	Ramanthapur	Church Colony	11KV	Habsiguda	5:45	6:24	0:39		11KV Disc failed at Indra Nagar	
2		Kushaiguda	Sriram Nagar	11KV	Sainikpuri	16.30	17.40	01.10		11KV Pin Insulator failed	
3		Vasanthapuri	Venkateshwara Nagar	11KV	Sainikpuri	11.57	12.41	00.44		11KV Line twisting at BJR Nagar	
1	HYD N	Tirumalagiri	Officers Colony	11KV	C-VI	13.25	14.58	01.33	EL,OL-Rph	Tree branches fallen on lines at Main Road	No
1	HYD C	Nampally	FAPCCI	11KV	VII	23.05	00.21	01.16	EL	Tree fallen on line & Conductor snapped at Criminal Court	No