

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403									
8	Hyd	194	1044		4		4		4			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	2	3	2	3	2			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 27.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Machanpally	33KV	Mahabubnagar	04.10	12.00	07.50	E/L	Due to Tree Fallen on the Line		Alternate Supply Arranged From 33KV Parepally at 12:00Hrs.
2		Ghanapur	Solipur	33KV	Wanaparthi	02.58	06.43	03.45	E/L	AB Switch Opened at Shapur Supply Stood OK		NO
3		Wanaparthi	Peddmandadi	33KV	Wanaparthi	08.05	09.08	01.03	E/L	Due to LV's & HV's Pull Out		Alternate Supply Arranged from 132KV SS Thirumalaipally at 9:08Hrs

TSSPDCL - LMRC / Corporate office

Date: 27.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Hemajipur	Koilkunta thanda	11KV	Jadcherla	04.00	09.10	05.10		Due to 11 KV Insulator fail	-
2		Midjil	Kothur	11KV	Jadcherla	04.30	09.30	05.00		11 KV Disc Failed Near Mallapur	-
1	NLG	Pamanagundla	Pittampally	11KV	Nalgonda	06.00	07.30	01.30	EL	11 KV Line Junper Cut	-
2		Gondriyala	Chimiryala	11KV	Huzurnagar	11.30	14.30	03.00	EL	Due to 11kv disk failure	-
3		Kolanpaka	Kolanpaka	11KV	Bhongir	07.50	10.00	02.10	EL	11 kv Line Snapped	-
1	RR N	Dulapally	Dulapally Village	11KV	Medchal	10.00	12.05	02.05	BD	11KV Disc Failed and replaced at Gangastan Opp	-
2		Subhash Nagar	Ramraj Nagar	11KV	Medchal	05.40	06.23	00.43	BD	11KV Line AB Switch Opened at Chennai Shopping Mall (Bird Fallen on 11KV Line at Eseva Opp)	-
3		Subhash Nagar	Gayatri Nagar	11KV	Medchal	05.45	08.25	02.40	BD	No Fault	-
1	HYD N	Borabanda	Saradhi Nagar	11KV	Erragadda	13.28	14.35	01.07	OL	HT Jumper cut at Vijetha Theater	-
1	HYD S	Miralam	Ranjan Colony	11KV	Charminar	16.23	17.53	01.30	EL,OL	2No. Jumpers cut & Relay problem at SS	Arranged B/F on 11KV Sather Bagh feeder
2		Petlaburz	Sha Gunj	11KV	Charminar	21.27	22.59	01.32	EL,OL	Faulty loads of 11KV Q.Q.Stadium feeder	removed loads of 11KV Q.Q.Stadium fdr
1	HYD C	Vittalwadi	Gandhi Kuteer	11KV	Saifabad	22.20	23.40	01.20	All Indication	Pin Insulator flash over at Progressive Teachers Union	-