

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		8		8		8			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044	1	8	1	8	1	8			
	Total	606	3055	1	20	1	20	1	20	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		21		21		21			
3	MDK	107	933		2		2		2			
4	SDPT			8	6	8	6	8	6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	8	29	8	29	8	29	0	0	
	Grand Total	1082	6468	9	49	9	49	9	49	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDP	Habsipur	Pothareddypet	33KV	Siddipet	03.30	07.50	04.20		Disk & insulater failure	Pothareddypet	-
2		Habsipur	Khajipur	33KV	Siddipet	04.30	08.50	04.20		Disk & insulater failure	Khajipur	-
3		Habsipur	Ragothampally	33KV	Siddipet	04.30	07.50	03.20		Insulator failed	Ragothampally	-
4		Habsipur	Peddacheekode	33KV	Siddipet	06.30	08.00	01.30		Disk failure	Peddacheekode	-
5		Palamakula	Baddipadaga	33KV	Siddipet	05.25	07.45	02.20		5 no Pin Insulater failure	Baddipadaga	-
6		Gajwel	B V pur	33KV	Gajwel	01.17	10.30	09.13		Disk failure	B V pur	-
7		Thukkapur	Mettu	33KV	Gajwel	06.00	09.10	03.10		Disk & insulater failure	Mettu	-
8		Angadikistapur	wardharajpur	33KV	Gajwel	01.41	07.58	06.17		Disk failure	wardharajpur	-
1	HYD S	220KV Ch' Gutta - Santosh Nagar Ckt-II	Santosh Nagar	33KV	Malakpet	03.00	03.20	00.20	OL-Bph	Old Cable Joint failed at Owaisy Turning	Santosh Nagar	Loads transferred onto 220KV Ch' Gutta SS via 33KV Santosh Nagar Ckt-I

TSSPDCL - LMRC / Corporate office

Date: 29.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kattangur	Pamanagundla	11KV	Nalgonda	00.26	06.36	06.10	E/L	11KV Jumper cut	-
2		Arlagaddagudem	N.R.Gudem	11KV	Nalgonda	06.30	07.30	01.00	E/L	Moment fault	-
3		Eduloor	Naregudem	11KV	Nalgonda	15.00	17.10	02.10	E/L	11KV Insulator failed	-
4		Pamanagundla	Yerasanigudem	11KV	Nalgonda	14.02	17.13	03.11	E/L	11KV Jumper cut	-
5		Nellikai	Chinthapalem	11KV	Miryalaguda	15.00	16.45	01.45	E/L	11KV conductor Snapped fallen on the DTR	-
6		Nandhipahad	Nandhipahad	11KV	Miryalaguda	14.10	18.38	04.28	E/L	Tree branches fallen on the line	-
7		Penpahad	Macharam	11KV	Suryapet	09.30	12.00	02.30	E/L	Bird fallen on the line	-
8		Ponugodu	Velidanda	11KV	Huzunagar	14.47	16.42	01.55	EL	Due to 11Kv line cutted	-
9		Mattapally	Sulthanpuram	11KV	Huzunagar	12.40	15.35	02.55	EL	Due to 11Kv line cutted	-
10		Chilukur	Janaki nagar	11KV	Huzunagar	12.20	15.10	02.50	EL	Due to 11Kv jumper cutted	-
11		Nandanam	Thukkapur	11KV	Bhongir	03.10	09.00	05.50	EL	11kv Line Snapped near Navathpally Village	-
12		Alair	Ch.Kandukur	11KV	Bhongir	07.40	09.10	01.30	EL	11kv Disc Failed near Ch.Kandukur Village	-
13		Bondugula	Parupally	11KV	Bhongir	11.50	16.55	05.05	EL/OL	11kv Insulator Failed near Parupally Village	-
14		Datherpally	Mallapur	11KV	Bhongir	06.05	13.00	06.55	EL/OL	11kv Insulator Failed near Mallapur Village	-
15		Motakondur	Choller	11KV	Bhongir	00.00	11.40	11.40	EL/OL	11kv Insulator Failed near Giriboina Gudem	-
16		Motakondur	Vattoor	11KV	Bhongir	04.00	10.00	06.00	EL	100kva DTR Failed & 11kv Insulator Failed near Vattoor Village	-
17		Paladugu	Paladugu	11KV	Bhongir	06.50	09.40	02.50	EL	11kv Pin Insulator Failed near Ragvapuram	-
18		Athmakur	Koratikal	11KV	Bhongir	15.10	17.40	02.30	EL	11kv Insulator Failed near Koratikal Village Single Phase B/d	-
19		Velmajala	Kommaipally	11KV	Bhongir	08.15	11.30	03.15	EL/OL	11kv Insulator Failed near Kammaipally Village	-
20		Panhangi	Indl	11KV	Choutuppal	15.35	16.50	01.15	EL/OL	11kv Line Snapped near Panhangi Village	-
21		Aroor	Aroor Agl	11KV	Choutuppal	15.45	17.00	01.15	EL/OL	11kv Insulator Failed near Aroor Village	-
1	MDK	SRD Town-II	No.III	11KV	Sangareddy	15.45	17.40	01.55		B/D due to Conductor snapped	-
2		SRD Town-II	Kosla	11KV	Sangareddy	15.45	17.40	01.55		B/D Due to Tree branches fallen on the line at ITI College.	-
1	SDP	Gandipally	Ramavaram Express	11KV	Husnabad	00.00	09.00	09.00		Heavy gale and wind	-
2		Gouravelli	Gudatipally & Gouravelli Exprss	11KV	Husnabad	03.30	07.30	04.00		Heavy gale and wind	-
3		Thotapally	Dacharam	11KV	Husnabad	00.00	20.20	20.20		Jumper problem	-
4		Samudrala	Baswapur	11KV	Husnabad	03.30	08.40	05.10		Heavy gale and wind	-
5		Nagapuri	Gandikunta	11KV	Husnabad	10.30	12.00	01.30		Heavy gale and wind	-
6		Marmamula	Salakpur	11KV	Husnabad	12.45	16.10	03.25		Jumper cut	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Nizampet	Nizampet	11KV	Kukatpally	15.06	17.06	02.00		11kv disk failure opp NRI Collage at Nizampet	-
2		Jeedimetla-II	Apuroopa colony	11KV	Jeedimetla	15.15	16.20	01.05		11kv Jumper Cut & touched The Channel At SR C naik Nagar	-
3		Bowrampet	Bowrampet Village	11KV	Jeedimetla	15.14	16.30	01.16		Tree Branches Fallen On the 11kv Line At S R R Venchar	-
4		Jagathgirigutta	Jagathgirigutta	11KV	Medchal	15.25	16.05	00.40		Tree Branches fallen on the 11KV Line at Somaiah Nagar	-
5		Keshavaram	Keshavaram	11KV	Medchal	08.30	09.50	01.20		100KVA T/F Brass patti Replaced at Potharam X Road	-
6		Gowdawelly	IDA Gowdawelly	11KV	Medchal	15.10	16.10	01.00		Tree Branches fallen on the 11KV Line at Saketh Venture	-
7		Town Medchal	Jyothi Nagar	11KV	Medchal	16.52	17.35	00.43		Kite Fallen on 11KV Line at Jyothi Nagar	-
8		Kandlakoya	Kandlakoya	11KV	Medchal	15.10	17.00	01.50		11KV Line & Jumper Cut & Replaced at Kandlakoya Cheruvu & Gubba Chowrasta	-
1	RR E	Nacharam	Nagarjuna	11KV	Habsiguda	16.10	17.00	00.50		Pin Insulator fail at Daigram company	-
2		NGRI	Kalyanpuri	11KV	Habsiguda	14.30	16.00	01.30		Tree fallen on 11kv line at Survey of India quators	-
3		Polytechince	Madhura nagar	11KV	Habsiguda	14.30	15.45	01.15		Due to tree fallen on 11kv line at Ram shankar nagar	-
4		Poacharam	Jodimetla	11KV	Keesara	14.30	15.15	00.45		Tree fallen on 11kv line at Chowdari guda	-
1	HYD N	Amberpet	C.P.L	11KV	II	14.30	16.31	02.01	All Indication	No Visible Fault	Arranged B/F on 11KV Chenna Reddy Nagar feeder
2		Indira Park	Domalguda	11KV	I	14.35	15.55	01.20	EL,OL-Rph	Tree branches fallen on lines at E-Seva	-----
3		Public Garden	Nampally Railway Station	11KV	I	14.36	16.02	01.26	EL,OL	Flexi fallen on lines at Huz House	-----
1	HYD S	Falaknuma	Jangammet OH	11KV	III	01.15	04.20	03.05	EL,OL-Bph	HT Line snapped at Progressive School, Cat fallen on lines & 3Way RMU End Kit fault at Khaveli Masjid	At 03:45Hrs Partial fdr charged & remaining loads added on 11KV Sharada College fdr
2		Asmangadh	P&T Colony	11KV	VIII	14.32	15.39	01.07	All Indication	No Visible Fault	-----
1	HYD C	Amberpet	C.P.L	11KV	II	14.30	16.31	02.01	All Indication	No Visible Fault	Arranged B/F on 11KV Chenna Reddy Nagar feeder
2		Indira Park	Domalguda	11KV	I	14.35	15.55	01.20	EL,OL-Rph	Tree branches fallen on lines at E-Seva	-----

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
3		Public Garden	Nampally Railway Station	11KV	I	14.36	16.02	01.26	EL,OL	Flexi fallen on lines at Huz House	-----