

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044	1	2	1	2	1	2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988	1	7	1	7	1	7			
3	MDK	107	933		2		2		2			
4	SDPT			5	3	5	3	5	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>6</b>	<b>14</b>	<b>6</b>	<b>14</b>	<b>6</b>	<b>14</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>7</b>	<b>21</b>	<b>7</b>	<b>21</b>	<b>7</b>	<b>21</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 30.10.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Wadapally	Damarcherla	33KV	Miryalguda	12.40	15.10	02.30	E/L	33Kv Insulater failed opposite Raasi cement factory	Damarcherla	-
1	SDP	Hashipur	Khajipur	33KV	Siddipet	04.30	08.50	04.20		B/D - Disk fail	Khajipur	-
2		Hashipur	Pothareddypet	33KV	Siddipet	03.30	07.50	04.20		B/D - Disk fail	Pothareddypet	-
3		Hashipur	Ragothampally	33KV	Siddipet	04.30	07.50	03.20		B/D - Disk fail	Ragothampally	-
4		Hashipur	Pedda cheedkoe	33KV	Siddipet	06.30	08.00	01.30		B/D - Disk fail	Pedda cheedkoe	-
5		Palamakula	Baddipadaga	33KV	Siddipet	05.28	07.04	01.36		B/D - Pin insulators fail	Baddipadaga	-
1	HYD S	132KV Imlibun	Industrial Area (Idle)	33KV	Chilalguda	10.15	17.35	07.20	OL-R&Bph	Jumper cut at Loc No. 27, Musi River, Malakpet Railway Station	Industrial Area (Idle)	-

TSSPDCL - LMRC / Corporate office

Date: 30.10.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bhoothpur	Bhoothpur Rural	11KV	Jadcherla	13.10	17.22	04.12		Due to 11 KV disc Failed Near pothulamadugu	-
2		Badepally	Burgupally	11KV	Jadcherla	07.35	10.32	02.57		Due to 11 KV Disc Failed Near Alloor (V)	-
1	NLG	Pamanagundla	Pittampally	11KV	Nalgonda	07.12	10.40	03.28	E/L	Tree Branches Fallen on the 11Kv Line	-
2		Arlagaddagudem	N.R.Gudem	11KV	Nalgonda	12.50	13.30	00.40	E/L	11 KV Jumper Cut	-
3		Palem	Ogodu	11KV	Nalgonda	16.00	17.30	01.30	E/L	11 KV Jumper Cut	-
4		Athmakur(S)	Dacharam	11KV	Suryapet	11.00	14.10	03.10	E/L	11Kv Disc Flashover	-
5		Dirincherla	Town-2	11KV	Huzunagar	13.50	14.50	01.00	E/L	11Kv Line Snapped	-
6		Garidepally	Kalmalcheruvu	11KV	Huzunagar	06.00	07.30	01.30	E/L	11Kv Jumper Cut	-
7		Munagala	Barakathgudem	11KV	Huzunagar	12.45	14.40	02.05	E/L	11Kv Line Snapped	-
1	MDK	Bollaram - I	Arobindo	11KV	Patancheru	05.22	08.58	03.36		BD due to Conductor snapped	-
2		Bonthapally	Jaishenkar	11KV	Patancheru	16.36	18.36	02.00		BD due to Conductor snapped at Company side	-
1	SDP	Thotapally	Veerapur	11KV	Husnabad	16.20	19.00	02.40		BD Jumpet Cut	-
2		Potharam	Potharam Rural	11KV	Husnabad	16.40	23.10	06.30		BD Jumpet Cut	-
3		Dharmaram	Potharam(J)	11KV	Husnabad	07.10	13.40	06.30		BD, Conductor snapped	-
1	RR N	Athiwelly	Dabeerpur	11KV	Medchal	04.20	05.20	01.00	BD	Tree fallen on the 11KV Line at Lingapur	-
1	RR E	Cherlapally-II	Jannuram	11KV	Habsiguda	15.05	17.05	02.00		11Kv Insulator failed at EC Nagar (AE/LM Ram Babu) due to Heavy Rain	-
2		Nagaram	Bandlaguda	11KV	Habsiguda	14.12	15.40	01.28		Insulaotar fail at Bandlaguda stadium	-
3		Keesara	Bogaram	11KV	Habsiguda	15.08	18.30	03.22		Tree fallen on 11kv line at matrix company	-
4		Saket	JawaharNagar	11KV	Habsiguda	14.15	16.20	02.05		11KV Line Twested at Rose Garden	-
1	HYD N	Clock Tower	Station Road	11KV	V	13.58	15.25	01.27	All Indication	3Way RMU Lug B/o near SS	-
1	HYD C	Vittalwadi	Y.M.C.A.	11KV	II	05.25	06.42	01.17	EL	Cable fault	Arranged B/F on 11KV Basanth Colony fdr