

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	5	1	5	1	5			
3	MDK	107	933		1		1		1			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	7	1	7	1	7	0	0	
	Grand Total	1082	6468	1	11	1	11	1	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 31.10.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Miryalaguda	Matoor	33KV	Miryalaguda	12:45	14:46	2:01	EL	Tree fallen on the line	Matoor	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Palakaveedu	Bothalapalem	11KV	Huzurnagar	6:30	9:30	3:00	EL	11KV Insulator failed	No
2		Ponugodu	Velidanda	11KV	Huzurnagar	06.00	09.00	03.00	EL	11KV Insulator failed	No
3		Edulur	Naragudem	11KV	Nalgonda	04.30	07.30	03.00	EL	Tree branches fallen on the line	No
4		Ch.Annaram	G.B.Gudem	11KV	Nalgonda	09.20	11.30	02.10	EL	11KV Jumper cut	No
5		Arlagaddagudem	N.R.gudem	11KV	Nalgonda	7:30	11:00	3:30	EL	11KV Jumper cut	No
1	MDK	SOL	BMF	11KV	Patancheru	12:10	14:30	2:20		Conductor snapped	No
1	SDPT	Bejjanki	Cotton Mill	11KV	Husnabad	8:40	9:10	0:30		Insulator failed	No
1	RR N	Chintal	Surya Nagar	11KV	Medchal	1:30	2:30	1:00		UG Cable failed at Main Road, Chintal	Backfeeding to 11KV Saibaba Nagar from Subhash Nagar SS
2		Kistapur	IDA Hanuman	11KV	Medchal	15.16	15.55	00.39		Tree fallen on the 11KV line at Bricks Company	No
3		GP Pally	Maisammaguda	11KV	Medchal	16.25	17.10	00.45		Tree branch fallen on the 11KV line at Satyam Computer	No
1	HYD S	Attapur	N.M.Guda UG	11KV	III	05.40	06.45	01.05	EL,OL-Bph	Cable fault	Arranged B/F on 11KV W.S.Colony for