

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		11		11		11			
7	RR(E)	168	403		5		5		5			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	20	0	20	0	20	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	6	1	6	1	6	0	0	
	Grand Total	1082	6468	1	26	1	26	1	26	0	0	

TSSPDCL - LMRC / Corporate office

Date: 14.09.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	B.B.Nagar	Bollepally	33KV	Bhongiri	00.38	03.25	02.47	EL	33KV Jumper Cut	Bollepally	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Arjalabavi	Arjalabavi AGL	11KV	Nalgonda	09.20	13.40	04.20	E/L	11KV Jumper cut	-
2		Athmakur(s)	Gottemukkalagudem	11KV	Suryapet	16.30	18.00	01.30	E/L	Insulator failed	-
3		Mamillagudem	Vibhulapuram	11KV	Huzurnagar	04.00	06.45	02.45	EL	11 KV LINE SNAPPED	-
4		Garidepally	Appannapet	11KV	Huzurnagar	05.45	08.00	02.15	EL	11 KV JUMPER CUT	-
5		Venkatapuram	Velupally	11KV	Bhongir	14.40	16.45	02.05	EL	11 KV Insulator Failed	-
6		Pamukunta	Jala	11KV	Bhongir	09.45	12.00	02.15	EL	11 kv Disc Failed	-
1	RR S	Papireddy Colony	Papireddy Colony	11KV	GCB	06.46	07.55	01.09	BD	Lorry Dashed 11KV Pole and 11KV Line Cut at Papireddy Colony Forest	-
1	RR N	Madinaguda	J P N nagar	11KV	Kukatpally	21.50	23.59	02.09	EL/OL	Grond Petroling No fault [Due to Heavy rain	-
2		Vijayanagar	Shanthinagar	11KV	Kukatpally	21.35	22.55	01.20	EL	Tree Branches Fallen On the 11kv line At Complex Road	-
3		Vijayanagar	Yellamma Banda	11KV	Kukatpally	21.25	22.35	01.10	EL	DTR BrassPatti Cut Touched Channel At mahakalinagar	-
4		Mayurinagar	Mayurinagar	11KV	Kukatpally	22.40	23.40	01.00	EL/OL	D T R post Of Insultor Failure At Sony Garden	-
5		G Vikas	Aparana	11KV	Kukatpally	21.58	23.50	01.52	OL	Tree Branches Fallen On the 11kv line At T F L company & T/F lighting Aresster Failure At Hostel	-
6		G Vikas	Reddy Colony	11KV	Kukatpally	22.01	23.15	01.14	EL	11kv pin Insultor Failure At Indian Gas godown	-
7		Mayurinagar	Cable	11KV	Kukatpally	22.25	23.29	01.04	EL/OL	DTR post Of Insultor Failure At Ramnareshanagar Road -14	-
8		Aleaps	DR Colony	11KV	Jeedimetla	16.35	18.30	01.55	EL/OL	J A wire Touched The 11kv Disk Near Pt-No 1339	-
9		Jeedimetla	Phase-II	11KV	Jeedimetla	22.00	23.59	01.59	OL	Due To Heavy Rain	-
10		Jeedimetla	Ragahava	11KV	Jeedimetla	21.50	22.50	01.00	EL/OL	Due To Heavy Rain	-
11		UMCC	Crusher	11KV	Medchal	04.10	05.00	00.50		11KV Cable end kit failed at Kaisar Nagar	-
1	RR E	Sainikpuri	Saipuri	11KV	Sainikpuri	22.13	23.50	01.37		11Kv Insuletor fail at OUT Colony (AE/OP)	-
2		Sainikpuri	Eshwaripuri	11KV	Sainikpuri	22.13	00.35	02.22		11Kv Pin Insuletor fail at Eshwaripuri Colony)	-
3		Sainikpuri	Kalyan Garden	11KV	Sainikpuri	22.13	23.50	01.37		11Kv Insuletor fail at Kalayn Garden (AE/OP)	-
4		Kushaiguda	Kapra	11KV	Sainikpuri	21.45	23.15	01.30		11Kv line 3 Jumper cut at APIIC Colony (AE/OP) due to Heavy Rain	-
5		RGK	Kowkooor	11KV	Sainikpuri	23.30	01.00	01.30		Tree fallen on 11Kv line at Kowkooor Bus Stop Opp High School (LM Rajender)	-
1	HYD N	Macha Bollaram	Sai Reddy Nagar	11KV	C-VI	21.43	23.13	01.30	OL	No Visible Fault	-
2		Gunrock	Subash Nagar	11KV	C-VI	21.55	23.40	01.45	EL	CT,PT I/C AB Switch Insulator flash over at Gunrock Pump House	-
3		Thirumalgiri	Sri Nagar Colony	11KV	C-VI	22.27	23.58	01.31	OL-Yph	Tree Branches fallen on lines at Sri Nagar Colony	-