

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		4		4		4			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>10</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	2	2	2	2	2			
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>7</b>	<b>2</b>	<b>7</b>	<b>2</b>	<b>7</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>17</b>	<b>2</b>	<b>17</b>	<b>2</b>	<b>17</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 15.09.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	G.R Cable	33KV	Jadcherla	01.10	09.45	08.35	EL	1No Insulator Replaced Near Thiruimalapur SS	Balanagar	No
2		Amangal	Polepally	33KV	Shadnagar	01.50	06.30	04.40	EL	Insulator Binding Replaced at Jangareddypally	Amangal	No

TSSPDCL - LMRC / Corporate office

Date: 15.09.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Khanapur	11KV	Jadcherla	02.20	10.35	08.15		11 KV Wire Cut Near Chamagadda thanda.	-
2		Thirmalapur	Dondlapally	11KV	Jadcherla	09.47	11.50	02.03		11 KV Disc Fail Near Dondlapally.	-
1	NLG	Chervupally	Dacharam	11KV	Nalgonda	06.00	09.00	03.00	E/L	11KV Jumper cut	-
2		N Annaram	Lingala	11KV	Suryapet	06.50	09.30	02.40	E/L	Conductor snapped	-
3		Dondapahad	Vajinepally	11KV	Huzurnagar	06.00	08.45	02.45	EL	11 KV LINE SNAPPED	-
4		Keethavarigudem	Velidanda	11KV	Huzurnagar	05.00	07.35	02.35	EL	11KV LINE SNAPPED	-
5		Palakeedu	Nagireddy gudem	11KV	Huzurnagar	07.00	10.30	03.10	EL	11 KV JUMPER CUT	-
1	RR S	Chanda Nagar	Tara Nagar	11KV	Gachibowli	15.55	17.50	01.55	BD	Tree branches fallen on the 11kv line at Telephone Colony , and Darga T/F failed	-
2		Kaithalapur	Kaithalapur	11KV	Kondapur	02.25	03.35	01.10	BD	11kv Pin-insulator failed at Kaithalapur thanda	-
1	RR N	Madinaguda	J P N nagar	11KV	Kukatpally	13.37	15.08	01.31	EL/OL	11kv AB cable Failure at Krushinagar	-
2		Jeedimetla-III	U S P organic	11KV	Jeedimetla	05.30	13.10	07.40	EL/OL	11kv AB cable Failure at Monica Company	-
3		Town Medchal	Country Club	11KV	Medchal	13.40	15.00	01.20	EL/OL	No Fault	-
1	RR E	Cherlapally-I	Phase-I	11KV	Sainikpuri	22.20	23.00	00.40		11KV Insulater Failed at Vasista Company	-
1	HYD N	Clock Tower	Anjali	11KV	Sec-Bad	01.48	03.26	01.38	All Indication	3Way R.M.U fault at Mahaboob College	Arranged B/F on 11KV Old Jailkhana fdr
2		Yousufguda	Celebration	11KV	Banjarahills	02.38	03.45	01.07	EL,OL-Bph	Tree branches fallen on lines at J'Hills Chech Post	-
3		Kundanbagh	B.S.Maktha	11KV	Erragadda	17.06	18.18	01.12	EL,OL-Rph	Pin Insulator flash over at Pochamma Temple	-
1	HYD S	Sultan Bazar	Taraka Rama	11KV	Begumbazar	12.45	13.47	01.02	EL	under Breakdown	Arranged B/F on 11KV Ramkoti fdr