

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		7		7		7			
3	MDK	107	933		1		1		1			
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	12	2	12	2	12	0	0	
	Grand Total	1082	6468	2	15	2	15	2	15	0	0	

TSSPDCL - LMRC / Corporate office

Date: 16.09.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1		Nagarkurnool	lthole	33KV	Nagarkurnool	00.10	06.10	06.00	EL	No Visible fault	Nagarkurnool	No
2	MBNR	Achampet	Veltoor	33KV	Nagarkurnool	14.10	20.45	06.35	EL	Insulator Replaced & Tree Branches Removed Near Koritikal Village & Poljala Village	Achampet	No

TSSPDCL - LMRC / Corporate office

Date: 16.09.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kethepally	Inupamula	11KV	Nalgonda	07.00	12.50	05.50	E/L	SS-6 DTR Damaged	-
2		SV College	New Busstand	11KV	Suryapet	05.50	07.35	01.45	E/L	11Kv Insulator failed	-
3		Aipoor	Aipoor	11KV	Suryapet	13.45	15.00	01.15	E/L	11Kv Disc failed	-
4		Ananthagiri	V R Puram	11KV	Huzurnagar	06.00	08.30	02.30	E/L	11 KV LINE SNAPPED	-
5		Akupamula	Akupamula	11KV	Huzurnagar	05.20	07.30	02.10	E/L	11 KV DISK FAILED	-
6		Nadigudem	Karvirala	11KV	Huzurnagar	14.10	16.05	01.55	E/L	11 KV DISK FAILED	-
7		MT.Pally	Mogilipaka	11KV	Choutuppal	10.30	12.35	02.05	E/L	11Kv Pin Insulator Failed at Doctor Well near Mogilipaka (V)	-
1	MDK	Sadasivpet	TSM	11KV	Sangareddy	02.04	07.09	05.05		B/D Due to tree falldown on line at IBZA company	-
1	SDPT	Gurjakunta	Dommata	11KV	Husnabad	03.40	07.00	03.20		BD, Due to rain	-
2		Rebarthy	Gagillapur Agl	11KV	Husnabad	04.05	07.50	03.45		BD, Due to rain	-
3		Cherial Town	Cherial-Town	11KV	Husnabad	04.10	04.40	00.30		BD, Insulator failure	-
4		Thotapally	Anthakkapet	11KV	Husnabad	06.00	07.00	01.00		BD, Tree fallen on conductor	-
1	HYD C	Asif Nagar	Military	11KV	Mehdipatanam	00.50	02.10	01.20	EL,OL	Tree branches on lines at Military Water Works	-
2		I.T.I Mallepally	P.S Nagar	11KV	Mehdipatanam	01.00	02.57	01.57	EL,OL	Pin Insulator flash over & Tree branches on lines at Water Works	-
3		Toli Chowki	Hakimsha	11KV	Mehdipatanam	10.34	12.00	01.26	OL-Y&Bph	No Visible Fault	-