

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	11	1	11	1	11			
7	RR(E)	168	403		6		6		6			
8	Hyd	194	1044		15		15		15			
	Total	606	3055	1	33	1	33	1	33	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	6	4	6	4	6			
2	NLG	144	988		59		59		59			
3	MDK	107	933		4		4		4			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	69	4	69	4	69	0	0	
	Grand Total	1082	6468	5	102	5	102	5	102	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.09.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Polepally	Konded	33KV	Jadcherla	03.02	04.05	01.03	E/L	Pin Insulator Damaged at Gollapally (vi)	Konded	-
2		Makthal	Krishna	33KV	Narayanapet	04.25	06.55	02.30	O/L	Tree Branches Fallen on the Line	Krishna	-
3		Maddur	Vepoor	33KV	Narayanapet	15.55	18.30	02.35	E/L&O/L	Line Phase to Phase at 6th Pole Near 132KV SS Maddur	Vepoor	-
4		Kodangal	Hamsanpally	33KV	Vikarabad	02.55	03.25	00.30	E/L	Jumper Open at Hamsanpally	Hamsanpally	-
1	RR N	132KV Medchal	33KV Keshavaram	33KV	Medchal	23.07	04.12	05.05		Tree fallen on the 33KV Line near Medicity SS	33KV Keshavaram	-

TSSPDCL - LMRC / Corporate office

Date: 18.09.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Fathepur	11kv	Jadcherla	05.00	08.22	03.22		Tree Fallen the line near Fathepur	-
2		Rajapur	Mallepally	11kv	Jadcherla	03.00	13.40	10.40		100KVA DTR Fail near Mallepally	-
3		Rajapur	Rajapur	11kv	Jadcherla	03.00	07.00	04.00		Phase to Phase near Rajapur	-
4		Teegalapally	Kakarlapadu	11kv	Jadcherla	05.00	09.00	04.00		11KV Disk fail near Kakarlapadu	-
5		Pomal	Ammapur	11kv	Jadcherla	05.00	09.30	04.30		11KV Wire cut near Pomal	-
6		Kothamolgara	Madigatla	11kv	Jadcherla	03.20	07.10	03.50		11KV Insulator fail near Madigatla	-
1	NLG	Kethepally	Inipamula	11kv	Nalgonda	07.30	10.00	02.30	E/L	Tree Branches Fallen on 11 KV Line	-
2		Palem	Ogodu	11kv	Nalgonda	00.00	11.20	11.20	E/L	Tree Fallen on 11 KV Line	
3		Palem	Palem	11kv	Nalgonda	00.00	10.40	10.40	E/L	Tree Fallen on 11 KV Line	
4		P.D.Pally	Kanchanapally	11kv	Nalgonda	17.05	08.12	15.17	E/L	11KV Insulators failed	
5		Velgupally	G.K.Annaram	11kv	Nalgonda	17.05	14.00	21.00	E/L	11KV line cut	
6		Thipparthi	Gangannapalem	11kv	Nalgonda	06.50	11.00	04.10	E/L	11KV Jumper cut	
7		Pajjur	K.Ramaram	11kv	Nalgonda	07.00	10.00	03.00	E/L	Tree Branches Fallen on 11 KV Line	
8		Rajupeta	Jonnagadlagudem	11kv	Nalgonda	18.30	12.00	18.30	E/L	Tree Fallen on 11 KV Line	
9		Thimmannagudem	Ch.Chennaram	11kv	Nalgonda	16.00	09.00	17.00	E/L	11KV Insulators failed	
10		Thimmannagudem	Narsimhapuram	11kv	Nalgonda	07.00	14.00	07.00	E/L	11KV line cut	
11		Thoragal	Madaram	11kv	Nalgonda	06.00	13.50	07.50	O/L	VCB problem	
12		Thoragal	Thoragal	11kv	Nalgonda	06.00	10.30	04.30	E/L	11KV Jumper cut	
13		Narketpally IE	Pump House	11kv	Nalgonda	02.55	11.00	08.05	E/L	11KV Jumper cut	
14		Narketpally IE	Vanipakal Agl	11kv	Nalgonda	06.00	10.30	04.30	E/L	11KV Insulators failed	
15		B.Vellemla	B.Vellemla AGL	11kv	Nalgonda	19.00	11.30	16.30	E/L	Tree Fallen on 11 KV Line	
16		B.Vellemla	B.Vellemla Town	11kv	Nalgonda	17.00	08.00	15.00	E/L	Tree Branches Fallen on 11 KV Line	
17		B.Vellemla	Avuravani	11kv	Nalgonda	17.00	09.00	16.00	E/L	DTR Failed	
18		Gudapoor	Singaram	11kv	Nalgonda	17.00	14.00	21.00	E/L	11KV Jumper cut	
19		Gudapoor	Ragigudem	11kv	Nalgonda	17.00	11.30	18.30	E/L	11KV Jumper cut	
20		Nakrekal	Chandampally	11kv	Nalgonda	18.30	10.50	16.20	E/L	Tree Fallen on 11 KV Line	
21		Nakrekal	Marrur	11kv	Nalgonda	18.58	10.30	15.28	E/L	11KV Jumper cut	
22		Gattuppal	Lachammagudem	11kv	Nalgonda	10.15	11.15	01.00	E/L	11KV Jumper cut	
23		Chandur	Thummalapally	11kv	Nalgonda	18.00	12.50	18.50	E/L	11KV Jumper cut	
24		Chandur	Kastala	11kv	Nalgonda	18.00	10.30	16.30	E/L	Tree Branches Fallen on 11 KV Line	
25		Pullemla	Kondapuram	11kv	Nalgonda	22.00	10.00	12.00	E/L	11KV Jumper cut	
26		Arlagaddagudem	Mangalapally	11kv	Nalgonda	02.20	11.30	09.10	E/L	11KV Jumper cut	
27		Kadaparthky	Chandampally	11kv	Nalgonda	18.30	11.30	17.00	E/L	11KV Insulators failed	
28		Rajupeta	Bandavarigudem	11kv	Nalgonda	08.30	11.30	03.00	E/L	11KV line cut	
29		Veliminedu	Parepally	11kv	Nalgonda	08.00	12.00	04.00	E/L	Tree Branches Fallen on 11 KV Line	
30		Devarakonda	Devarakonda Town-1	11kv	Devarakonda	07.45	08.55	01.10	E/L	11KV Disk Failed	
31		Devarakonda	Mynampally	11kv	Devarakonda	05.30	07.30	02.00	E/L	HT/LT Line Melt	
32		Pochampally	Pochampally	11kv	Devarakonda	04.00	08.00	04.00	E/L	Jumper Cut	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
33	NLG	Chepur	Theratigudam	11kv	Devarakonda	05.15	09.15	04.00	E/L	11KV Insuletor Failed & Jumper Cut	
34		Koppole	Kolaram	11kv	Devarakonda	00.50	07.00	06.10	E/L	11KV line cut	
35		Gundepuri	Gundepuri	11kv	Suryapet	19.22	23.40	04.18	E/L	Insulator flashover	
36		Arvapally	Thungagudem	11kv	Suryapet	08.00	09.50	01.50	E/L	Insulator flashover	
37		Cheedella	Thangellagudem	11kv	Suryapet	03.40	08.20	04.40	E/L	2Nos Pole Damaged	
38		Ravulapally	Kukkadam	11kv	Suryapet	04.40	08.30	03.50	E/L	Insulator flashover	
39		Munagala	Turkagudem-1	11kv	Huzurnagar	06.00	09.30	03.30	EL	11 KV LINE SNAPPED	
40		Urlugonda	N S puram	11kv	Huzurnagar	06.30	09.00	02.30	EL	11 KV LINE SNAPPED	
41		Palakeedu	Janpahad Indl	11kv	Huzurnagar	04.00	06.30	02.30	EL	Heavy Rain problem Atomic Stand	
42		MT.Pally	Mulkalapally	11kv	Bhongir	07.00	10.00	03.00	EL	11 KV Disc Failed Near Mulkalapally Village	
43		Kondamadugu	Kepal Indl	11kv	Bhongir	21.50	01.40	03.50	EL	11 kv Pole Dammaged at Mahila mandal Office Near Kondamdugu Village	
44		B.Ramaram	Hajipur	11kv	Bhongir	03.00	07.00	04.00	EL	SS-11 11KV Insulator Failed	
45		Golankonda	Matoor	11kv	Bhongir	04.00	08.00	04.00	EL	1 Phase DTR Failed Near Matoor Village	
46		Datherpally	Mallapuram	11kv	Bhongir	03.30	09.10	05.40	EL	11 kv Insulator Failed Near Mallapuram Village	
47		Peddakandukur	Bahuoet	11kv	Bhongir	06.25	08.00	01.35	EL	11kv Line Snapped near	
48		Peddakandukur	Peddakandukur	11kv	Bhongir	08.00	10.05	02.05	EL	LT Line snapped near Pedda Kandukur Village	
49		Mothkur	Anajipur	11kv	Bhongir	06.50	09.15	02.25	EL	11 kv Insulator Failed Near Dacharam Village. 3 Phase B/d Single Phase OK	
50		Paladugu	Panakabanda	11kv	Bhongir	03.00	08.35	05.35	EL	11 kv Pole Dammaged & 11 LV Line Snapped Near Panakabanda Village	
51		Paladugu	Dattappagudem	11kv	Bhongir	03.00	07.00	08.15	EL	16kv DTR Failed near Podicheru Village	
52		Addagudur	Addagudur	11kv	Bhongir	02.30	06.00	03.30	EL	SS-3 DTR Insulator Failed 3 Phase B/d Single Phase OK	
53		Chada	Katepally	11kv	Bhongir	01.00	07.00	06.00	EL	11 kv Insulator Failed Near Katepally Village	
54		Ambala	Parupally	11kv	Bhongir	04.00	07.00	03.00	EL	11 KV Disc Failed Near Parupally Village	
55		Ishkilla	Munipampula	11kv	Choutuppal	02.00	08.00	06.00	EL	11 kv Insulator Failed Near Munipampula Village.3 Phase B/d Single Phase OK	
56		Ramannapet	Janmpally	11kv	Choutuppal	09.15	10.35	01.20	EL	11kv Insulator Failed near Janmpally Village	
57		Panhangi	Panhangi Agl	11kv	Choutuppal	05.06	08.32	03.26	EL	11 kv Disc Failed Near Areygudem Village	
58		Voligonda	Voligonda Twon	11kv	Choutuppal	19.40	22.30	02.50	EL	11kv Line snapped near POLE NO1 Voligonda Sub_station	
59		Golnepally	Golnepally	11kv	Choutuppal	11.50	12.25	00.45	EL	11kv Disc Filed near Golneypally Sub_station pole no 5	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MDK	Pati	Shalimar	11kv	Patancheru	00.05	07.00	06.55		B/D Due to Conductor Snapped and Jumper Cut	-
2		Dundigal	DRF Agl	11kv	Patancheru	00.00	05.00	05.00		B/D Due to Branches fallen on the line	-
3		Gundla Machnoor	Industrial	11kv	Patancheru	00.25	01.50	01.25		B/D Due to Jumper Cut	-
4		Inole	Bayers Corp	11kv	Patancheru	00.05	05.00	04.55		B/D Due to Branches fallen on the line	-
1	RR S	Gachibowli	Kalajyothi	11kv	Kondapur	01.40	02.40	01.00	BD	Tree branches fallen on the 11kv line at HCU	-
1	RR N	Dulapally	IDA-II	11kv	Medchal	00.55	02.55	02.00	BD	11KV Pin Insulator failed at Jwala Company	-
2		Subhash Nagar	Meenakshi	11kv	Medchal	00.00	01.26	01.26	BD	Tree fallen on the 11KV Line at Pudur Road	-
3		Kistapur	Time Techno	11kv	Medchal	00.30	04.20	03.50	BD	Tree fallen on the 11KV Line at Pudur Road	-
4		Kandlakoya	KV Reddy Nagar	11kv	Medchal	00.00	02.30	02.30	BD	Tree fallen on the 11KV Line at EMRI	-
5		Devarayamjal	Kottapet	11kv	Medchal	01.00	08.00	07.00	BD	11KV Disc failed at Devarayamjal Village	-
6		Athiwelly	Dabeerpur	11kv	Medchal	03.10	05.20	02.10	BD	11KV Pin Insulator failed at Athiwelly Village	-
7		Athiwelly	SPIC	11kv	Medchal	03.20	10.20	07.00	BD	11KV Pin Insulators failed at Crusher	-
8		Nuthankal	Bharathi	11kv	Medchal	05.25	06.30	01.05	BD	11KV Line cut and replaced at Grip Company	-
9		Yellampet	IDA Yellampet	11kv	Medchal	04.15	06.40	02.25	BD	Tree fallen on the 11KV Line at Petrol Pump	-
10		Suraram	Sriramnagar	11kv	Jeedimetla	07.15	08.40	01.25	BD	CTBT Failure at Sapthagiri,Patedhar Company,Sriramnagar	-
11		Bowrampet	AGL	11kv	Jeedimetla	13.20	14.25	01.05	BD	A bird fallen the 11kv line at Opp:DRK Collage	-
1	RR E	Moula-Ali	Mirzalguda	11kv	Sainikpuri	21.50	22.25	00.35		Tree branches fallen on 11Kv line at RPF Compound (Artisan Bal Narsihma)	-
2		Singapur	RGK	11kv	Keesara	22.00	01.30	03.30		Tree fallen on 11kv line at RGK Block 30 & Disc failed at NTPC	-
3		Singapur	Singapur2	11kv	Keesara	02.30	04.00	01.30		11KV 2 No's Insulator failed at Block C8 & C9	-
4		P&T Colony	NIN	11kv	Keesara	04.10	06.20	02.10		11KV Post of Insulator failed at Happy Homes	-
5		Nagaram	Bandlaguda	11kv	Keesara	03.15	05.02	01.47		Tree branches fallen on 11kv line at Bharath Rathna School	-
6		Aushapur	NFC Nagar	11kv	Keesara	01.00	09.00	08.00		11KV Pin Insulator failed at Aushapur Road, 11KV Polymer disc failed at SS Yard & 100KVA T/F lighting erector failed at Dathathreya Colony	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	Seethaphal Mandi	Medi Bavi	11kv	V	00.05	03.00	02.55	EL,OL-Rph	DTR Cable fault at Uppalamma PT	-----
2		I.D.P.L	SVCIE	11kv	VI	00.08	01.15	01.07	EL,OL-Rph	No Visible Fault (Due to Rain)	-----
3		R.P.Nilayam	Raithu Bazar	11kv	C-VI	01.22	04.10	02.48	EL,OL-Rph	No Visible Fault (Due to Rain)	Arranged B/F on 11KV Allwal fdr
4		Nehru Nagar	Rezimental Bazar	11kv	V	02.50	04.25	01.35	OL-Rph	Cable fault at Ratnadeep Super Market	-----
5		H.P.S	Post Office	11kv	IV	08.36	09.56	01.20	EL	UG Cable fault at Geethanjali School	-----
6		Chilkaiguda	P.R.Nagar	11kv	V	09.55	11.35	01.40	EL,OL	End Kit failed at Jayachandra Apts	-----
7		Patigadda	Sindhi Colony	11kv	V	12.02	13.05	01.03	EL,OL-Bph	UG Cable damaged near Patigadda SS	Arranged B/F on 11KV D.V.Colony fdr
1	HYD S	Falaknuma	Aliyabad	11kv	III	04.35	06.10	01.35	EL	No Visible Fault (Due to Rain)	Arranged B/F on 11KV Rooplal Bazar fdr
1	HYD C	A.S.R.Raju Nagar	Jeevan Kalyan Nagar	11kv	VII	00.05	02.45	02.40	EL,OL	No Visible Fault (Due to Rain)	-----
2		Nampally	Yousufin Darga	11kv	VII	00.34	03.22	02.48	EL	AB Cable fault at Lorry Adda	-----
3		ITI Mallepally	Indira Nagar	11kv	VII	00.26	03.34	03.08	EL,OL	Pin Insulator flash over at Owasi Park	-----
4		Asif Nagar	Padmanabha Nagar	11kv	VII	01.10	02.57	01.47	EL,OL-Bph	Pin Insulator flash over & Tree branches fallen on lines at 777 Hotel	-----
5		Golconda	Mothi Mahal	11kv	VII	01.45	04.25	02.40	EL,OL-Bph	Tree branches fallen on lines at Nadeem Colony	-----
6		Nizam College	Shantha Bai Nursing Home	11kv	I	03.10	05.30	02.20	EL	No Visible Fault (Due to Rain)	-----
7		Nizam College	Galaxy Hotel	11kv	I	16.14	18.30	02.16	EL,OL	Cable fault at Himayath Nagar	Arranged B/F on 11KV A.P.Tourism fdr