

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	3	1	3	1	3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		4		4		4			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	7	3	7	3	7			
2	NLG	144	988	1	9	1	9	1	9			
3	MDK	107	933	3	1	3	1	3	1			
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>8</b>	<b>20</b>	<b>8</b>	<b>20</b>	<b>8</b>	<b>20</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>9</b>	<b>28</b>	<b>9</b>	<b>28</b>	<b>9</b>	<b>28</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 19.09.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Machanpally	33KV	Mahabubnagar	08.40	13.10	04.30	E/L	Tree fallen on the line	Machanpally	No
2		Nagarkurnool	lthole	33KV	Nagarkurnool	07.14	08.10	00.56	E/L	No visible fault	lthole	No
3		Maddur	Vepoor	33KV	Narayanapet	18.30	21.00	02.30	E/L&O/L	Due to rain	Vepoor	Alternate supply given from Parepally SS
1	NLG	Nalgonda	Anneparthi	33KV	Nalgonda	7:25	10:00	2:35		Crow died on 33KV line at Arjalabavi (V)	Anneparthi	No
1	MDK	Sadasivpet	Munipally	33KV	Sangareddy	2:00	6:35	4:35		Insulator failed	Munipally	No
2		Bollaram	Anrich	33KV	Patancheru	14.20	15.20	01.00		Jumper cut	Anrich	No
3		Gummadidala	GPSS-II	33KV	Patancheru	19.20	20.10	00.50		Insulator failed	GPSS-II	No
1	SDPT	Gajwel	Mulugu	33KV	Gajwel	6:15	16:25	10:10		Insulator disc replacement near bakthiram thota	Mulugu	No
1	RR N	132KV Medchal	Bandamadaram	33KV	Medchal	3:30	9:05	5:35		33KV Line AB Switch Opened at near Kandlakoya (End Kit failed at ORR)	Bandamadaram	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Udithyal	Macharam	11KV	Jadcherla	08.45	15.00	06.15		11KV Phase to Phase near Suraramvagu Side	No
2		Teegalapally	Teegalapally	11KV	Jadcherla	09.00	13.35	04.35		11KV Jumper cut near Teegalapally (V)	No
3		Kothamolgara	Maddigatla	11KV	Jadcherla	01.00	11.10	10.10		11KV Disc failed & 11KV Jumper cut near Maddigatla (V)	No
4		Karvena	Karvena	11KV	Jadcherla	7:35	12:10	4:35		11KV Insulator failed near kothamolgara (V)	No
5		Kollur	Rural	11KV	Jadcherla	9:00	13:50	4:50		11KV Jumper cut near Kollur ( V)	No
6		Pomal	Pomal	11KV	Jadcherla	10:20	12:56	2:36		11KV Jumper cut near Pomal ( V)	No
7		Gangapur	Alwanpally	11KV	Jadcherla	00.30	08.30	08.00		Insulator failed near gangapur SS	No
1	NLG	Turkapally	M.Gouraram	11KV	Nalgonda	10:14	11:46	1:32	E/L	11KV Jumper cut	No
2		Pamanagundla	Pittampally	11KV	Nalgonda	11.55	13.48	01.53	E/L	11KV Jumper cut	No
3		Mattapally	Mattapally	11KV	Huzurnagar	08.55	11.55	03.00	EL/OL	11KV Line snapped	No
4		Repala	V R Puram	11KV	Huzurnagar	06.10	09.15	03.05	E/L	11KV Jumper cut	No
5		Urulugonda	Thummagudem	11KV	Huzurnagar	07.00	09.45	02.45	E/L	11KV Jumper cut	No
6		Nemaragomula	Nemaragomula	11KV	Bhongir	07.50	11.20	03.30	EL	11KV Insulator failed near Nemaragomula Village	No
7		Choutuppal	Chinna kondur	11KV	Choutuppal	06.00	08.15	02.15	EL	11KV Disc failed near Chinna kondur Village	No
8		Choutuppal	Thangadapally	11KV	Choutuppal	10.30	14.00	03.30	EL	11KV Insulator failed near Thangadapally Village	No
9		Narayanpur	Guddimalkapur	11KV	Choutuppal	6:00	9:00	3:00	EL	11KV Insulator failed near Guddimalkapur Village	No
1	MDK	Cheryal	Turbovent	11KV	Sangareddy	2:00	6:00	4:00		Insulator failed	No
1	SDPT	Cherial Town	Cherial-Town	11KV	Husnabad	13:10	14:34	1:24		Jumper problem	No
2		Cherial Town	Rollabanda Agl	11KV	Husnabad	15.50	16.18	00.28		Insulator burst	No
3		Nagapuri	Nagapuri	11KV	Husnabad	08.20	09.30	01.10		Insulator failed	No
1	RR N	Nuthankal	Bharathi	11KV	Medchal	9:10	10:20	1:10		Bird fallen on the 11KV line at Shekhar Reddy Bore Well	No
2		Yellampet	IDA Yellampet	11KV	Medchal	16.10	17.10	01.00		Tree fallen on the 11KV line at Yellampet Village	No
3		Vijayanagar	Yellammabanda	11KV	Kukatpally	15.50	17.00	01.10		Star Wire fallen on the 11KV line	No
1	RR E	Moula-Ali	HCL	11KV	Sainikpuri	20:45	21:23	0:38		11KV Pin insuletor failed at Krishna Nagar	No
1	HYD S	Laxmi Nagar	Singareni Colony	11KV	VIII	14.28	15.43	01.15	EL	Jumper cut at Cable Raising Point	Arranged B/F on 11KV Saraswathi Nagar & 11KV Shankeshwara Bazar feeders
2		Malakpet B-Block	C-Quarters	11KV	VIII	17:17	18:37	1:20	EL	Tree branches fallen on lines at C-Quarters	Arranged B/F on 11KV Samatha Degree College feeder
1	HYD C	Asif Nagar	N.S.F Colony	11KV	VII	02.43	04.20	01.37	EL	Tree branches fallen on lines at Niraja Colony & AB Switch fault at Ice Depot	No
2		A.S.R.Raju Nagar	Jeevan Kalyan Nagar	11KV	VII	11.25	12.48	01.23	EL,OL	Pin Insulator flash over at Roya Residence & Tree branches fallen on lines at J.K.Nagar	No