

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550	1	9	1	9	1	9			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044	1	3	1	3	1	3			
	Total	606	3055	2	17	2	17	2	17	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		12		12		12			
3	MDK	107	933									
4	SDPT				6		5		5		1	1 No.11KV Still pending
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	18	2	17	2	17	0	1	
	Grand Total	1082	6468	4	35	4	34	4	34	0	1	

TSSPDCL - LMRC / Corporate office

Date: 20.09.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kodangal	Kodangal	33KV	Vikarabad	08.35	11.05	02.30	E/L	Due to disc Insulator failed	Kodangal	No
2		Maddur	Damargidda	33KV	Narayanpet	16.40	19.10	02.30	E/L	Kyathanpally SS 132KV SS Incoming Breaker fault	Damargidda	No
1	RR N	132KV Malkaram	Ratnalayam	33KV	Medchal	0:00	11:27	11:27		33KV Line AB Switch opened at Bits Campus	Ratnalayam	No
1	HYD S	132KV Imlibun	Salarjung	33KV	Malakpet	16.21	16.29	00.08	OL-Rph	Cable fault	Salarjung	Loads transferred onto 132KV Imlibun SS via 33KV Seetharam Bagh fdr

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Aitipamula	GD Gudem	11KV	Nalgonda	6:30	11:30	5:00	E/L	11KV Tree branch fallen on the 11KV line	No
2		Pamanagundla	Pittampally	11KV	Nalgonda	1:00	8:18	7:18	E/L	11KV Jumper cut and 2 Nos. DTRs Jumpers Open	No
3		Pamanagundla	Pittampally	11KV	Nalgonda	3:18	12:15	8:57	E/L	11KV Jumper cut	No
4		Athmakur(S)	Town feeder	11KV	Suryapet	5:25	7:30	2:05	E/L	11KV Insulator flashed over	No
5		Gaddipally	Gaddipally	11KV	Huzurnagar	4:00	6:30	2:30	E/L	11KV Line Snapped	No
6		Urlugonda	Tummagudem	11KV	Huzurnagar	10:40	13:00	2:20	E/L	11KV Line Snapped	No
7		Anantharam	Anantharam	11KV	Bhongir	21:00	3:20	6:20	E/L	11KV Disc failed near Tajpur Village	No
8		NG.Bandal	Veerareddypally	11KV	Bhongir	5:30	9:45	4:15	EL/OL	Thirumalapuram Village SS-16 63 KVA DTR Failed	No
9		Rajapet	Pamkunta	11KV	Bhongir	07.00	09.50	02.50	EL/OL	11KV Line snapped near Pamkunta Village	No
10		BP.Pally	Deshmukhi	11KV	Choutuppal	22.00	23.00	01.00	E/L	11KV Insulator failed near Deshmuki Village	No
11		Voligonda	Nagaram	11KV	Choutuppal	09.00	13.00	04.00	E/L	11KV Line snapped near Nagaram Village	No
12		Voligonda	Voligonda	11KV	Choutuppal	11:30	12:30	1:00	E/L	11KV Insulator failed near Nagaram Village	No
1	SDPT	Akunoor	Akunoor Agl	11KV	Husnabad	10:30	0:00	13:30			No
2		Chityal	Thadoor	11KV	Husnabad	11.25	14.55	03.30		Disc failed	No
3		Gandipally	Ramavaram	11KV	Husnabad	04.20	07.20	03.00		Insulator failed	No
4		Marmamula	Salakpoor	11KV	Husnabad	02.40	09.55	07.15		Insulator failed	No
5		Nagapuri	Pothireddypalli	11KV	Husnabad	19.10	21.10	02.00		Insulator failed	No
6		Thotapally	Gandinagar	11KV	Husnabad	12:10	16:50	4:40		Insulator failed	No
1	RR S	Chanda Nagar	Market	11KV	Gachibowli	14:15	15:50	1:35		11KV Conductor snapped at Tara Nagar Market	No
2		Huda Truck park	Raghavendra Colony	11KV	Kondapur	15.11	16.25	01.14		Tree branches fallen on the 11KV Line at Metro backside	No
1	RR N	Jagathgirigutta	Jagathgirigutta	11KV	Medchal	15:05	16:45	1:40		11KV Pin Insulator failed at Gynana Saraswathi School, Jagathgirigutta	No
2		Chintal	Dwaraka Nagar	11KV	Medchal	15.30	18.30	03.00		11KV Line Reconductoring work at Dwaraka Nagar	No
3		Dulapally	KK Society	11KV	Medchal	15.48	17.15	01.27		11KV Pin Insulator Failed at Shivalok Complex, IDA Dulapally	No
4		Athiwelly	Athiwelly	11KV	Medchal	00.18	02.10	01.52		11KV Pin Insulator Failed at near by Shantha Biotech	No
5		Athiwelly	SPIC	11KV	Medchal	05.45	07.20	01.35		Tree Fallen on 11KV Line at Subbaraju Poultry farm	No
6		Shameerpet	Nalsar	11KV	Medchal	23.30	01.25	01.55		Tree Fallen on 11KV Line at Bus Stop, Shameerpet	No
7		Shameerpet	Shameerpet	11KV	Medchal	23.30	07.30	08.00		Tree Fallen on 11KV Line at St.Pal's School, Shameerpet	No
8		Aliabad	HBL	11KV	Medchal	17.15	17.55	00.40		11KV Disc Failed at CRV college, LGM Pet	No
9		Kandlakoya	KV Reddy Nagar	11KV	Medchal	18:25	19:10	0:45		Tree Fallen on 11KV Line at Engine oil company	No
1	RR E	IDA Uppal	Metro	11KV	Habsiguda	15:22	16:00	0:38		Tree fallen on 11KV line near RN Filters at IDA Uppal	No
2		Kushaiguda	Kushaiguda	11KV	Sainikpuri	15.55	18.15	02.20		Car dashed to 11KV pole at Vimal Show Room	No
3		Peerzathiguda	Peerzathiguda	11KV	Keesara	17.09	19.15	02.06		11KV Brass patti cut at Ayyangar Bakery Opposite	No
1	HYD N	Lalaguda	St. Ann's	11KV	V	07.46	08.59	01.13	EL, OL-Bph	No visible fault	Arranged B/F on 11KV Solex feeder
2		N.I.M.S	Tata Rao	11KV	X	16:50	19:35	2:45	EL	Breaker fault at SS	Arranged B/F on 11KV E-Seva feeder
1	HYD C	Fever Hospital	Barkathpura Bus Depot	11KV	II	17.03	18.35	01.32	All Indication	Cable End Kit failed at Raghavendra Hotel	Arranged B/F on 11KV Nallakunta fdr