

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		9		9		9			
6	RR(N)	54	550	1	6	1	6	1	6			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044	2	8	2	8	2	8			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>3</b>	<b>27</b>	<b>3</b>	<b>27</b>	<b>3</b>	<b>27</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		9		9		9			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>9</b>	<b>2</b>	<b>9</b>	<b>2</b>	<b>9</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>5</b>	<b>36</b>	<b>5</b>	<b>36</b>	<b>5</b>	<b>36</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 22.09.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kosgi	Surayapally	33KV	Mahabubnagar	19.05	22.30	03.25	E/L	for Pin Insulator Replaced at Challapur	Kosgi	No
2		Kothur	PNG	33KV	Shadnagar	16.40	18.45	02.05	E/L	for Disk Replacement at Vinayaka company	Kothur	No
1	RR N	132KV Medchal	33KV Keshavaram	33KV	Medchal	11.40	14.00	02.20	BD	No Fault		-
1	HYD N	132KV Hubilee Hills	Road No.2	33KV	Kalyannagar	12.57	13.00	00.03		End kit failed at Jubilee hills Cheakpoint		Loads transferred onto 132KV Erragadda SS via 33KV LV prasad Marg UG fdr
1	HYD S	132KV Moosarambagh	Durga Nagar	33KV	Chilkaiguda	09.18	09.26	00.08		O/G side Endkit failed at 132KV Mossarambagh SS		Loads transferred onto 132KV Moosarambagh SS via 33KV Amberpet fdr.

TSSPDCL - LMRC / Corporate office

Date: 22.09.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Jalapuram	Mamidala	11KV	Suryapet	08.00	10.10	02.10	E/L	Tree branch fallen on the line	-
2		Mattampally	Erajelu	11KV	Huzurnagar	08.55	12.00	03.05	E/L	Due to 11Kv insulator	-
3		Mattapally	Ramachandhrapuram	11KV	Huzurnagar	12.30	14.30	02.00	E/L	Due to 11Kv jumper cutted	-
4		Thogarrai	Thogarrai	11KV	Huzurnagar	09.10	10.16	01.06	E/L	Due to HT/LT fault occurred	-
5		Rajapeta	Renikunta Agl	11KV	Bhongir	10.15	14.30	04.15	E/L	11 kv Insulator Failed	-
6		Rajapeta	Pamukunta	11KV	Bhongir	08.05	11.30	03.25	E/L	11 kv Disc Failed	-
7		Addagudur	CH.Ramaram	11KV	Bhongir	14.30	16.45	02.15	E/L	Insulator Failed	-
8		Choutuppal	Jublakpally	11KV	Choutuppal	07.00	11.10	03.10	E/L	11 kv Insulator Failed	-
9		S.Lingotam	Lingoigudem	11KV	Choutuppal	09.10	12.22	03.12	E/L	11 KV Insulator Failed	-
1	RR S	ESCI	Divyasree NSL	11KV	Gachibowli	02.08	08.10	06.02		HT Service internal cable problem at Divyasree NSL	-
2		IIT	Kendriya Vihar	11KV	Gachibowli	16.25	18.15	01.50		11kv Cable failed at Indra nagar, Bank line	-
3		Hafeezpet	Vyshali Nagar	11KV	Gachibowli	16.10	17.20	01.10		Tree fallen on the 11kv line at Vyshali nagar	-
4		Madinaguda	Allwyn Colony	11KV	Gachibowli	16.28	17.52	01.24		T/F HG fuse insulator failed at Madinaguda village	-
5		Chandanagar	Madinaguda	11KV	Gachibowli	16.20	16.30	00.10		T/F HG fuse insulator failed at Madinaguda masjeed	-
6		Chandanagar	Mythri Nagar	11KV	Gachibowli	16.15	17.30	01.15		Tree fallen on the 11kv line at Vyshali nagar, C-block	-
7		L & T	PJR Nagar	11KV	Gachibowli	17.40	19.05	01.25		Srinu patel T/F disc failed at Telecom nagar	-