

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		4		4		4			
6	RR(N)	54	550	1	16	1	16	1	16			
7	RR(E)	168	403		9		9		9			
8	Hyd	194	1044	1	41	1	41	1	41			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>70</b>	<b>2</b>	<b>70</b>	<b>2</b>	<b>70</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	6	5	6	5	6	5			
2	NLG	144	988	2	19	2	19	2	19			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				14		14		14			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>9</b>	<b>39</b>	<b>9</b>	<b>39</b>	<b>9</b>	<b>39</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>11</b>	<b>109</b>	<b>11</b>	<b>109</b>	<b>11</b>	<b>109</b>	<b>0</b>	<b>0</b>	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Buddaram	33KV	Wanaparthy	01.10	07.04	05.54	O/L	Tree Branches fallen on the line at Polkepadu (V)	Buddaram	No
2		Wanaparthy	Buddaram	33KV	Wanaparthy	12.37	16.18	03.41	E/L	Disc flashover at Thadipathri Gutta	Buddaram	No
3		Ghanapur	Lattupally	33KV	Wanaparthy	01.40	09.02	07.22	E/L	Isolator opened Supply Stood OK	Lattupally	No
4		Gadwal	Oil Seeds	33KV	Gadwal	1:25	7:40	6:15	E/L	Insulator damaged Near Berelly	Oil Seeds	No
5		Kothur	Thimmapur	33KV	Shadnagar	2:30	11:00	8:30	E/L & O/L	Insulator damaged at Venkateshwara Hatcheries	Thimmapur	No
6		Kothur	PNG	33KV	Shadnagar	02.25	14.40	12.15	O/L	Pin insulator damaged at KDL Company	PNG	No
1	NLG	Mattampally	B.N.L thanda	33KV	Huzurnagar	14:30	18:00	3:30	EL/OL	Cabel fault	B.N.L thanda	No
2		Aitipamula	Nakrekal	33KV	Nalgonda	17.15	20.00	02.45	EL	33KV Line jumper cut	Nakrekal	No
1	MDK	Kandi	Signod	33KV	Sangareddy	6:10	9:45	3:35		Jumper Cut	Signod	No
1	RR N	132KV LGM Pet	Aliabad	33KV	Medchal	4:47	11:33	6:46		33KV Pin insulator failed at SR Petrol Pump Opposite	Aliabad	No
1	HYD C	132KV N.I.M.S	Erramanzil	33KV	H' Sagar	14.26	14.36	00.10	OL-Yph	Cable End Kit failed	Erramanzil	Loads transferred onto 132KV Erragadda SS

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Narva	Raicode	11KV	Mahabubnagar	03.50	09.00	05.10		11KV Disc failure near Raicode(V)	No
2		Abhagapatnam	Kanaipally	11KV	Mahabubnagar	03.40	11.00	07.20		11KV Insulator failure Near Kanaipally (V)	No
3		Kodur	Kodur JPNCE	11KV	Mahabubnagar	02.10	08.25	06.15		11KV Conductor cut at Boklonipally (V)	No
4		Udityal	Udityal	11KV	Jadcherla	5:06	8:10	3:04		11KV Disc failed near Adavi Bavulu	No
5		Boothpur	Town	11KV	Jadcherla	13.30	15.30	02.00		11 KV Disc failed near Moosa Dhaba	No
1	NLG	Arlagaddagudem	N.R.Gudem	11KV	Nalgonda	6:50	13:40	6:50	O/L	11KV Jumper cut	No
2		Arlagaddagudem	Suraram	11KV	Nalgonda	06.50	09.00	02.10	E/L	11KV Jumper cut	No
3		Kethepally	Korlapahad	11KV	Nalgonda	07.30	12.20	04.50	E/L	11KV Insulator failed	No
4		Shivannagudem	Venkapally	11KV	Devarakonda	02.30	09.00	06.30	E/L	11 Kv Line cut	No
5		Shivannagudem	Water works	11KV	Devarakonda	02.30	10.30	08.00	E/L	Tree Fllowen	No
6		Reddygudem	Kothagudem	11KV	Suryapet	05.00	07.10	02.10	E/L	Insulator failed	No
7		Athmakur(S)	Town feeder	11KV	Suryapet	07.30	09.00	01.30	E/L	Insulator failed	No
8		Palakaveedu	Bothalapalem	11KV	Huzurnagar	05.20	08.20	03.00	EL	Due to 11kv line jumper cutted	No
9		Garidepally	L B Nagar	11KV	Huzurnagar	05.00	07.25	02.25	EL	Due to 11kv line jumper cutted	No
10		Munagala	Bharakath Gudem	11KV	Huzurnagar	05.50	08.50	03.00	EL	Due to 11kv line snapped	No
11		Repala	V R Puram	11KV	Huzurnagar	11.35	14.40	03.05	EL	Due to 11Kv Disk failed	No
12		Bollepally	Jumpally	11KV	Bhongir	03.00	07.00	04.00	EL	11kv Insulator Failed & HT/LT near Srinivaskunta	No
13		Kondamadugu	kepal Indl	11KV	Bhongir	09.05	11.30	02.25	EL/OL	11kv Insulator Failed near Sai baba Tempul	No
14		Golankonda	Golankonda	11KV	Bhongir	11.50	14.00	02.10	EL/OL	11kv Disc Failed near Golankonda Village 3 Phase B/d Single phase ok	No
15		Golankonda	Vanchyagudem	11KV	Bhongir	14.30	16.00	01.30	EL/OL	11kv Line Snapped near Vanchagudem Village 3 Phase B/d Single phase ok	No
16		Datherpally	Jangampally	11KV	Bhongir	03.30	08.45	05.15	EL	11 kv Insulator Failed Near Jangampally Village. 3 Phase B/d Single phase ok	No
17		Motakondur	Vartoor	11KV	Bhongir	03.30	09.00	05.30	EL	11 kv Line Snapped Near Vartoor Village	No
18		Jangam	Vailapally	11KV	Choutuppal	03.00	08.40	05.40	EL/OL	11 kv Insulator Failed Near Vailapally Village	No
19		Puligilla	Kerchipally	11KV	Choutuppal	3:15	12:35	9:20	EL/OL	11kv Disc Failed near Veerappa gadda 3 Phase B/d Single phase ok	No
1	MDK	Kistareddypet	Industrial	11KV	Patancheru	11:40	12:40	1:00		Conductor snapped	No
1	SDPT	Komuravelly	Inapur agl	11KV	Husnabad	8:10	10:10	2:00		Tree branches fallen on the line	No
2		Komuravelly	Kistampet	11KV	Husnabad	06.35	11.20	04.45		Insulator failed	No
3		Komuravelly	Peddrajpet	11KV	Husnabad	14.50	16.30	01.40		Tree branches fallen on the line	No
4		Nagapuri	Pothireddypally	11KV	Husnabad	04.05	08.45	04.40		Insulator failed	No
5		Cherial	Rollabanda	11KV	Husnabad	09.55	15.30	05.35		11KV Disc failed	No
6		Rebarthy	Gagillapur	11KV	Husnabad	04.35	17.10	12.35		Tree branches fallen on the line	No
7		Rebarthy	Maddur T	11KV	Husnabad	05.10	09.20	04.10		Insulator failed	No
8		Husnabad	Malapally	11KV	Husnabad	08.30	11.20	02.50		Insulator failed	No
9		Pandhilla	Pandhilla R	11KV	Husnabad	02.30	08.00	05.30		Pole damage	No
10		Potharam	Nagaram	11KV	Husnabad	04.25	05.20	00.55		Due to rain	No
11		Potharam	Potharam R	11KV	Husnabad	20.15	23.30	03.15		Due to rain	No
12		Begumpet	Laxmipur	11KV	Husnabad	04.00	10.00	06.00		Insulator failed	No
13		Ramchadrapur	Sriramulapally	11KV	Husnabad	11.00	13.55	02.55		Line problem	No
14		Ramchadrapur	Sriramulapally	11KV	Husnabad	16:25	17:30	1:05		Line problem	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR S	Nallagandla	Epispom School	11KV	Gachibowli	3:00	4:00	1:00		11KV Disc failed at Sadana School, Nallagandla Huda	No
2		Gachibowli	Gopanpally	11KV	Gachibowli	02.40	04.30	01.50		Tripped on OL due to rain	Back Feeding from 11KV Nallagandla feeder (Gachibowli Sub-Station)
3		Mathrusri Nagar	Madhava Nagar	11KV	Gachibowli	00.00	04.07	04.07		11KV Pin insulator failed at Plot no.512, 472, Madhava Nagar	No
4		Balaji Nagar	Dhanalaxmi	11KV	Kondapur	02.20	03.25	01.05		11kv Jumper cut at Kondareddy T/F due to heavy rain	No
1	RR N	Suraram	Matrix	11KV	Jeedimetla	3:25	7:35	4:10		11KV Pin insulotor failure & C T P T failure At Matrix Company Back Side	No
2		Jeedimetla-II	Uttam Biscut	11KV	Jeedimetla	02.15	03.40	01.25		Due to rain	No
3		UMCC	Sreeram Nagar	11KV	Medchal	02.15	03.30	01.15		Tree fallen on 11KV line at Community Hall,Sreeram Nagar	No
4		Kompally	Jaibheri	11KV	Medchal	05.25	06.06	00.41		Tree fallen on 11KV line at Nagarjuna Homes	No
5		Kompally	Jaibheri	11KV	Medchal	09.25	10.08	00.43		No visible fault	No
6		Kompally	NCL	11KV	Medchal	09.25	10.14	00.49		11KV Cable failed at Prajay Aparatment	No
7		Petbasheerabad	Balaji Hospital	11KV	Medchal	00.45	04.00	03.15		11KV Pin insulator failed at Andra Bank	No
8		Subhash Nagar	Jairam Nagar	11KV	Medchal	00.10	01.30	01.20		11KV Cable touched to 11KV Line at HP Petrol Bunk	No
9		HMT	Ganesh Nagar	11KV	Medchal	23.20	05.00	05.40		63KVA DTR Post of insulator failed at Sai Apartment,Padma Nagar Phase-I	No
10		Dp Pally-II	Tech Mahindra	11KV	Jeedimetla	00.00	07.10	07.10		11kv Disc failure At tech Mahindra	No
11		Kandlakoya	Kandlakoya	11KV	Medchal	03.00	07.00	04.00		Tree fallen on 11KV Line at Railway Gate,Kandlakoya	No
12		Kandlakoya	Saigeetha Ashramam	11KV	Medchal	11.00	15.00	04.00		Tree fallen on the 11KV Line at Saigeetha Ashramam	No
13		GP Pally	Malla Reddy	11KV	Medchal	00.30	04.20	03.50		Tripped on EL due to heavy wind & Rain	No
14		Devarayamjal	DMC	11KV	Medchal	08.00	10.25	02.25		11KV Disc failed at Redimix Company, Devarayamjal	No
15		Town Medchal	NGO's Colony	11KV	Medchal	03.30	05.18	01.48		Tree fallen on the 11KV line at Chilukaraju Wines,Medchal	No
16		Aliabad	Majeedpur	11KV	Medchal	5:00	6:00	1:00		11KV Pole damaged at Medchal Road,Majeedpur	No
1	RR E	Moula-Ali	Spectra	11KV	Sainikpuri	3:00	6:04	3:04		11KV Disc failed at IDA Moula Ali	No
2		Sainikpuri	Kalyan Garden	11KV	Sainikpuri	10.05	10.35	00.30		11Kv Pin insulator failed at Ragava Kalyan Garden	No
3		Yapral	Tulasi Garden	11KV	Sainikpuri	01.10	03.40	02.30		11Kv Pin insulator failed at Shaily Garden	No
4		Ramanthapur	Gokul nagar	11KV	Habsiguda	00.43	02.48	02.05		11KV Jumper cut & tree branches fallen near AB switch at Gokul nagar	No
5		Uppal	Navbharath	11KV	Habsiguda	03.00	04.40	01.40		Tree branches fallen on 11KV line at Ashok leland company	No
6		Uppal	Navbharath	11KV	Habsiguda	05.35	07.20	01.45		Tree branches fallen on 11KV line at RN Filler company	No
7		Aushapur	Bookenguda	11KV	Keesara	09.00	10.00	01.00		11KV Disc failed at Chandupatlaguda Village	No
8		Singapur	RGK	11KV	Keesara	02.00	04.30	02.30		11KV Disc failed at RGK Vikalangula Colony	No
9		Peerzathiguda	Shankar Nagar	11KV	Keesara	2:20	5:20	3:00		Line patrolling but no visible fault	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	R.P Nilayam	Naga Devatha Temple	11KV	C-VI	00.05	02.25	02.20	EL	No Visible Fault (Due to Rain)	No
2		James Street	Coramandal	11KV	V	0:10	9:30	9:20	EL	No Visible Fault (Due to Rain)	Arranged B/F on 11KV C.T.C fdr
3		Marredpally	A.O.C	11KV	C-VI	1:00	7:20	6:20	EL,OL-Yph	No Visible Fault (Due to Rain)	No
4		Vasanthapuri	Siripuri	11KV	V	1:10	3:51	2:41	EL	No Visible Fault (Due to Rain)	Arranged B/F on 11KV Lalapet fdr
5		E.S.I	I.A.S Quarters	11KV	IV	1:25	2:55	1:30	EL	I/C Cable fault	Arranged B/F on 11KV Swarna Jayanthi fdr
6		R.P Nilayam	Raithu Bazar	11KV	C-VI	1:36	4:50	3:14	EL	2No. Trees fallen on lines	No
7		Tirumalagiri	Officers Colony	11KV	C-VI	1:40	2:45	1:05	EL	Conductor snapped at Jangal Bit	No
8		I.D.P.L	Shivalayam	11KV	VI	1:43	3:00	1:17	EL,OL-Rph	No Visible Fault (Due to Rain)	No
9		Osm. University	Ladies Hostel	11KV	V	1:45	5:50	4:05	EL,OL-Bph	Tree branches fallen on lines at Cycle Stand	No
10		Macha Bollaram	Chinthai Bazar	11KV	C-VI	2:00	4:10	2:10	EL,OL	No Visible Fault (Due to Rain)	No
11		Macha Bollaram	Father Balaiah Nagar	11KV	C-VI	2:00	3:00	1:00	EL,OL	No Visible Fault (Due to Rain)	No
12		Osm. University	Keshava Nagar	11KV	V	2:05	3:43	1:38	EL,OL	No Visible Fault (Due to Rain)	No
13		Zamistanpur	Sanjeevapuram	11KV	V	2:18	3:55	1:37	EL,OL	No Visible Fault (Due to Rain)	No
14		Bhudevi Nagar	Shastry Nagar	11KV	C-VI	2:20	4:45	2:25	EL,OL	Tree fallen on lines at Army Pump House	No
15		Tirumalagiri	Srinagar Colony	11KV	C-VI	2:30	3:40	1:10	EL,OL-Rph	No Visible Fault (Due to Rain)	No
16		Road No.13	Gowri Shankar Nagar	11KV	X	2:30	3:30	1:00	EL,OL	No Visible Fault (Due to Rain)	No
17		Sanjeevaiah Park	Police Lines	11KV	C-VI	3:05	5:10	2:05	OL-R&Bph	Cable fault at Saina Bowli Hotel	Arranged B/F on 11KV Rasoolpura fdr
18		Gymkhana	Balamrai	11KV	C-VI	3:30	5:40	2:10	EL,OL-Rph	No Visible Fault (Due to Rain)	Arranged B/F on 11KV Rani Bagh fdr
19		Chilkaiguda	Water Works (Dedicated)	11KV	V	5:40	13:35	7:55	EL,OL-Rph	Insulator flash over at back side of DE Office	No
20		Road No.2	Lumbini Mall	11KV	X	6:20	7:45	1:25	EL	No Visible Fault (Due to Rain)	Arranged B/F on 11KV Kamalapuri Colony feeder
21		Road No.13	Gowri Shankar Nagar	11KV	X	6:28	7:38	1:10	EL,OL	UG Cable fault at Govt. Hospital	No
22		Chilkaiguda	Pragatools	11KV	V	8:05	13:10	5:05	EL,OL-Rph	Pin Insulator flash over of 5 Way RMU at Axis Bank	No
23		Chinthai	Caption Gas	11KV	VI	8:45	10:30	1:45	EL,OL	AB Switch sparking at Bhagath Singh Ngr	No
24		New Bowenpally	Chandana Hospital	11KV	VI	10:58	11:58	1:00	EL	No Visible Fault	No
25		Pragatools	L&T	11KV	VI	11.25	12.34	01.09	EL	HT Line snapped at Industrial Café, Gandhi Nagar	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD S	E.N.T	Gurudwara	11KV	IX	03.05	06.10	03.05	EL,OL-Rph	Cable fault at Gurudwara	No
2		Osm. Hospital	Osmangunj	11KV	IX	3:25	4:33	1:08	EL,OL-Rph	No Visible Fault (Due to Rain)	No
3		Falaknuma	Farooq Nagar	11KV	III	14:36	16:36	2:00	EL,OL	AB Cable End Kit failed at 33KV Tower, near 33KV Falaknuma SS	No
4		Gunj	Race Course	11KV	VIII	18:20	19:37	1:17	EL,OL-Rph	Cable fault	Arranged B/F on 11KV Hara Hara Kshetra feeder
1	HYD C	Industrial Area	Azamabad I.E	11KV	II	00.55	03.30	02.35	EL	Pin Insulator flash over at Sai Home	No
2		Industrial Area	Barkathpura	11KV	II	01.30	07.36	06.06	EL	2No DTR's fault	Arranged B/F on 11KV Sri Ram Nagar fdr
3		Asif Nagar	Padmanabha Nagar	11KV	VII	01.58	03.05	01.07	OL-R&Bph	Tree branches fallen on lines at Laxmi Nagar	No
4		Z.P.Office	H.P.Sabha	11KV	I	02.00	03.10	01.10	EL	No Visible Fault (Due to Rain)	No
5		Mothi Mahal	Saleh Nagar	11KV	VII	02.04	03.10	01.06	EL,OL-Yph	No Visible Fault (Due to Rain)	No
6		Golconda	Aditya Nagar OH	11KV	VII	02.15	03.30	01.15	EL	No Visible Fault (Due to Rain)	Arranged B/F on 11KV Aditya Nagar UG fdr
7		I.T.I Mallepally	Afzal Sagar	11KV	VII	02.15	04.10	01.55	EL,OL	Cable fault	Arranged B/F on 11KV Nampally Hospital fdr
8		Indira Park	Gulshan Nagar	11KV	I	02.30	03.50	01.20	EL,OL-Rph	No Visible Fault (Due to Rain)	No
9		Asif Nagar	Mehdipatnam Cable	11KV	VII	03.35	05.05	01.30	OL-R&Bph	Disc Insulator flash over at Amba Theatre	No
10		A.C.Guards	Mahaveer Hospital UG	11KV	VII	04.45	05.55	01.10	EL,OL-Yph	3Way RMU Cable fault at Singareni Bhavan	No
11		Mothi Mahal	Risala Bazar	11KV	VII	5:30	6:54	1:24	All Indication	Disc Insulator flash over at Boys Hostel	No
12		Lumbini Park	A.I.R	11KV	I	23.22	00.25	01.03	EL	Cable fault	Arranged B/F on 11KV Parisram Bhavan fdr