

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		5		5		5			
3	MDK	107	933		2		2		2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	8	0	8	0	8	0	0	
	Grand Total	1082	6468	0	12	0	12	0	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.09.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Shadnagar	Mogiligidda	11KV	Shadnagar	07.30	10.55	03.25	E/L	Jumper Cut at Paradise Road	-
1		Raghunadapalem	Nakkagudem	11KV	Huzurnagar	06.00	08.30	02.30	EL	11 KV LINE SNAPPED	-
2	NLG	Mattapally	Ramachandrapuram	11KV	Huzurnagar	10.15	11.25	01.10	EL	11 KV LINE SNAPPED	-
3		Kethepally	Korlapahad	11KV	Nalgonda	13.00	16.30	03.30	EL	11KV Jumper cut	-
4		Bairavanibanda	Thakellapahad	11KV	Nalgonda	07.00	09.45	02.45	EL	11KV Jumper cut	-
5		Eduloor	Kurumarthy	11KV	Nalgonda	05.00	08.30	03.30	EL	11KV Insulator failed	-
1		MDK	SOL	IDA-II	11KV	Patancheru	07.55	10.10	02.15		BD Due to Connductor Snapped
2	SOL		IDA-II	11KV	Patancheru	11.05	13.30	02.25		BD Due to Jumpercut	-
1	RR N	Kompally	Jaibheri	11KV	Medchal	09.01	09.47	00.46		Tree Branch fallen on the 11KV Line at Nagarjuna Homes Opposite	-
2		Jagathgirigutta	Maqdoom Nagar	11KV	Medchal	14.10	14.50	00.40		100KVA T/F Brass Patti cut and replaced at Ganga Putra, Ring Basti	-
3		Medicity	Rajabollaram	11KV	Medchal	08.00	10.15	02.15		11KV Line Cut & Replaced at Ganapur Village & Rajabollaram Village	-
1	HYD S	Attapur	Allah Masjid	11KV	Charminar	03.25	05.00	01.35	EL,OL	Cable fault	Arranged B/F on 11KV Kishanbagh OH feeder