

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	3	8	3	8	3	8			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		20		20		20			
	Total	606	3055	3	33	3	33	3	33	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		8		8		8			
3	MDK	107	933		3		3		3			
4	SDPT			1	1	1	1	1	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	12	1	12	1	12	0	0	
	Grand Total	1082	6468	4	45	4	45	4	45	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.09.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Shanigaram	Chelmeda	33KV	Husnabad	00.00	16.55	16.55		Tree branches thouched line, same rectified	Shanigaram	No
1		132KV Medchal	33KV Keshavaram	33KV	Medchal	14.12	16.21	02.09		Bird fallen on the 33KV Line at Medicity SS		-
2	RR N	132KV Medchal	33KV Medchal -I	33KV	Medchal	15.45	18.00	02.15		33KV Cable endkit failed at 33/11KV Medchal SS		-
3		132KV LGM Pet	33KV Aliabad	33KV	Medchal	13.57	15.55	01.58		33KV Pin Insulator failed at Aliabad		-

TSSPDCL - LMRC / Corporate office

Date: 30.09.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Biravunibanda	Biravunibanda	11KV	Nalgonda	07.00	08.30	01.30	EL	Bird died on line	-
2		Narketpally	Mandra	11KV	Nalgonda	11.00	13.10	02.10	EL	Jumper cut	-
3		Athmakur(S)	Dacharam	11KV	Suryapet	15.20	17.30	02.10	EL	Insulator failed	-
4		Dirincherla	Narsaigudem	11KV	Huzurnagar	08.25	11.00	02.35	EL	11 KV LINE SNAPPED	-
5		Ponugodu	Kothagudem	11KV	Huzurnagar	13.00	15.20	02.30	EL	11 KV LINE SNAPPED	-
6		Motakondur	Vartoor	11KV	Bhongir	05.00	10.00	05.00	EL	11 kv Insulator Failed	-
7		Mandollagudem	Nelapatla	11KV	Choutuppal	03.28	08.35	05.07	EL	11 kv Line Snapped	-
8		Panthangi	Panthangi	11KV	Choutuppal	06.55	09.00	02.05	EL	11kv Line snapped	-
1	MDK	Rupa	Bollaram - II	11KV	Patancheru	04.20	04.50	00.30		B/D Due to Conductor Snapped	-
2		Jinnaram	Dundigal	11KV	Patancheru	15.30	16.15	00.45		B/D Due to Jumper Cut	-
3		Hepro	Bonthapally	11KV	Patancheru	14.30	18.00	03.30		B/D Due to tree Branch fallen on the line	-
1	SDPT	Gagillapur	Gagillapur Agl	11KV	Galwel	08.05	16.28	08.23		Line snapped, same rectified	-
1	RR S	Lodha	INDU Villa	11KV	Kondapur	15.30	17.40	02.10		11kv jumper cut at Indu Villa gate and Tree branches fallen on the 11kv line RTO office lane.	-
1	RR N	KPHB	Bhagyanagar	11KV	Kukatpally	15.44	17.36	01.52		11kv line Jumper cut & Net Wire Touch the 11kv line at main Road KPHB	-
2		Jeedimetla-I	Maheshwari	11KV	Jeedimetla	16.20	17.50	01.30		11kv line Jumper cut at pipe line Road	-
3		JDM SS - 1	Sudarshan Drugs	11KV	Jeedimetla	15.40	16.40	01.00		11kv pin insulator failed at Sudarshan Drugs company	-
4		Thumkunta	Thumkunta	11KV	Medchal	15.00	16.00	01.00		Tree fallen on the 11KV Line at RTC Colony	-
5		Medicity	Rajabollaram	11KV	Medchal	14.00	17.00	03.00		11KV Line cut and replaced at Rajabollaram Village	-
6		Dppally-II	Indo fab	11KV	Jeedimetla	16.20	19.30	03.10		11kv line Disk failure at Police Station Back Side	-
7		Dppally-II	Millineum	11KV	Jeedimetla	17.55	19.20	01.25		11kv line Disk failure at BVR company	-
8		Gagillapur	Sundara Ashramam	11KV	Jeedimetla	15.00	16.00	01.00		11kv line Disk failure at Gagillapur Bus Stop	-
1	RR E	Cherlapally-II	Jannuram	11KV	Habsiguda	15.05	17.05	02.00		11Kv Insulator failed at EC Nagar (AE/LM Ram Babu) due to Heavy Rain	-
2		Nagaram	Bandlaguda	11KV	Habsiguda	14.12	15.40	01.28		Insulaotar fail at Bandlaguda stadium	-
3		Keesara	Bogaram	11KV	Habsiguda	15.08	18.30	03.22		Tree fallen on 11kv line at matrix company	-
4		Saket	JawaharNagar	11KV	Habsiguda	14.15	16.20	02.05		11KV Line Twested at Rose Garden	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	Macha Bollarum	Radhasath Sang	11KV	Bowenpally	12.25	14.39	02.14	EL,OL	HT Cable fault at Karayshan Gutta	Arranged B/F on 11KV Balaji Rice Mill fdr
2		Marredpally	Military Hospital	11KV	Bowenpally	12.58	15.35	02.37	EL	RMU fault at Military Hospital	-----
3		R.P Nilayam	Saraswathi Nagar	11KV	Bowenpally	13.10	16.00	02.50	EL	2No. Pin Insulators flash over at Saraswathi Nagar	-----
4		R.P Nilayam	Nagadevatha Temple	11KV	Bowenpally	13.15	14.30	01.15	EL	No Visible Fault (Due to Rain)	-----
5		Monda Market	Gurudwara	11KV	Sec-Bad	14.38	15.40	01.02	EL,OL-Bph	No Visible Fault (Due to Rain)	-----
6		Tirumalagiri	Chinna Kamela	11KV	Bowenpally	15.10	17.20	02.10	EL	Tree branches fallen on lines at BSNL Office	-----
7		Road No.22	Obul Reddy	11KV	Banjarahills	15.14	17.00	01.46	EL,OL,	Tree branches fallen on lines at Road No.25	-----
8		Jubilee Hills	Film Nagar	11KV	Banjarahills	15.15	16.30	01.15	All Indication	No Visible Fault (Due to Rain)	-----
9		Road No.22	Jubilee Hills PS	11KV	Banjarahills	15.15	16.40	01.25	EL	Tree branches fallen on lines at Road No.17	-----
10		Prashasan Nagar	Nandagiri Hills	11KV	Banjarahills	15.15	16.22	01.07	EL,OL-Rph	No Visible Fault (Due to Rain)	-----
11		Prashasan Nagar	Nyaya Vihar	11KV	Banjarahills	15.16	17.58	02.42	EL,OL-Yph	Jumper cut & tree branches fallen on lines at Wishper Vally	-----
12		Kalyan Nagar	Rahamath Nagar	11KV	Banjarahills	15.18	21.07	05.49	All Indication	I/C Rph Jumper & O/G Rph Jumper cut at SS & Tree branches at Various locations	At 20:35Hrs partial loads added on 11KV Savera fdr & remaining loads added on 11KV Krishna Nagar feeder
13		Hakimpet	Risala Bazar	11KV	Bowenpally	15.20	16.29	01.09	EL	No Visible Fault (Due to Rain)	-----
14		Road No.22	UCO Bank	11KV	Banjarahills	15.28	20.30	05.02	EL,OL	Tree branches fallen on lines at Road No.20 & 22	-----
15		Road No.22	Road No.5	11KV	Banjarahills	15.28	16.50	01.22	EL,OL	Tree branches fallen on lines at Road No.10	-----
16		Prashasan Nagar	Arogya Sree	11KV	Banjarahills	15.44	21.40	05.56	OL-R&Bph	Tree branches fallen on lines at Various locations	-----
17		Kalyan Nagar	Vengalrao Nagar	11KV	Banjarahills	15.56	18.12	02.16	All Indication	Pin Insulator flash over at Directors Quarters	-----
18		Kalyan Nagar	Laxmi Nagar	11KV	Banjarahills	15.57	17.40	01.43	All Indication	Tree branches fallen on lines at Pochamma Temple	-----
19		Ravindra Society	Benz Showroom	11KV	Banjarahills	17.05	19.25	02.20	EL	Tree branches fallen on lines at Plot No.171	-----
1	HYD S	Hussain Sagar	Lakdikapool	11KV	Saifabad	14.30	18.32	04.02	EL	5Way RMU fault at Govt. Printing Press	-