

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT			1	1	1	1	1	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	3	2	3	2	3	0	0	
	Grand Total	1082	6468	2	6	2	6	2	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.04.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Kodir	33kv	Wanaparthi	13.57	16.50	02.53		Cable Problem	Kodir	-
1	SDPT	Gajwel	B V pur	33kv	Gajwel	08.10	15.10	07.00		B/D due to vehicle dashed 33kv pole	B V pur	-

## TSSPDCL - LMRC / Corporate office

Date: 02.04.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Mothkur	Mothkur Town	11kv	Bhongiri	03.10	03.40	00.30	EL/OL	11kv Insulator Failed near Mothkur Town	-
2		Mothkur	Mothkur Rural	11kv	Bhongiri	08.40	11.20	02.40	EL/OL	11kv Line Snapped & 11kv Insulator Filaed near Mothkur Rural Village	-
1	SDPT	Akkannapet	Pakilnayak Thanda	11kv	Husnabad	00.00	09.00	09.00		11KV line snapped	-
1	RR S	ESCI	Nanakramguda	11kv	Gachibowli	10.56	12.12	01.16		UG Cable Damaged at Divya Sree, SNL	-
1	RR E	CRPF	CRPF Residential	11kv	Keesara	10.45	13.45	03.00		11KV 3Nos HG Fuse failed at CRPF Yard	-
1	HYD N	Chilkaiguda	Parsigutta	11kv	Secunderabad	06.30	08.25	01.55	EL	Tree branches fallen on lines at Grave Yard	