

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1		1		1				
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>3</b>	<b>1</b>	<b>3</b>	<b>1</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4		3		3				1no 33KV fdr Still
2	NLG	144	988									
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>4</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>5</b>	<b>3</b>	<b>4</b>	<b>3</b>	<b>4</b>	<b>3</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 08.04.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	132 KV SS Kothur	SANGEM	33KV	Shadnagar	18.40	20.45	02.05	E/L & O/L	Due to Heavy Gale & Wind Rain AB Switch open at Enmulnarva		No
2		132 KV SS Kothur	SANGEM	33KV	Shadnagar	21.20	21.50	00.30	E/L & O/L	under Breakdown		Alternate arranged from 132KV Alwal - 33KV Eppalapally at 21.50 hrs
3		132 KV SS Kothur	Binju Sariya	33KV	Shadnagar	18.45		05.15	E/L & O/L	Conductor snapped at 132KV Kothur SS & Breaker problem ( Not Rectified)		No
4		132 KV SS Kothur	Thimmapur	33KV	Shadnagar	18.40	23.40	05.00	E/L & O/L	for Tree fallen on the line near Kistappa garden near By pass road kothur		No
1	HYD S	220KV Ch' Gutta	Kandikalgate	ST	Malakpet	17.22	17.38	00.16	EL,OL-Rph	under Breakdown		Loads transferred onto 220KV Ch' Gutta - C.R.P.F line

## TSSPDCL - LMRC / Corporate office

Date: 08.04.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR S	IJM	New 6th Phase	11KV	Gachibowli	00.19	01.19	01.00		Tree branches fallen on the 11kv line at HIG-272, New 6th phase	-
2		IIIT	IVRCL	11KV	Gachibowli	12.20	13.25	01.05		11kv Endy kit failed in Sub-Station and Cable damaged at IVRCL back side	-
1	RR N	Medicity	IDA Medicity	11KV	Medchal	05.30	06.10	00.40		Tree Fallen on 11KV Line at Medicity X Road	-