

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1	2	1	2	1	2			
	Total	606	3055	1	6	1	6	1	6	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		10		10		10			
3	MDK	107	933	1		1		1				
4	SDPT			1	9	1	9	1	9			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	19	2	19	2	19	0	0	
	Grand Total	1082	6468	3	25	3	25	3	25	0	0	

TSSPDCL - LMRC / Corporate office

Date: 10.04.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Sadasivapet	Koheer	33kv	Sangareddy	12.15	15.35	03.20		B/D Due to Pin Insulator failure	Koheer	-
1	SDPT	Angadikistapur	Jagadevpur	33kv	GAJWEL	00.00	06.34	06.34		B/D due to poles Damagaed	Jagadevpur	-
2	HYD N	132KV I.D.P.L	Prashanath Nagar	33kv	Bowenpally	06.50	07.02	00.12	EL,OL-Bph	B/D Due to tripped on EL	Prashanath Nagar	Loads transferred onto 220KV Shapur Nagar SS via 33KV IDPL fdr

TSSPDCL - LMRC / Corporate office

Date: 10.04.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pamanagundla	Pittampally	11kv	Nalgonda	07.17	12.13	04.56	EL	11KV Jumper Cut	-
2		Kamareddygudem	Brundavanapuram	11kv	Miryalaguda	13.18	14.16	00.58	EL	Tree Branches Fallen	-
3		Urlugonda	Sarvaram	11kv	Huzurnagar	05.30	07.35	02.05	EL	11 KV Line Snapped	-
4		IDA	Bommaipally	11kv	Bhongiri	11.40	16.05	04.25	OL	11 kv Top Insulator failed at Elezabeth school Opposite Near Bhongir town	-
5		Anantharam	Hanmapuram	11kv	Bhongiri	04.00	12.30	08.30	OL	11 kv Insulator failed at SS-1 , 11 KV Disc failed at Ravinder well , tree branchess fallen at line at SS=2 & Tree fallen at Karnal well near hanmapur village	-
6		Nandanam	Nagireddypally	11kv	Bhongiri	05.00	11.00	06.00	EL	2 NO's 11 KV Insulators Failed & Phase to Phase Near Yerrambelli Village.	-
7		Rajapeta	Rajapeta Agl	11kv	Bhongiri	05.15	10.30	05.15	EL	2 NO's 11 KV Disc Failed Near Rajapeta village	-
8		Pamukunta	Singaram	11kv	Bhongiri	08.00	12.20	04.20	EL	11 kv Disc Failed Near Singaram Village.	-
9		Peddapadishala	Bandakothapally	11kv	Bhongiri	01.40	11.00	09.20	EL	2 No's 11 kv Disc Failed Near Bandakothapally Village	-
10		Tekulasomaram	Pahilwanpuram	11kv	Choutuppal	06.30	12.45	06.15	EL	11 KV Disc Failed at Gadi Bavi Near Pahilwanpuram Village.	-
1	SDPT	Gurjakunta	Gurjakunta Agl	11kv	Husnabad	00.00	16.20	16.20		3-PH Break Down	-
2		Gurjakunta	Vecharani	11kv	Husnabad	00.00	18.20	18.20		Insulator Failed	-
3		Nagapuri	Gandikunta	11kv	Husnabad	08.00	09.45	01.45		11 KV LINE CUT	-
4		Chityala	Thadoor	11kv	Husnabad	07.10	08.45	01.35		Tree cutting	-
5		Chityala	Thadoor	11kv	Husnabad	09.45	14.00	04.15		LC&Break Down	-
6		Gagillapur	Vallampatla	11kv	Husnabad	07.40	08.06	00.26		3-PH Break Down,1-PH OK	-
7		Guruvannapet	Guruvannapet	11kv	Husnabad	00.00	08.05	08.05		3-PH Break Down,1-PH OK	-
8		Guruvannapet	Posanpally	11kv	Husnabad	00.00	10.47	10.47		Insulator Failed	-
9		Guruvannapet	Posanpally	11kv	Husnabad	12.05	13.20	01.15		Line cut	-
1	RR S	Lanco Hills	Khajaguda	11kv	Gachibowli	16.46	19.26	02.40	BD	11kv Cable end-kt failed at Subs-Station backside	-
1	RR N	GP Pally	Apparel Park	11kv	Medchal	11.40	12.15	00.35	BD	Tree fallen on the 11KV Line at Apparel park	-
2		Shameerpet	Devarayamjal	11kv	Medchal	11.30	12.15	00.45	BD	Tree fallen on the 11KV Line at ORR Smeerpet	-
1	RR E	Singapur	Annojiguda	11kv	Keesara	16.10	17.30	01.20		11KV line cut at LIG Colony A-1 Block	-
1	HYD N	Seethaphal Mandi	Namala Gundu	11kv	V	08.00	09.20	01.20	EL,OL-Rph	Cable End Kit failed at Namala Temple	Arranged B/F on 11KV Warasiguda fdr

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
2	HYD S	Kanchan Bagh	Kanchan Bagh	11kv	VIII	12.27	13.36	01.09	OL-R&Bph	Conductor snapped at Pisal Banda	----