

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	2	7	2	7	0	0	
	Grand Total	1082	6468	2	8	2	8	2	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.04.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Peddmandadi	33KV	Wanaparthi	07.13	11.30	04.17	E/L&O/L	Y B Phase Conductor snapped at 132KV SS WNP	Peddmandadi	Alternate supply Arranged from 132KV Thirumalaipally to 33KV Veltoor at 11:30Hrs.
1	SDP	Habsipur	Khajipur	33KV	Siddipet	12.25	13.40	01.25		BD (Jumper Cut)	Khajipur	-

TSSPDCL - LMRC / Corporate office

Date: 12.04.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Veljal	11KV	Jadcherla	10.35	12.35	02.00		11KV Jumper cut near Veljal	-
1	NLG	Reddygudem	Reddygudem	11KV	Suryapeta	05.30	07.20	01.50	E/L	Conductor Snapped	-
2		Palakeedu	Bothalapalem	11KV	Huzurnagar	08.10	10.00	01.50	EL	11 KV LINE SNAPPED	-
3		Bondugula	Bondugula	11KV	Bhongiri	06.00	12.10	06.10	EL/OL	63 KVA DTR Failed at SS- 17 Kurraram road Bondugula village.	-
1	SDP	MARKOOK	MARKOOK SS	11KV	Gajwel	06.35	09.10	02.35		11KV LINE CUT	-
2		WARDARAJPUR SS	DHARMARAM FEEDER	11KV	Gajwel	09.20	09.30	00.10		COPPERPATTI CUT	-
3		LINGAPUR SS	VENKATRAOPET FEEDER	11KV	Gajwel	16.40	18.45	02.05		TOUCHED TO THE TIPPER TRACK 11KV LINE	-
1	HYD N	Kalyan Nagar	Krishna Nagar	11KV	X	06.03	07.50	01.47	EL,OL-Rph	No Visible Fault	Arranged B/F on 11KV Police Lines feeder