

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		11		11		11			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		10		10		10			
	Total	606	3055	0	22	0	22	0	22	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4		4		4				
2	NLG	144	988		3		3		3			
3	MDK	107	933	4	4	4	4	4	4			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	8	7	8	7	8	7	0	0	
	Grand Total	1082	6468	8	29	8	29	8	29	0	0	

TSSPDCL - LMRC / Corporate office

Date: 20.04.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Kankurthy	33KV	Narayanapet	17.20	17.40	00.20	EL	insulator failed	Kankurthy	Alternate Supply Arranged from 33KV Mogalmdaka SS
2		Kodangal	Kothur	33KV	Vikarabad	16.50	19.20	02.30	EL	Disc failed near Kothur Town	Kothur	-
3		Kodangal	Hamsanpally	33KV	Vikarabad	20.30	22.30	02.00		Breaker internal proble	Hamsanpally	Alternate supply arranged from 33KV Peddanadigama feeder
4		Shadnagar	Mogilgidda	33KV	Shadnagar	17.22	20.50	03.28	EL	Disc replaced	Mogilgidda	Alternate Supply Arranged from 132KV Srirangapur
1	MDK	Jogipet	Dakur	33KV	Jogipet	17.30	18.25	00.55		BD Due to Jumper cut	Dakur	-
2		Singoor	Muddaipet	33KV	Jogipet	17.20	18.20	01.00		BD Due to insulator Fail	Muddaipet	-
3		Borpatla	Covalent	33KV	Jogipet	16.23	18.48	02.25		BD Due to Heavy wind	Covalent	-
4		Bollaram	Shathavahana	33KV	Patancheru	17.25	23.30	06.05		BD Due to conductor snapped	Shathavahana	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thungathurthy	Ganugubanda	11KV	Suryapet	12.10	14.45	02.35	EL	Jumper cut	-
2		Mellacheruvu	Y Madaram	11KV	Huzurnagar	06.20	08.00	01.40	EL	11 KV LINE SNAPPED	-
3		Pamanagundla	Yerrasanigudem	11KV	Nalgonda	08.10	09.30	01.20	EL	11KV Line Junper Cut	-
1	MDK	Cheryal	Dulchand	11KV	Sangareddy	18.05	21.00	02.55		BD due to Tree branches fallen on line	-
2		Pati	Shalimar	11KV	Patancheru	16.35	21.05	04.30		BD Due to Pin Insulotor Fail	-
3		Patancheru Town	Town	11KV	Patancheru	18.30	20.30	02.00		BD Due to Jumper connection Work	-
4		Gummadidala	Agrobell	11KV	Patancheru	17.05	20.15	03.10		BD Due to tree branches fallen on line	-
1	RR N	Dulapally	IDA-II	11KV	Medchal	17.20	18.33	01.13		11KV Jumper cut and replaced Mid Cap Industry	-
2		Subhash Nagar	Bank Colony	11KV	Medchal	17.38	18.39	01.01		Tree Fallen on the 11KV Line at SR Digi School	-
3		Jagathgirutta	IDA	11KV	Medchal	17.35	19.05	01.30		11KV Cable Endkit Failed at Hari Storeroom,Jagathgirutta	-
4		GP Pally	APIIC	11KV	Medchal	17.50	19.30	01.40		Tree Fallen on 11KV Line at Apparel Park	-
5		R G K Suraram	Suraram Village	11KV	Jeedimetla	17.10	18.10	01.00		Due To Rain	-
6		R G K Suraram	R G K -I	11KV	Jeedimetla	17.10	18.10	01.00		Due To Rain	-
7		R G K Suraram	R G K -II	11KV	Jeedimetla	17.10	18.10	01.00		Due To Rain	-
8		Dp Pally-II	Indain Oil	11KV	Jeedimetla	17.04	18.28	01.24		Due To Rain	-
9		Dp Pally-II	Cable M L R	11KV	Jeedimetla	17.10	18.30	01.20		Due To Rain	-
10		Dp Pally-II	Indo FEB	11KV	Jeedimetla	17.12	19.15	02.03		11kv Jumper Cut At 120 Basti Colony	-
11		Dp Pally-II	Indo FEB	11KV	Jeedimetla	19.20	20.30	01.10		Tree Fallen On The 11kv Line At Wall Company Madchal	-
1	RR E	Chakripuram	Shilpa nagar	11KV	Keesara	06.40	08.30	01.50		Thonda fallen on 160KV T/F at Madila narayana colony	-
1	HYD N	Pragatools	R.R.Nagar	11KV	VI	17.22	18.33	01.11	EL,OL-Rph	No Visible Fault (Due to heavy Gale)	-
2		Pragatools	L&T	11KV	VI	17.25	18.48	01.23	EL,OL-Rph	No Visible Fault (Due to heavy Gale)	-
3		New Bowenpally	Police Quarters	11KV	VI	17.27	18.45	01.18	EL,OL	Snapped Line at Kalyan Nagar Nala	-
4		Prashanth Nagar	Shakthipuram	11KV	VI	17.30	18.55	01.25	EL	Tree branches fallen on lines at Rajiv Gandhi Nagar	-
5		Pragatools	Asbestos Colony	11KV	VI	17.37	20.56	03.19	EL	Jumper cut at 1st Line AB Switch, Cable fault & Tree branches on lines at Sanjay Gandhi Nagar	-
6		H.M.T.	Chinthal	11KV	VI	17.45	19.50	02.05	EL	Tree branches fallen on lines at MCH Office	-
7		H.M.T.	A.O.L.	11KV	VI	17.58	19.25	01.27	EL	No Visible Fault (Due to heavy Gale)	-
1	HYD C	Industrial Area	D.D.H	11Kv	II	08.10	09.30	01.20	EL,OL-Rph	Bird fault on lines at Hindi Mahava Vidyalaya	Arranged B/F on 11KV Shivam feeder
2		Asif Nagar	Toli Chowki	11Kv	VII	17.58	19.05	01.07	EL	Foreign material fallen on lines at Toli Chowki	-----
3		Karwan	Langer House Cable	11Kv	VII	19.00	20.45	01.45	EL,OL-Rph	End Kit failed at Rangvan Tower	At 19:54Hrs Partial loads added on 11KV Prashanth Nagar fdr & remaining loads charged at SS