

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		9		9		9			
3	MDK	107	933									
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	15	0	15	0	15	0	0	
	Grand Total	1082	6468	0	18	0	18	0	18	0	0	



## TSSPDCL - LMRC / Corporate office

Date: 27.04.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Akupamula	Singaram	11KV	Huzurnagar	13.45	15.10	01.25	EL	11 KV DISK FAILED	-
2		Anantharam	Hanmapuram	11KV	Bhongir	09.00	09.20	00.20	EL/OL	11kv Line Snapped near Husnabad vaillge	-
3		Narayanapur	Kothagudem	11KV	Choutuppal	00.00	09.00	09.00	EL/OL	Solid core Insulator failed at SS- 6 near Kothagudem village	-
4		Aragaddagudem	N.R.Gudem	11KV	Nalgonda	06.00	11.00	05.00	EL/OL	11 KV Jumper Cut (Due to heavy Rain)	-
5		Pamanagundla	Yerrasanigudem	11KV	Nalgonda	00.25	10.00	09.35	EL/OL	11 KV Insulator Failed (Due to heavy Rain)	-
6		Palem	Palem	11KV	Nalgonda	06.00	08.30	02.30	EL/OL	11 KV Jumper Cut (Due to heavy Rain)	-
7		Palem	Ogodu	11KV	Nalgonda	06.00	09.05	03.05	EL/OL	11Tree Fallen on the 11 KV Line (Due to heavy Rain)	-
8		Palem	Bopparam	11KV	Nalgonda	06.00	09.00	03.00	EL/OL	11 KV Jumper Cut (Due to heavy Rain)	-
9		Reddygudem	Kothagudem	11KV	Suryapeta	06.00	09.35	03.35	EL	Insulator failed	-
1	SDP	Nangnoor	Nangnoor	11KV	Siddipet	05.25	09.00	03.35		LC-B/D-Tree branches fallen on the line, LC book completed	-
2		Irkode	Irkode	11KV	Siddipet	13.15	17.45	04.30		LC -B/D - DTR fault, LC No. 15151	-
3		MARKOOK	BHAVANDHAPUR LC No. 25207	11KV	Gajwel	09.00	13.53	04.53		Pole was broken the work has done	-
4		MEDHINIPUR	MATHPALLY LC No. 127	11KV	Gajwel	14.20	17.50	03.30		Disc falt	-
5		Guruvannapet	Posanpally	11KV	Husnabad	06.45	07.35	00.50		HT/LT Falling	-
6		Rebarthy	Ladnoor	11KV	Husnabad	17.05	23.00	05.55		Pole was broken the work has done	-
1	RR N	Madeenaguda	Reddy Lab	11KV	Kukatpally	15.35	19.10	03.35	BD	11KV AB Cable failure near Vishitha Aptt	-
1	RR E	Peerzathiguda	RTC	11KV	Habsiguda	Keesara	07.50	08.38		Tree branches fallen on 11kv line at New Sai Nagar Colony	-
1	HYD C	Zamistanpur	Dayara Market	11KV	II	20.26	21.44	01.18	EL,OL-Bph	AB Cable fault at Bhandan Funtion Hall	Partial feeder charged & Remaining fdr arranged B/F on 11KV RTC X-Roads feeder