

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	1	5	1	5	1	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		5		5		5			
3	MDK	107	933		2		2		2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	9	0	9	0	9	0	0	
	Grand Total	1082	6468	1	14	1	14	1	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.08.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	RR E	132KV Medchal	33KV Keshavaram	33KV	Medchal	17.30	20.26	02.56	EL	33KV Pin Insulator failed at ORR Kandlakoya	33KV Keshavaram	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 02.08.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Balanagar	Balanagar	11KV	Jadcherla	02.24	06.45	04.21		11KV Jumper cut Near Town	-
2		Karkonda	Fathepur	11KV	Jadcherla	10.25	11.55	01.30		11KV Disc Failed Near Fathepur	-
1	NLG	Mukundapuram	Mamilla Madava	11KV	Suryapet	09.35	12.00	02.25	EL	Insulator failed	-
2		Munagala	Kokkireni	11KV	Huzurnagar	06.10	08.30	02.20	EL	Insulator failed	-
3		Thimmanagudem	RWS	11KV	Nalgonda	05.00	10.24	05.24	EL	11KV jumper cut	-
4		Kopple	Bheemaram	11KV	Nalgonda	08.45	09.41	00.56	EL	AB Switch Fault at Bheemaram Rice Mill	-
5		Narayanapur	Kothagudem	11KV	Choutuppal	06.15	09.30	03.15	EL/OL	11 KV Insulator failed near Kothagudem village	-
1	MDK	Bollaram - I	Soubagya	11KV	Patancheru	18.24	19.24	01.00		BD due to Jumper cut	-
2		Gundla Machnoor	Industrial	11KV	Patancheru	14.40	17.30	02.50		BD due to Conductor snapped	-
1	RR E	Uppal	RTA	11KV	Habsiguda	01.50	02.50	01.00		Tree branches fallen on 11KV line & 11KV Line cut at Survey Colony	-
1	HYD N	Macha Bollaram	Ayyappa Nagar	11KV	C-VI	02.07	03.38	01.31	EL	Disc Insulator flash over at Sneha Colony (1No. DTR Kept Off)	-
2		Pragatools	Asbestos Colony	11KV	VI	09.42	11.23	01.41	OL	Tree branches fallen on lines at Asbestos Colony	-
1	HYD C	Golconda	Narayanamma College	11KV	VII	06.55	09.40	02.45	EL,OL-Yph	Pin Insulator flash over at Madhura Hills (1No. DTR Kept Off)	-
2		Langer House	Prashanth Nagar	11KV	VII	07.05	08.49	01.44	EL,OL-Yph	Cable fault	Arranged B/F on 11KV Pensionpura fdr