

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		4		4		4			
3	MDK	107	933	2	2	2	2	2	2			
4	SDPT			1	6	1	6	1	6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	12	3	12	3	12	0	0	
	Grand Total	1082	6468	3	14	3	14	3	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 03.08.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Bollaram	Meenakshi	33KV	Patancheru	14.05	17.00	02.55		B/D Due to Conductor Snapped		-
2		Zaheerabad	Mannapur	33KV	Zaheerabad	07.55	08.40	00.45		B/D Due to tree Branch fallen on the line		-
1	SDPT	Thunkibollaram	Markook	33KV	Gajwel	22.07	23.10	01.03		BD (Due to rain)		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 03.08.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Bugathanda	Bugathanda	11KV	Devarakonda	13.10	13.50	00.40	E/L	11KV jumper cutt	-
2		Ravulapally	Thurpugudem	11KV	Suryapet	06.30	10.00	03.30	E/L	Insulator failed	-
3		Kondamadugu	Kondamadugu	11KV	Bhongir	08.40	10.40	02.00	E/L	11kv Line Snapped	-
4		NG.Bandal	Veerareddypally	11KV	Bhongir	05.30	10.00	04.30	E/L	11kv Insulator Failed	-
1	MDK	Patancheru Town	MIA-II	11KV	Patancheru	11.35	12.40	01.05		B/D Due to Conductor Snapped	-
2		Patancheru Town	Shanthinagar	11KV	Patancheru	08.30	10.30	02.00		B/D Due to Jumper Cut	-
1	SDPT	Komuravelli	Komuravelly 7 Hrs.	11KV	Husnabad	00.10	05.50	05.40		Line cut	-
2		Komuravelli	Posanpally	11KV	Husnabad	00.05	07.26	07.21		Line cut	-
3		Komuravelli	Inapur Agl	11KV	Husnabad	00.17	05.50	05.32		3-Ph Break Down Due to Heavy rain	-
4		Komuravelli	Kistampeta	11KV	Husnabad	00.15	15.15	15.00		Break Down Due to Heavy rain	-
5		Komuravelli	Kadaverugu	11KV	Husnabad	00.07	05.50	05.43		Disc Failed	-
6		Guruvannapet	Thapasally	11KV	Husnabad	11.00	16.20	05.20		Disc Failed	-
1	RR N	Kandlakoya	KV Reddy Nagar	11KV	Medchal	15.55	16.37	00.42		Tree fallen on 11KV Line at Prestige park	-
1	RR E	Keesara	Cheryala	11KV	Keesara	13.45	16.25	02.40		Insulaotr fail at Kundanpalli	-