

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988		8		8		8			
3	MDK	107	933	2		2		2				
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	13	3	13	3	13	0	0	
	Grand Total	1082	6468	4	17	4	17	4	17	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.08.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Polepally	Kondeed	33KV	Jadcherla	01.25	01.30	00.05	E/L	Due to LA Blast	Kondeed	Alternate supply Arranged form 33KV Jadcherla
1	MDK	Zaheerabad	Old Allana	33KV	Zaheerabad	17:55	19:25	1:30		Conductor snapped	Old Allana	No
2		Sadasivpet	Kondapur	33KV	Sangareddy	11.10	12.15	01.05		Jumper cut	Kondapur	No
1	RR N	132KV Medchal	Aliabad	33KV	Medchal	4:05	6:57	2:52	EL	Peacock fallen on the 33KV Line at Attala Company	Aliabad	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Sampally	11KV	Narayanapet	16.10	16.35	00.25		LT line spanned and cut due to gale and wind	No
2		Kosgi	Hanmanpally	11KV	Narayanapet	18.15	19.30	01.15		Tree fallen branch down to LT line	No
3		Salkarpet SS	Pagdiyal	11KV	Narayanapet	15.38	17.30	01.52		Tree branch fallen down to LT line	No
1	NLG	Kethepally SS	Gudivada	11KV	Nalgonda	7:18	8:30	1:12	EL	Tree branches fallen on the line	No
2		Akaram	Vaddipamula	11KV	Nalgonda	12.40	13.45	01.05	EL	Insulator failed	No
3		Thimmapuram	Kallepally	11KV	Miryalaguda	10.10	12.26	02.16	EL	Insulator failed	No
4		Ravulapally	Kukkadam	11KV	Suryapet	02.40	06.45	04.05	EL	Insulator flashover	No
5		Jalapuram	Jalapuram	11KV	Suryapet	02.40	07.35	04.55	EL	Conductor snapped	No
6		Alingapuram	Raghavapuram	11KV	Huzurnagar	12.40	14.30	01.50	EL	11 KV LINE SNAPPED	No
7		Addagudur	Kotamarthy	11KV	Bhongir	05.00	09.00	04.00	EL	11kv Insulator Failed	No
8		Ishkilla	Kakkireni	11KV	Choutuppal	2:20	7:45	5:25	EL	11 kv Line snapped	No
1	SDPT	Ramakkapet	Ramakkapet	11KV	Siddipet	7:00	12:08	5:08		Tree branches fallen on the wire	No
2		Singataam	Dacharam	11KV	Gajwel	19.20	21.10	01.50		1 Phase DTR failed	No
1	RR S	Balajinagar	Dhanalaxmi	11KV	Kondapur	16:40	17:44	1:04		Flexi fallen on the 11kv line near MIG - 190 at Mana Eye hospital.	No
1	HYD N	Prashasan Nagar	Journalist Colony	11KV	X	02.55	04.50	01.55	EL	No Visible Fault	Arranged B/F on 11KV Apollo fdr
2		Pragatools	Indo Swing	11KV	VI	19:33	20:44	1:11	EL	Cable fault	Arranged B/F on 11KV Giri Nagar fdr
1	HYD C	Z.P.Office	Hindi Prachara Sabha	11KV	I	11.40	12.52	01.12	EL,OL	Cable fault	Arranged B/F on 11KV Mahaveer OH feeder