

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		3		3				
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933		1		1		1			
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	12	4	12	4	12	0	0	
	Grand Total	1082	6468	4	16	4	16	4	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.08.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Buddaram	33KV	Wanaparthy	08.10	13.03	04.53	E/L&O/L	B Phase Pad clamp Tightening From line Isolator to line	Buddaram	-
2		Wanaparthy	Gopalpet	33KV	Wanaparthy	06.28	10.00	03.32	O/L	Due to Breaker Problem	Gopalpet	Alternate supply arranged from 132KV Nagarkurnool to 33KV Bijinepally at 10:00Hrs.
3		leeza	T.T Doddy	33KV	Gadwal	13.28	16.02	02.34	E/L	33KV Line Jumper Cut at Uttanoor SS	T.T Doddy	-
1	NLG	Dirsincherla	Mukundapuram	33KV	Huzurnagar	11.30	14.10	02.40	EL/OL	33 KV LINE SNAPPED		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 08.08.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Palem	Ogodu	11KV	Nalgonda	13.25	14.50	01.25	E/L	11KV jumper cut	-
2		Aitipamula	GD Gudem	11KV	Nalgonda	04.12	10.31	06.19	E/L	Tree branches fallen on line	-
3		Bugathanda	Bugathanda	11KV	Devarakonda	10.25	11.10	00.45	E/L	11Kv Insulator failed	-
4		Putamgandi	Chinthal Thanda	11KV	Devarakonda	13.25	13.55	00.30	E/L	11Kv jumper cut	-
5		Bopparam	M.K Kothagudem	11KV	Suryapet	09.50	11.45	01.55	E/L	Tree branch fallen on the line	-
6		Keethavarigudem	K K Thanda	11KV	Huzurnagar	06.20	08.30	02.10	EL	11 KV LINE SNAPPED	-
1	MDK	Patancheru Town	MIA-II	11KV	Patancheru	14.55	16.20	01.25		B/D due to Tree branches fallen on the line	-
1	SDP	Raghvapur	Peddalingareddypally	11KV	Siddipet	18.00	07.15	13.15		B/D for 25KV DTR failure	-
2		Ensanpally	Ensanpally	11KV	Siddipet	07.25	08.55	01.30		B/D OL/EL Tripping	-
3		Kondapur	Kondapur	11KV	Siddipet	14.30	17.30	03.00		B/D for HT/LT line phase to phase LC No.17125	-
4		Bekkal	Bairanpally	11KV	Husnabad	13.30	16.30	03.00		BD for HT/LT	-
5		Gagillapur	Narsaipally	11KV	Husnabad	12.51	13.37	00.46		conductor snapped	-
1	HYD N	Tirumalagiri	Officers Colony	11KV	C-VI	16.40	19.32	02.52	EL	No Visible Fault	17:20 hrs partial feeder charged, 18:29 hrs Partial loads added on 11KV Nagadevtha fdr & Remaining loads added on 11KV R.K Puram feeder
1	HYD C	Golconda	Narayanamma College	11KV	VII	11.50	13.00	01.10	EL,OL-Yph	Cable fault at Vaternary Colony	-----
2		S.D Hospital	Khadi Bandar	11KV	VII	14.22	15.37	01.15	EL,OL-Bph	Tree branches on lines at Wall PT	-----
3		Mothi Mahal	M.D.Lines	11KV	VII	20.02	22.20	02.18	EL,OL-Rph	Cable Fault	Arranged B/F on 11KV Jyothi Nagar fdr