

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	6	1	6	1	6			
7	RR(E)	168	403		5		5		5			
8	Hyd	194	1044		7		7		7			
	Total	606	3055	1	19	1	19	1	19	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988		13		13		13			
3	MDK	107	933	1	4	1	4	1	4			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	20	2	20	2	20	0	0	
	Grand Total	1082	6468	3	39	3	39	3	39	0	0	

TSSPDCL - LMRC / Corporate office

Date: 19.08.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kothur	Ennar Steel	33KV	Shadnagar	21.35	22.40	01.05	EL	No Visible fault due to Rain	Ennar Steel	No
1	SDPT	Mustyala	Komuravelly	33KV	Husnabad	15:15	15:50	0:35		Due to heavy rain	Komuravelly	Alternative supply arranged from 132KV Duddeda SS
1	RR N	132KV Medchal	Devarayamjal	33KV	Medchal	8:34	10:18	1:44	EL/OL	No Visible fault		No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Parpally	Malkapur	11KV	Mahabubnagar	07.10	10.05	02.55		11KV Tree fallen on conductor at Malkapur	No
2		Pallerla	Nandipad	11KV	Narayanapet	00.00	10.00	10.00		3Nos.11KV Disc failed	No
3		Mohammadabad	Shaikpally	11KV	Narayanapet	02.10	04.15	02.05		Breakdown due to heavy gale and wind	No
1	NLG	Eduloor	Munukuntla	11KV	Nalgonda	23:20	2:20	3:00	EL	Tree Fallen on the Line	No
2		Kattangur	Bollepally	11KV	Nalgonda	03.50	04.53	01.03	EL	Tree Fallen on the Line	No
3		Pittalagudem	Venkatapuram	11KV	Devarakonda	12.10	13.35	01.25	EL	11 Insulator Failed	No
4		Penpahad	Dubba thanda	11KV	Suryapet	06.55	09.35	02.40	E/L	Insulator failed	No
5		Durajpally	Town feeder	11KV	Suryapet	14.40	16.20	01.40	E/L	Insulator failed	No
6		Gaddipally	Ponugodu	11KV	Huzurnagar	05.00	07.00	02.00	E/L	11KV Line Snapped	No
7		Keethavarigudem	Velidanda	11KV	Huzurnagar	04.25	06.30	02.05	E/L	11KV Line Snapped	No
8		Venkatapuram	Venkatapuram	11KV	Bhongir	04.00	11.35	07.35	EL/OL	11kv Disc Failed near Venkatapuram Village	No
9		Venkiryala	Padamatisomaram	11KV	Bhongir	06.45	08.15	01.30	EL/OL	16 kva DTR Failed at Hanuman temple Pallegudem village	No
10		Alair	Ch.Kandukur	11KV	Bhongir	12.35	14.50	02.15	EL/OL	11kv Insulator Failed near Ramasamudram Village	No
11		Golankonda	Golankonda	11KV	Bhongir	08.45	11.30	02.45	EL/OL	11 kv post-off Insulator failed Karbar well.golankonda village.	No
12		Yennaram	Kunkudupamula	11KV	Choutuppal	10.35	13.40	03.05	EL/OL	11kv Line sanpped near Kunkudupamula Village	No
13		Choutuppal IPDS	Dhamera Agl	11KV	Choutuppal	14.46	16.16	01.30	EL/OL	11kv Line Snapped near Dhamera Village	No
1	MDK	Bollaram - I	Arobindo	11KV	Patancheru	6:10	8:50	2:40		B/D Due to Jumper Cut	No
2		Bollaram - II	Vasavidatta	11KV	Patancheru	03.00	08.00	05.00		B/D Due to Insulator Failure	No
3		Bollaram - II	Rupa	11KV	Patancheru	14.15	15.15	01.00		B/D Due to Conductor Snapped	No
4		Hathnoora	Town Ind	11KV	Jogipet	13.30	16.00	02.30		B/D Due to Insulator Failure	No
1	RR S	Manikonda	Friends Colony	11KV	Ibrahimbagh	21:02	22:10	1:08		11KV Pin insulator failed at Friend Colony	No
1	RR N	KPHB	HMT Hills	11KV	Kukatpally	19:14	21:30	2:16	EL/OL	11kv Pin insulator failure at Narayana collage	No
2		Mayurinagar	Gokaraju Rangaraju	11KV	Kukatpally	21.10	22.25	01.15	EL	11kv Pin insulator failure at Gokaraju Rangaraju Road	No
3		Dp Pally SS	IDA Cable	11KV	Jeedimetla	05.00	06.00	01.00	EL/OL	11kv pin insulator failure sub station back side	No
4		Athiwelly	IDA	11KV	Medchal	09.10	10.20	01.10	EL	NO Fault(Breaker Mechanical Problem)	No
5		Gowdavelly	Ayodhya	11KV	Medchal	16.07	17.45	01.38	EL/OL	11KV Pin Insulator Failed and replaced at Saket Vencher backside	No
6		Kandlakoya	Saigeetha Ashramam	11KV	Medchal	18:10	19:15	1:05	EL	Tree Branch Fallen on 11KV Line at Petrol Bunk,Kandlakoya	No
1	RR E	Uppal	Chilaka Nagar	11KV	Habsiguda	3:50	5:10	1:20		Gabbilam fallen on 11KV line at Adarsha Nagar Church DTR	No
2		Cherlapally-V	Ambedkar Nagar	11KV	Sainikpuri	20.57	21.57	01.00		11Kv Insulator failed at Church Colony near Ambedkar Nagar (AE/OP)	No
3		Aushapur	NFC nagar	11KV	Keesara	02.40	04.50	02.10		Disk fallen at NFC nagar	No
4		Narapally	P.Singaram	11KV	Keesara	14.30	15.15	00.45		Copper patti cut at Korremulla	No
5		Nagaram	SN colony	11KV	Keesara	15:59	17:07	1:08		Insulator fail at Rampally X Road	No
1	HYD N	Marredpally	Ramser Café	11KV	C-VI	00.50	02.00	01.10	EL,OL	Faulty loads of 11KV Teachers Colony fdr	No
2		I.D.P.L.	Saakshi	11KV	VI	3:50	5:30	1:40	OL-R&Bph	3Nos. Brass Patti B/O & HT Jumper cut at Techno Company	No
3		Sanjeevaiah Park	Police Line	11KV	C-VI	23:30	1:26	1:56	AR Tripped	Disc Insulator flash over near Ramalayam	(00:00 Hrs partial feeder charged)
1	HYD S	Kanchan Bagh	I.S.Sadan	11KV	VIII	19.38	20.55	01.17	EL	Pin Insulator flash over at Khaja Hotel	No
1	HYD C	A.S.R.Raju Nagar	Golla Basthi	11KV	VII	10.22	11.30	01.08	EL,OL	Pin Insulator flash over at Govt.School	No
2		Golnaka	Nehru Nagar	11KV	II	14.31	15.48	01.17	EL,OL	Post type Insulator flash over at Saibaba Temple	No
3		Toli Chowki	Hakimsha	11KV	VII	20.50	22.35	01.45	EL	Disc Insulator flash over at Paramount Colony	No