

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988		5		5		5			
3	MDK	107	933	1		1		1				
4	SDPT				8		8		8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	15	2	15	2	15	0	0	
	Grand Total	1082	6468	2	16	2	16	2	16	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.08.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Polepally	Jadcherla	33KV	Jadcherla	03.47	07.07	03.20		AB Switch failed	Jadcherla	-
1	MDK	Kandi	HFC I	33KV	Sangareddy	19.20	20.10	00.50		BD due to CT Blast	HFC I	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 24.08.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Sri Venkatapur	Suraram	11KV	Mahabubnagar	15.10	16.10	01.00		Tree branches fallen on line	-
2		Kodur	Zamistapur	11KV	Mahabubnagar	10.50	13.00	02.10		Conductor snapped	-
1	NLG	Thungathurthy	Velugupally	11KV	Suryapet	09.00	13.10	04.10	E/L	Jumper cut	-
2		Thummadam	Vallabhapuram	11KV	Miryalaguda	12.30	14.30	02.00	E/L	Jumper cut	-
3		Narkatpally	M.Yedavally	11KV	Nalgonda	08.00	09.30	01.30	E/L	11 KV Line Jumper Cut	-
4		Velugupally	Iethavarigudem	11KV	Nalgonda	12.00	13.25	01.25	E/L	Insulator failed	-
5		Velmajala	Seetharampur	11KV	Bhongir	13.20	15.15	01.55	EL/OL	11kv Line snapped near Chippalakunta Village	-
1	SDP	Chellapur	Rajakkapet	11KV	Siddipet	02.30	09.50	07.20		B/D-Lt Wire Cut Line Touch Ic No 3087	-
2		Erravally SS	Lift Irrigation & Police station Feeder LC: 26368	11KV	Gajwel	11.50	12.30	00.40		Disk Fail	-
3		Seetharam Pally Ss	Vellore Feeder	11KV	Gajwel	08.50	12.05	03.15		Tree Branch Fallen	-
4		Kpkkonda SS	Singannaguda Feeder LC:4679 (Raju LM)	11KV	Gajwel	10.15	10.50	00.35		Tree Branch Fallen	-
5		Dommata SS	Dommata Feeder	11KV	Gajwel	07.46	08.31	00.45		Face to Face	-
6		Doulthabad SS	Lingarajapally Feeder LC: 3160 (Dubbaiah LM)	11KV	Gajwel	16.59	17.52	00.53		Problem Not Found	-
7		Mubaraspur SS	Thirmalapur Feeder LC:850(Srinu CL)	11KV	Gajwel	08.54	10.10	01.16		11 K V jumper cut	-
8		Gajwel SS	Town II Feeder	11KV	Gajwel	10:30	12:00	01.30		Problem Not Found	-
1	RR N	Thumkunta	Thumkunta	11KV	Medchal	07.50	09.30	01.40		No visible fault	-