

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4		4		4				
2	NLG	144	988		1		1		1			
3	MDK	107	933		0		0		0			
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	4	4	4	4	4	0	0	
	Grand Total	1082	6468	4	6	4	6	4	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.08.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Ghanapur	Solipur	33KV	Wanaparthi	07.09	09.30	02.21	E/L	Disc Failed Near Kothapally Thanda		-
2		Balanagar	Navadurga	33KV	Jadcherla	19.50	20.30	00.40	O/L	Problem in Company		-
3		Maddur	Damargidda	33KV	Narayanapet	22.00	00.15	02.15	E/L	Disc Insulator Failed Near Desaipally(V)		-
4		Kothur	Manasa Sarovar	33KV	Shadnagar	01.15	09.05	07.50	E/L	Disc Insulator Failed in Company		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 26.08.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	T Singaram	T Singaram	11KV	Suryapet	06.00	09.35	03.35	E/L	11Kv Disk failed	-
1	SDPT	Bekkal	Kondapur	11KV	HUSNABAD	00.20	10.30	10.10		Insulator Fail	-
2		Mulugu	Mulugu AGL Feeder	11KV	GAJWEL	14.20	15.20	01.00		AB Switch Open	-
3		Mulugu	Mulugu AGL Feeder	11KV	GAJWEL	16.20	18.40	02.20		Tree Baranch Fallen	-
1	RR N	ICICI	SP-I	11KV	Medchal	09.50	10.55	01.05	BD	HG fuse Cut at RVM-2 & 3	-
1	HYD N	Osm.University	Mettuguda	11KV	Sec-Bad	14.35	17.10	02.35	EL	Cable fault at Mettuguda	3No DTR's Kept off at Mettuguda