

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	5	1	5	1	5			
7	RR(E)	168	403									
8	Hyd	194	1044		9		9		9			
	Total	606	3055	1	15	1	15	1	15	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	2	14	2	14	12	14			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT				22		2		22			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	38	5	18	15	38	0	0	
	Grand Total	1082	6468	6	53	6	33	16	53	0	0	

TSSPDCL - LMRC / Corporate office

Date: 27.08.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Devarkadra	33KV	Narayanpet	21.45	22.00	00.15	E/L	Due to Rain	Devarkadra	Alternate Supply Arranged From 33KV Koukuntla at 22:00Hrs.
2		Gadwal	Maldakal	33KV	Gadwal	22.40	04.20	05.40	E/L	Not Rectified	Maldakal	NO
1	NLG	Kusumanchi	Mamillagudem	33KV	Huzurnagar	06.00	10.15	04.15	EL	Line Petroling		-
2		Aitipamula	Nakrekal	33KV	Nalgonda	13.32	15.34	02.02	EL	Bird Fallen the Line		-
1	MDK	Narayankhed	Kalher	33KV	Jogipet	09.25	11.40	02.15		B/D Due to Jumper Cut	Kalher	-
1	RR N	132KV LGM Pet	33KV Aliabad	33KV	Medchal	10.04	11.09	01.05		No visible fault	33KV Aliabad	-

## Circle-wise 11KV Breakdowns

Date: 27.08.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thimmanagudem	Ch Chennaram	11KV	Nalgonda	03.10	10.30	07.20	EL	Jumper Cute	-
2		Palem	Ogodu	11KV	Nalgonda	07.25	08.10	00.45	EL	Jumper Cute	-
3		Aitipamula	Gngadevi Gudem	11KV	Nalgonda	09.00	10.15	01.15	EL	Insulator Failed	-
4		Bollapally	Bollapally AGL	11KV	Nalgonda	11.00	12.20	01.20	EL	Tree Branches Fallen on the Line	-
5		Eduloor	Garlabavi Gudem	11KV	Nalgonda	16.00	18.20	02.20	EL	Jumper Cute	-
6		Panagal	Panagal Town	11KV	Nalgonda	12.10	14.25	02.15	EL	11KV Pin Insulator Fail	-
7		Palem	Ogodu	11KV	Nalgonda	12.35	13.45	01.10	EL	Jumper Cute	-
8		Kattangur	Kattangur Town	11KV	Nalgonda	15.10	17.20	02.10	EL	11KV Jumper Cute	-
9		Koppole	Koppole AGL	11KV	Nalgonda	14.45	16.23	01.38	EL	11KV Jumper Cute	-
10		Thatipamula	Nandhapuram	11KV	Suryapet	08.30	10.55	02.25	EL	Insulator falshover	-
11		Penpahad	SR Palem	11KV	Suryapet	10.00	13.15	03.15	EL	Disk failed	-
12		Bethavolu	Bethavolu	11KV	Huzurnagar	07.05	09.00	01.55	EL	11 KV LINE SNAPPED	-
13		Bollepally	Indriyala	11KV	Bhongir	08.40	11.20	02.40	EL	11 kv Insulator failed	-
14		Ch.Laxmapur	Ch.Laxmapur	11KV	Bhongir	13.15	15.10	01.55	EL	11kv Insulator Failed	-
1	MDK	Patancheru Town	MIA-I	11KV	Patancheru	07.50	09.30	01.40		B/D Due to tree branch fallen on the line	-
2		Fasalwadi	MNR	11KV	Sangareddy	09.14	10.30	01.16		B/D Due to Jumper Cut	-
1	SDP	Indoor	Town PS	11KV	Siddipet	13.51	14.45	00.54		B/D 11Kv Insulator Fail LC no. 35864	-
2		Ponnala	Kistasagar	11KV	Siddipet	12.20	15.30	03.10		B/D Tree fall Down on line	-
3		Mittapally	Mittapally	11KV	Siddipet	07.20	12.00	04.40		B/D Tree fall Down on line	-
4		Gonepally	Gonepally	11KV	Siddipet	15.47	16.05	00.18		I Ph DTR Jumper Cut Lc no. 20725	-
5		Peddachikode	Achumaipally	11KV	Siddipet	10.30	12.38	02.08		B/D Tree fall Down on line	-
6		Jangapally	Jangapally	11KV	Siddipet	08.30	11.16	02.46		B/D LT Line cut	-
7		Mirdoddy	Kasulabad	11KV	Siddipet	05.00	08.50	03.50		B/D Tree fall Down on line	-
8		Mirdoddy	Mirdoddy	11KV	Siddipet	06.20	08.40	02.20		11 Kv Disk Fail	-
9		Gajwel -Pregnapur SS	Town II Feeder	11KV	Gajwel	05.10	06.10	01.00		HG fuse Set Problem	-
10		Pregnapur SS	Gundanapally Feeder (3Ph)	11KV	Gajwel	08.25	14.00	05.35		Tree Baranch Fallen	-
11		Pregnapur SS	Akkaram Feeder (3Ph)	11KV	Gajwel	06.42	13.18	06.36		Pin Insulater Fail	-
12		Erravalli SS	Erravalli AGL Feeder	11KV	Gajwel	04.20	14.31	10.11		Insulater Fail	-
13		Ganeshpally SS	Ganeshpally Town Feeder	11KV	Gajwel	09.10	10.35	01.25		Insulater Fail	-
14		Gowraram SS	Gowraram Town 1	11KV	Gajwel	12.43	14.11	01.28		11 KV line Cut	-
15		Seetharampally Ss	Veloore Feeder	11KV	Gajwel	16.10	17.10	01.00		11 KV line Cut	-
16		Godugupally SS	Godugupalli Feeder	11KV	Gajwel	11.32	14.33	02.59		Insulater Fail	-
17		Gurrallasofa SS	Vaddepally Village Feeder	11KV	Gajwel	04.40	10.10	05.30		HT By LT	-
18		Mettu SS	Ghanapur Feeder	11KV	Gajwel	14.10	16.45	02.35		11 KV disk Fail	-

19		Pallepahad SS	Vemulaghat Feeder	11KV	Gajwel	06.15	09.35	03.20		11KV wire Cut	-
20		Thukkapur SS	PS feeder LC:7204	11KV	Gajwel	08.20	11.50	03.30		Tree Baranch Fallen	-
21		Gurjakunta	Gurjakunta 24 hrs	11KV	Husnabad	08.45	13.05	04.20		B.D TREE FALEN ON LINE	-
22		Komuravelly	Kistampet	11KV	Husnabad	06.10	14.58	08.48		B.D INSULATOR FAILURE	-
1	RR S	Chnada Nagar	Madinaguda	11KV	Gachibowli	10.30	12.00	01.30	BD	HG fuse insulator failed at Sai krupa Apartmemnt	-
1	RR N	Dulapally	Dulapally Village	11KV	Medchal	06.16	07.05	00.49		11KV Line Touched on the 11KV Pole at Ashoka Developers	-
2		Laxmapur	Narayanpur	11KV	Medchal	10.55	14.25	03.30		11KV Disc failed & Replacled at Gururaja Company Opposite, Narayanpur	-
3		Laxmapur	Laxmapur	11KV	Medchal	10.55	12.40	01.45		Tree Branch fallen on the 11KV Line at Karkapatla Road, Laxmapur	-
4		Yellampet	Yellampet Village	11KV	Medchal	03.15	05.15	02.00		11KV Pin Insulator failednear Hanuman Temple	-
5		Kistapur	IDA Hanuman	11KV	Medchal	11.30	13.50	02.20		No Fault(Due to Heavy Rain)	-
1	HYD N	Pragatools	Giri Nagar	11KV	VI	08.25	09.55	01.30	EL	Pin Insulator flash over at Plot No.25, APHB Colony	-----
2		Pragatools	Eshwar Vimal	11KV	VI	08.35	09.50	01.15	EL	Tree branches fallen on lines at Gandhi Nagar	-----
3		R.P.Nilayam	Ram Nagar	11KV	C-VI	08.40	09.45	01.05	EL,OL	No Visible Fault	-----
4		Gunrock	Tirumalagiri	11KV	C-VI	08.45	10.30	01.45	EL	No Visible Fault	-----
5		Gunrock	A.W.H.O Colony	11KV	C-VI	08.45	10.20	01.35	EL	Post type Insulator flash over at C-Block	-----
6		Clock Tower	Sangeeth	11KV	V	08.48	10.10	01.22	EL,OL	No Visible Fault	Arranged B/F on 11KV Sangeeth fdr
7		Seethaphal Mandi	Namala Gundu	11KV	V	08.50	10.25	01.35	EL,OL	Cable fault at Wesley Church	-----
8		Lalaguda	A.P.Dairy	11KV	V	12.10	13.50	01.40	EL	HT Jumper cut at A.P.Dairy Form	-----
9		Prashanth Nagar	Sony Complex	11KV	VI	13.30	15.10	01.40	OL-Rph	2No. Line AB Switch Jumpers cut at Telepone Exchange	-----