

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		6		6		6			
	Total	606	3055	0	11	0	11	0	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	4	1	4	1	4			
2	NLG	144	988	2	5	2	5	2	5			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT			1	7	1	7	1	7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	17	5	17	5	17	0	0	
	Grand Total	1082	6468	5	28	5	28	5	28	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.08.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Amangal	Kadthal	33KV	Shadnagar	11.55	14.15	02.20	EL	Bird fallen on the line ramunthala (vi)		-
1	NLG	Aitipamula	Arlagaddagudem	33KV	Nalgonda	01.30	15.15	13.45	E/L	Line Snapped		-
2		Miryalaguda	Avanthipuram	33KV	Miryalaguda	06.03	13.15	07.12	E/L	Insulator Failure		-
1	MDK	Narayankhed	wasar	33KV	Jogipet	14.50	16.34	01.44		BD due to Tree branches fallen on line		-
1	SDPT	Habsipur	Chittapur	33KV	Siddipet	18.05	18.25	00.20		B/D Tree Fallen		-

## Circle-wise 11KV Breakdowns

Date: 29.08.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Jadcherla	Gangapur X Press	11KV	Jadcherla	00.00	07.10	07.10		11KV Jumper cut near Aloor Railwa Get	-
2		Kosgi	Bhogaram	11KV	Narayanapet	13.50	16.05	02.15		11KV Jumper cut & Disc failure	-
3		Maddur	Ayyawarpally	11KV	Narayanapet	05.45	07.45	02.00		11KV Disc failure	-
4		Chinnajatram	Mission of Bhagiratha	11KV	Narayanapet	07.21	08.40	01.19		11KV Disc failure	-
1	NLG	Kuda Kuda	Ilapuram	11KV	Suryapet	13.10	14.25	01.15	E/L	Insulator failed	-
2		Kodur	Kommala	11KV	Suryapet	10.00	13.20	03.20	E/L	Disc Failed	-
3		Mattampally	Errajelu	11KV	Huzurnagar	04.00	06.45	02.45	EL	11 KV LINE SNAPPED	-
4		Repala	Repala	11KV	Huzurnagar	06.00	08.15	02.15	EL	11 KV JUMPER CUT	-
5		Motakondur	Motakondur Agl	11KV	Bhongiri	04.00	08.00	04.00	EL/OL	11 kv Line snapped at SS-11 near Motakondur village	-
1	MDK	Patancheru Town	MIA-I	11KV	Patancheru	11.50	13.00	01.10		BD due to Conductor snapped	-
1	SDPT	Nangnoor	Akenapllay	11KV	Siddipet	09.32	11.37	02.05		B/D-11KV wire cut and touch the rectified	-
2		Nangnoor	Nangnoor	11KV	Siddipet	13.30	14.55	01.25		B/D-Dtr Fail-rectified	-
3		Pandilla	Potlapally	11KV	Husnabad	18.20	18.40	00.20		Jumper cut	-
4		Komuravelli	Inapur Agl	11KV	Husnabad	08.15	09.50	01.35		Copper patti Cut	-
5		Nemtoor Ss	Jabbapur feeder LC:019 (Swamy CL) (3Ph)	11KV	Gajwel	13.20	14.45	01.25		11 Line snaped	-
6		Thunki Bollaram Ss	Achaipally Feeder LC:2276 (Babu CL)	11KV	Gajwel	20.00	11.00	15.00		Bird Fallen In 11 KV Line	-
7		Raipole SS	Kothapally Feeder LC:6373 (Mohan Reddy LM)	11KV	Gajwel	7:35	13:25	5:50		Jumper Cut	-
1	RR S	Nalagandla	Jawahar Navodaya	11KV	Gachibowli	19.20	20.40	01.20		Due to heavy rain, 2 No's 11kv pin Insulators failed near Andhra bank at Nalagandla.	-
1	RR E	Uppal	Uppal	11KV	Habsiguda	01.50	03.35	01.45		Line Patrolling & 11KV Jumper opened near Laxmi Garden at Laxma Reddy Colony due to 11KV disc insulator failed at Padmalaxmi DTR & 11KV Jumper cut at Surya Nagar Colony DTR & B/F supply taken from 11KV Vijayapuri Colony feeder	-
2		Uppal Bhagath	Saraswathi colony	11KV	Habsiguda	03.15	04.25	01.10		Line Patrolling & 11KV Jumper opened near Shilparamam Dumping Yard	-
3		IDAuppal	Srikrishna	11KV	Habsiguda	11.15	13.16	02.01		Tree branches fallen & brash patti cut at arts printing company	-
4		Narapally	Industrial	11KV	Keesara	10.05	11.35	01.30		HG Fuse Insulator fail at Venkatdri town ship	-
1	HYD N	Kalyan Nagar	Laxmi Nagar	11KV	X	18.40	19.50	01.10	EL	Jumper cut at Plot No.32, Kalyan Nagar	-
2		I.D.P.L	Wonder Plast	11KV	VI	19.40	21.55	02.15	EL	Insulator flash over at Canteen & Jumper cut at 1st line AB Switch	-
3		Gunrock	Thirumalgiri	11KV	C-VI	19.42	21.25	01.43	EL	Insulator flash over at LIC Building	-
1	HYD S	Santosh Nagar	Dry Land	11KV	VIII	02.35	04.10	01.35	EL	Pin Insulator flash over at Water Works	-
1	HYD C	Lake View	Kapadia Lane	11KV	I	12.48	14.06	01.18	EL	I/C Cable fault at R.M.U	Arranged B/F on 11KV Jaffer Ali Bagh feeder
2		Golconda	Narayanamma College	11KV	VII	14.25	15.40	01.15	EL,OL-Bph	Bird fault at Darga	-