

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		8		8		8			
3	MDK	107	933	1		1		1				
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	8	1	8	1	8	0	0	
	Grand Total	1082	6468	1	9	1	9	1	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.08.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Sadasivpet	Kondapur	33KV	Sangareddy	07.15	09.40	02.25		B/D Due to Conductor Snapped	Kondapur	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 30.08.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Athmakur(S)	Naseempeta	11KV	Suryapet	08.00	11.35	03.35	E/L	Jumper cut	-
2		Janpahad	Janpahad	11KV	Huzurnagar	05.00	07.30	02.30	EL	11 KV LINE SNAPPED	-
3		Ch.Annaram	Gadibaigudem	11KV	Nalgonda	08.30	12.40	04.10	EL	11KV jumper cut	-
4		Eduloor	Parada	11KV	Nalgonda	02.30	07.00	04.30	EL	11KV jumper cut	-
5		Arlagaddagudem	Naregudem	11KV	Nalgonda	03.40	08.00	04.20	EL	Tree branch fallen on line	-
6		Katangur	Kalimera	11KV	Nalgonda	04.20	09.00	04.40	EL	11KV jumper cut	-
7		Venkatapuram	Datthaipally	11KV	Bhongir	06.55	10.30	03.35	EL/OL	11 kv Insulator failed near Manthronimammilu village	-
8		Mandollgudem	Peddakondur	11KV	Choutuppal	06.41	10.40	03.59	EL/OL	11kv Line Snapped near Peddakondur Village	-
1	RR E	Sai Nagar	Maruthi Nagar	11KV	Habsiguda	03.55	04.40	00.45		11KV Jumper cut at BL Nagar Colony	-