

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT				7		7		7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	10	0	10	0	10	0	0	
	Grand Total	1082	6468	0	17	0	17	0	17	0	0	

TSSPDCL - LMRC / Corporate office

Date: 01.12.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
NIL												

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Sampally	11KV	Narayanapet	11.09	12.00	00.51		11KV Conductor cut at sampally village	No
1	NLG	Thatipamula	Thatipamula	11KV	Suryapet	13:33	14:49	1:16	EL	Line cut	No
2		B.Ramaram	Malyala	11KV	Bhongir	09.30	11.00	01.30	EL	11kv Insulator failed	No
1	SDPT	AHMEDIPUR	JILLALPUR	11KV	Gajwel	16:10	17:40	1:30		11KVA Conductor cut	No
2		MULUGU	SWEETHA GRANED	11KV	Gajwel	14.05	17.50	03.45		11KV Line cut	No
3		Narsapur	Lingareddypally	11KV	Siddipet	12.50	14.15	01.25		Due to bird fallen on the line	No
4		Habshipur	Habshipur	11KV	Siddipet	06.06	08.22	02.16		Disc failed LC No.4270	No
5		Ragothampally	Gosanpally	11KV	Siddipet	03.46	09.14	05.28		Grass fall on 11KV line	No
6		Ragothampally	Gosanpally	11KV	Siddipet	09.49	11.22	01.33		Due to Grass fall on 11KV line	No
7		Gurjakunta	Gurjakunta AGL	11KV	Husnabad	9:35	10:55	1:20		Tree branches fallen on the line	No
1	RR S	Kothaguda	Hafeezpet	11KV	Kondapur	14:40	16:30	1:50		11KV AB cable failed at Kondapur	No
1	RR N	GP Pally	APIIC	11KV	Medchal	5:50	7:00	1:10		Lizard fallen on 11KV line at Pipes Company	No
2		Kandlakoya	Saigeetha Ashramam	11KV	Medchal	10.40	12.10	01.30		Tree fallen on 11KV line at Bharath reddy Godham	No
1	HYD N	Road No.2	Arora Colony	11KV	X	17.19	20.42	03.23	EL	Cable fault at Satya Sai back side	Arranged B/F on 11KV Eye Drusti & 11KV Lumbini Mall feeders
1	HYD C	Public Garden	Telugu University	11KV	I	00.15	01.39	01.24	EL,OL-Rph	HT Jumper cut at Maruthi Show Room	No
2		Lumbini Park	Avanthi Nagar	11KV	I	01.44	03.12	01.28	OL	No Visible Fault	Arranged B/F on 11KV Commissioner Officer feeder
3		Indira Park	Kawadiguda	11KV	I	09.35	11.00	01.25	EL,OL	Cable End Kit Lug damaged at Traffic Police Station	No