

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		5		5		5			
3	MDK	107	933		1		1		1			
4	SDPT			1	2	1	2	1	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	9	2	9	2	9	0	0	
	Grand Total	1082	6468	2	9	2	9	2	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 04.12.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Ghanapur	33KV	Mahabubnagar	10.24	15.52	05.28	E/L&O/L	Pin Binding Replacemnet Work at Wader Basti	Ghanapur	-
1	SDP	Habsipur	Chittapur	33KV	Siddipet	00.24	11.10	10.56		BD (Insulater failure)	Chittapur	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 04.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Kothur	11KV	Jadcherla	00.10	06.30	06.20		11KV Wire cut near Midjil	-
1	NLG	Thungathurthy	Bandaramaram	11KV	Suryapeta	06.00	09.30	03.30	EL	Insulator failed	-
2		Gaddipally	Medaram	11KV	Huzurnagar	07.35	09.00	01.25	EL	11 KV LINE SNAPPED	-
3		Bethavolu	Bethavolu	11KV	Huzurnagar	08.30	09.35	01.05	EL	11 KV LINE SNAPPED	-
4		Datherpally	Mallapur	11KV	Bhongir	12.30	14.23	01.53	EL/OL	11kv Insulator Failed near Mallapur Village	-
5		Bondugula	Bondugula Agl	11KV	Bhongir	04.00	12.10	08.10	EL/OL	100kva DTR Failed near Bondugula Village	-
1	MDK	Bollaram - I	Sulaxshana-I	11KV	Patancheru	14.50	15.50	01.00		BD Due to Jumpercut	-
1	SDP	Jakkapur	Jakkapur	11KV	Siddipet	17.02	17.50	00.48		B/D-1ph supply run-now rectified	-
2		Laxmidevipally	Laxmidevipally	11KV	Siddipet	00.02	07.40	07.38		B/D-DTR failure-Now rectified	-