

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		5		5		5			
2	NLG	144	988		5		5		5			
3	MDK	107	933		2		2		2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	12	0	12	0	12	0	0	
	Grand Total	1082	6468	0	17	0	17	0	17	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 08.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Bhogaram	11KV	Narayanapet	08.30	11.28	02.58		11KV insulator failed at Bhogaram village	-
2		Kothapally	Lingalched	11KV	Narayanapet	13.00	16.10	03.10		HT line snapped and fallen on LT cross arms at Kommur village	-
3		Makthal	SANGAMBANDA	11KV	Narayanapet	09.07	09.15	00.08		line fault	-
4		Makthal	SANGAMBANDA	11KV	Narayanapet	13.30	15.20	01.50		line fault	-
5		Paspula	MUSTIPALLY(PANC HDEV PADU)	11KV	Narayanapet	15.20	15.45	00.25		1KV disc failure	-
1	NLG	Thungathurthy	Ganugubanda	11KV	Suryapet	07.40	09.45	02.05	E/L	Bird fallen on the line	-
2		Thatipamula	Sri Ram thanda	11KV	Suryapet	02.50	07.30	04.40	E/L	Jumper cut	-
3		Timmareddygudem	Ganapavaram	11KV	Huzurnagar	06.40	08.00	01.20	EL	11 KV LINE SNAPPED	-
4		Yennaram	Kunkudupamula	11KV	Choutuppal	09.50	11.07	01.17	EL	11 KV Line snapped at Kapukunta SS-9 near Kunkudupamula village	-
5		Pamanagundla	Ismailpally	11KV	Nalgonda	13.10	14.30	01.20	EL	Jumper cut	-
1	MDK	EPIP-II	Marigold	11KV	Sangareddy	12.35	13.58	01.23		BD Due tree fallan on line	-
2		Patancheru Town	Kanjarla	11KV	Patancheru	11.25	13.50	02.25		BD Due tree fallan on line	-
1	RR N	UMCC	Crusher	11KV	Medchal	09.05	09.35	00.30	BD	11KV AB Switch Opened at Lal Sahebguda (Tree Branch fallen on the 11KV Line at Ravindhar Traders)	-
2		GP Pally	Neighbourhood	11KV	Medchal	11.30	12.35	01.05	BD	11KV Brass Patti Cut & Replaced at Neighbourhood Villas	-
1	HYD N	Alwal	Dinakar Nagar	11KV	C-VI	01.52	03.50	01.58	EL,OL	No Visible Fault	Arranged B/F on 11KV Venu Gopal Nagar fdr
1	HYD S	Panjesha	Pancha Mohalla	11KV	III	11.50	12.59	01.09	EL,OL	No Visible Fault	12:47 Hrs partial feeder charged & Partial loads arranged B/F on 11KV Charminar fdr
2		Malakpet	Bibi Ka Alam	11KV	VIII	13.57	15.25	01.28	All Indication	AB Switch fault at Dabeerpura Bridge	-----