

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	4	0	4	0	4	0	0	
	Grand Total	1082	6468	0	7	0	7	0	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.12.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
NIL												

TSSPDCL - LMRC / Corporate office

Date: 13.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nidmanoor	Bankapuram	11KV	Miryalaguda	16:10	18:00	1:50	EL	Single phase transformer failed near bankapuram village	No
2		Kudakuda	MG Nagar Thanda	11KV	Suryapet	03.00	06.40	03.40	EL	Jumper cut	No
1	SDPT	Ragothampally	Gosanpally	11KV	Siddipet	0:00	10:28	10:28		Due to Wire cut	No
2		Chityal	Dommata	11KV	Husnabad	01.12	07.12	06.00		Due to insulator failed	No
1	RR N	Shameerpet	Shameerpet	11KV	Medchal	16:10	19:05	2:55		11KV Poles 3Nos Damaged at Babaguda (11KV Jumper opened)	No
1	RR E	Nacharam	Nagarjuna	11KV	Habsiguda	14:58	16:20	1:22		11KV Pin Insulator failed at Sifco Company	No
1	HYD C	Osm. University	Boudha Nagar	11KV	II	18.35	20.06	01.31	EL	DTR fault at Raja Bowli	At 19:40Hrs Partial fdr charged