

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		5		5		5			
3	MDK	107	933		3		3		3			
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	11	0	11	0	11	0	0	
	Grand Total	1082	6468	0	14	0	14	0	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 14.12.2020

33 KV BREAKDOWNS

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
NIL												

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 15.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Narayanapet	Narayanapet RURAL(JAJAPUR)	11KV	Narayanapet	10.40	11.45	01.05		DUE TO NEAR TO HT/LT CROSSING, SINGARAM	-
1	NLG	Kistrampally	Kurampally	11KV	Devarakonda	10.12	11.02	00.50	E/L	11 KV Jumper Cutt	-
2		Azmapur	Azmapur	11KV	Devarakonda	14.10	14.55	00.45	E/L	11 KV Insulator Failed	-
3		Ravulapally	Manapuram	11KV	Suryapet	08.40	11.55	03.15	E/L	11Kv Conductor snapped	-
4		D Nagaram	NS Gudem	11KV	Suryapet	11.30	12.30	01.00	E/L	11Kv Jumper cut	-
5		Munagala	Kokkereni-2	11KV	Huzurnagar	04.00	07.15	03.15	E/L	11Kv Jumper cut	-
1	MDK	Chaitanya	EPIP-I	11KV	Sangareddy	09.45	11.20	01.35		B/D Due to Conductor Snapped	-
2		MIA-I	Patancheru Town	11KV	Patancheru	10.03	11.03	01.00		BD Due to Jumpercut	-
3		MIA-II	Patancheru Town	11KV	Patancheru	14.40	15.55	01.15		B/D Due to Conductor Snapped	-
1	SDPT	Gurralongondi	Gurralongondi	11KV	SDPT	08.54	09.44	00.50		B/D Tree brach fall on the line	-
2		Chellapur	Rajakkapet	11KV	SDPT	10.18	12.50	02.32		B/D Due to Bird	-
1	RR N	Aliabad	Majeedpur	11KV	Medchal	10.45	12.15	01.30	BD	11KV Jumper Cut and Replaced at Nadigadda	-
2		Ravalkole	IDA Ravalkole	11KV	Medchal	11.41	12.27	00.46	BD	11KV Pin Insulator failed at Kasimbai Thanda	-
1	RR E	Moula-Ali	Moula-Ali	11KV	SKP	13.10	14.30	01.20		11Kv line cut on Stinging at JTC X Road (L Insp Venkateshwar Rao)	-