

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		7		7		7			
3	MDK	107	933	1		1		1				
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	11	1	11	1	11	0	0	
	Grand Total	1082	6468	1	11	1	11	1	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 16.12.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Sadasivpet	Jogipet	33KV	Sangareddy	5:25	8:45	3:20		Tree branches fallen on the line	Jogipet	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bijwar	Maqdumpur	11KV	Narayanapet	13.30	14.25	00.55		HT line cut and fallen on LT line at 100KVA DTR	No
2		Makthal	Sangambanda	11KV	Narayanapet	11.30	14.20	02.50		B/D due to pole damaged at Kondaiiah chenu	No
1	NLG	Kasarabadha	Imampeta	11KV	Suryapet	11:15	14:30	3:15	EL	HT/LT line melt	No
2		Kudakuda	Ilapuram	11KV	Suryapet	05.20	08.00	02.40	EL	Insulator failed	No
3		Munagala	Kokkereni-2	11KV	Huzurnagar	04.00	06.45	02.45	EL	11KV Line snapped	No
4		Siripuram	Vallapuram	11KV	Huzurnagar	11.30	13.00	01.30	EL	11KV Jumper cut	No
5		Koppole	Bheemaram	11KV	Nalgonda	05.25	07.10	01.45	EL	11KV Jumper cut	No
6		Kistrampally	Kurampally	11KV	Devarakonda	10.12	11.02	00.50	EL	11KV Jumper cut	No
7		Azmapur	Azmapur	11KV	Devarakonda	14:10	14:55	0:45	EL	11KV Insulator failed	No
1	SDPT	Mobharaspur	Malleshampally	11KV	Gajwel	1:30	7:51	6:21		DTR Failure	No
2		Mobharaspur	Thirumalapur	11KV	Gajwel	11.16	13.06	01.50		25KVA DTR failure	No