

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	7	1	7	1	7	0	0	
	Grand Total	1082	6468	1	8	1	8	1	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.12.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Musthyala	Komuravelly	33KV	Husnabad	8:00	9:30	1:30		Tree fallen on the line	Komuravelly	No

TSSPDCL - LMRC / Corporate office

Date: 17.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Salkarpet SS	Jangamreddypally	11KV	Narayanapet	08.00	10.00	02.00		Jumper cut and fallen on DTR	No
2		Marikal	P.C.Kunta	11KV	Narayanapet	07.51	09.05	01.14		Bird Sat on the Jumper Wire	No
1	NLG	B.Chandupatla	V.K Pahad	11KV	Suryapet	4:50	7:40	2:50	EL	Insulator failed	No
2		B.Ramaram	Maliyala	11KV	Bhongir	14.20	15.50	01.30	EL/OL	11KV Insulator failed near Malyala Village	No
1	SDPT	Nangunoor	Nangunoor Town	11KV	Siddipet	15:05	16:55	1:50		Insulator Problem LC.No.22892	No
2		Bekkal	Bairanpally	11KV	Husnabad	12.45	17.45	05.00		Tree branch fallen on the line	No
3		Maddur	Maddur Agl	11KV	Husnabad	08.45	09.30	00.45		Insulator failure	No
1	HYD N	Gunrock	Bowenpally	11KV	C-VI	16.10	17.55	01.45	EL	No visible fault	No