

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	10	1	10	1	10	0	0	
	Grand Total	1082	6468	1	12	1	12	1	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.12.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33KV	Narayanpet	00.30	00.55	00.25	E/L	No Visible Fault	Vepoor	Alternate supply Arranged to 33KV Hanwada Feeder at 00:55Hrs

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 18.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Manthangoud	Kathwar	11KV	Narayanpet	13.08	13.50	00.42		Bird Fallen on the 11KV Line	-
2		Marikal	P.C.Kunta	11KV	Narayanpet	08.25	10.00	01.35		11KV Conductor snapped & Fallen on the Other Line	-
3		Marikal	Tileru	11KV	Narayanpet	08.25	10.00	01.35		11KV Conductor snapped & Fallen on the Other Line	-
1	NLG	Kistrampally	Kurampally	11KV	Devarakonda	10.12	11.02	00.50	EL	11 KV Jumper Cutt	-
2		Azmapur	Azmapur	11KV	Devarakonda	14.10	14.55	00.45	EL	11 KV Insulator Failed	-
3		Kodur	Kodur	11KV	Suryapet	04.00	07.30	03.30	EL	Insulator failed	-
1	SDP	Husnabad	Madatha	11KV	Husnabad	13.30	15.40	02.10		DTR fault	-
2		Mulugu SS	Mulugu AGL	11KV	Gajwel	15.00	15.30	00.30		11 KV Line Cut Insulater Fail	-
3		Mulugu SS	Narsampally	11KV	Gajwel	15.06	15.36	00.30		11 KV line Cut	-
4		Doulthabad SS	Lingarajpally	11KV	Gajwel	04.29	08.18	03.49		Coper Patty Cut	-
1	HYD C	Industrial Area	Mother Dairy	11KV	II	08.45	12.20	03.35	EL	Breaker problem at SS	-
2		I.T.I Mallepally	Afzal Sagar	11KV	II	17.47	18.52	01.05	EL,OL	Pin Insulator flash over Afzal Sagar	-