

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		5		5		5			
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	8	0	8	0	8	0	0	
	Grand Total	1082	6468	0	14	0	14	0	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 21.12.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
NIL												

TSSPDCL - LMRC / Corporate office

Date: 21.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevelly	Chinnarevelly	11KV	Jadcherla	13.50	15.30	01.40		11Kv Jumper cut near Pochamma Gadda Tanda Side.	No
1	NLG	Mellavai	Revelly	11KV	Devarakonda	12:00	13:20	1:20	EL	11 KV Jumper Cutt	No
2		Kasarabada	Kasarabada	11KV	Suryapet	08.10	10.15	02.05	E/L	Insulator failed	No
3		Gundala	Gangapur	11KV	Bhongir	00.10	08.20	08.10	EL/OL	100 kva DTR failed at SS-6 near Gangapur village	No
1	SDPT	Chittapur	Mothey	11KV	Siddipet	4:15	9:25	5:10		Breakdown	No
2		Nimtoor	Jabbapur	11KV	Gajwel	10.45	11.10	00.25		Insulator failed	No
3		Nimtoor	Jabbapur	11KV	Gajwel	15.07	15.27	00.20		Tree branches fallen on the line	No
4		Thukkapur	Industrial	11KV	Gajwel	06.00	11.10	05.10		Jumper cut	No
1	RR N	Devarayamjal	Pothaipally	11KV	Medchal	4:50	6:05	1:15		11KV Jumper cut and replaced at Devarayamjal	No
1	HYD N	Lalaguda	St Ann's	11KV	V	08.17	11.30	03.13	EL	No Visible Fault	At 09:00 Hrs partial feeder chaged
2		Lalaguda	Railway Work Shop	11KV	V	11:25	12:38	1:13	EL	CT PT I/C Lugs B/o at Railway Work Shop	No
3		Chilkguda	Pragatools	11KV	V	14:21	15:30	1:09	EL,OL-Rph	No Visible Fault	No
4		Gymkhana	Mud Fort	11KV	C-VI	16:17	18:05	1:48	Tripped AR	Compound Wall fallen on lines at Madhubala Apts	No
1	HYD C	Asif Nagar	Padmanabha Nagar	11KV	VII	11.39	14.35	02.56	All Indication	Auto Reclosure End Kit fault at SS backside	Arranged B/F on 11KV Maruthi Nagar feeder