

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		3		3		3			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	5	1	5	1	5			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>10</b>	<b>1</b>	<b>10</b>	<b>1</b>	<b>10</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>14</b>	<b>1</b>	<b>14</b>	<b>1</b>	<b>14</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 22.12.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Chinchode	33KV	Jadcherla	00.45	03.00	02.15		LV's Pull Out & Breaker tripping Mechanizam Problem & 2no Insulators failed and replaced	Chinchode	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 22.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gokulnagar	Nandigama	11KV	Narayanapet	02.30	06.30	04.00		Due to Tree branch fallen on 11KV line	-
2		Salkarpet SS	Reddypally	11KV	Narayanapet	07.25	10.43	03.18		Due to Squirrel fallen on 11KV line	-
3		Gudeballore	KHANDOODI	11KV	Narayanapet	14.30	15.15	00.45		Due to 11KV conductor cut at Kothapally village	-
4		Kothamolgara	L and T	11KV	Jadcherla	03.40	07.50	04.10		11Kv pin Bindin Failure Near Patha Paper Mill side.	-
5		Kothamolgara	Maddigatla	11KV	Jadcherla	09.18	11.10	01.52		11Kv Jumper Cut Near Nallagutta Side.	-
1	NLG	Gondiryala	Gondiryala-2	11KV	Huzurnagar	04.00	07.15	03.15	E/L	11Kv Line Snapped	-
2		Indl.Estate	Vijayacolony	11KV	Suryapet	01.40	04.30	02.50	E/L	11Kv Insulator failed	-
3		Narkatpally	Yellareddygudem	11KV	Nalgonda	07.00	08.30	01.30	E/L	11Kv Insulator failed	-
1	SDPT	Gajwel	Mutrajpally	11KV	Gajwel	13.25	14.30	01.05		11Kv Line Snapped	
2		Varadarajpur	Varadarajpur	11KV	Gajwel	07.12	08.45	01.33		11Kv Line Cut	
1	RR E	Cherlapally-II	Phase-IV	11KV	Sainikpuri	08.55	09.40	00.45		11KV Jumper cut at Phase-I (AE)	-
1	HYD N	I.D.P.L.	Saakshi	11KV	VI	00.25	02.32	02.07	EL,OL-Bph	Rusted Pole damaged at Canara Bank	Arranged B/F on 11KV SIFCO fdr
2		Alwal	24 Hours Water Tap	11KV	C-VI	12.59	14.44	01.45	EL	No Visible Fault	-----
3		Road No.13	Namdhari	11KV	X	15.45	16.56	01.11	EL	Cable fault at Star Hospital	At 16:34 Hrs Partial loads arranged B/F on 11KV Meridian fdr