

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		3		3				
2	NLG	144	988	1	5	1	5	1	5			
3	MDK	107	933	1		1		1				
4	SDPT			1	2	1	2	1	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	7	6	7	6	7	0	0	
	Grand Total	1082	6468	6	10	6	10	6	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.12.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Machanpally	33KV	Mahabubnagar	04.45	05.25	00.40	EL	33KV Line Fault	Machanpally	-
2		Wanaparthi	Revally	33KV	Wanaparthi	05.07	08.30	03.23	EL	33KV Line Fault	Revally	-
3		220/33KV SS Singotam	Narsaipally	33KV	Nagarkurnool	07.55	12.14	04.19	EL	Tree Cutting & Insulator Replacement at Vitem X Raod	Narsaipally	-
1	NLG	Aitipamula	Kethepally	33KV	Nalgonda	09.50	15.04	05.14	E/L	33KV line cut at near by Inupamula(V)	Kethepally	-
1	MDK	Pashamailaram	Nactor	33KV	Sangareddy	6:15	13:05	6:50		BD Due to Bus jumper snapped OL R Y Phase	Nactor	-
1	SDPT	Gajwel	Mission Bhageeratha	33KV	Gajwel	10.47	13.50	02.03		Breaker Problem	Mission Bhageeratha	13:50 Alternate Feeder 33 KV B.V Pur From 132 KV Gajwel SS

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 23.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Eduloor	Parada	11kv	Nalgonda	08.30	10.00	01.30	E/L	11Kv Jumper cut	-
2		Chitriyala	Peddamura	11kv	Devarakonda	14.02	15.07	01.05	E/L	11Kv Insulator Failed	-
3		Dugyala	Thirumalagiri	11kv	Devarakonda	08.10	08.45	00.35	E/L	11Kv Jumper cut	-
4		Phanigiri	Phanigiri Agl	11kv	Suryapet	14.30	16.30	02.00	E/L	11kV Insulator failed	-
5		Solipet	Solipet	11kv	Bhongir	06.20	10.00	03.40	EL/OL	11 KV Line snapped at BC Colony near Chikatimamidi (V)	-
1	SDPT	MULUGU	ALL FEEDERS SHUT DOWN	11kv	Gajwel	16.10	17.10	01.00		AB SWITCH REPAIR	-
2		RAMPUR	INDUSTRIAL	11kv	Gajwel	5:10	7:40	2:30		POLE DAMAGE	-
1	HYD N	R.P.Nilayam	Saraswathi Nagar	11kv	C-VI	07.34	09.04	01.30	EL,OL-Rph	HT Cable burnt out at Lothukunta Signal	-----
2		Gymkhana	Vasavi Nagar	11kv	C-VI	08.14	09.35	01.21	W/O Indication	Pigeon fallen on lines at Andhra Bank	Arranged B/F on 11KV Jyothi Colony feeder
3		Marredpally	Ramsar Café	11kv	C-VI	19.10	20.30	01.20	EL	Breaker problem at SS	Arranged B/F on 11KV Teachers Colony feeder