

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		5		5		5			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT			1	2	1	2	1	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	7	1	7	1	7	0	0	
	Grand Total	1082	6468	1	13	1	13	1	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.12.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Gajwel	Express	33KV	Gajwel	13:07	17:07	4:00		No visible fault	Express	No

TSSPDCL - LMRC / Corporate office

Date: 29.12.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Mustipally	Anugonda	11KV	Narayanapet	10.26	11.07	00.41		11KV Conductor cut at ankenpally vlg	No
2		Damargidda	Bapanpally	11KV	Narayanapet	14.00	15.35	01.35		Disc failure near Bapanpally Village	No
1	NLG	Thungathurthy	B Ramaram	11KV	Suryapeta	3:40	8:00	4:20	E/L	Insulator failed	No
2		Malkapur	Malkapur Agl	11KV	Choutuppal	09.09	11.05	01.56	EL/OL	Lorry Damedged 11kv Pole near Pochampally Road	No
3		Malkapur	Thooprampet Indl	11KV	Choutuppal	08.15	09.10	00.55	EL/OL	DCM Damedged 11kv Pole near Malkapur Village	No
1	SDPT	Mirdoddy	Kasulabad	11KV	Siddipet	10:40	12:50	2:10		11 KV Wire cut	No
2		Lingapur	Industrial	11KV	Gajwel	14.45	16.06	01.21		Conductor snapped	No
1	RR N	Jeedimetla SS II	Kompalli pharma	11KV	Jeedimetla	11:05	12:15	1:10	EL/OL	AB Cable End Kit 2 nos failure Kompally Pharma out side	No
2		UMCC	Gajularamaram	11KV	Medchal	00.30	02.35	02.05	EL/OL	11KV Pole damaged by Lorry at Chittaramma Temple	No
3		UMCC	Crusher	11KV	Medchal	00.30	02.35	02.05	EL	11KV Pole damaged by Lorry at Chittaramma Temple	No
4		UMCC	Mahadevpuram	11KV	Medchal	00.30	02.35	02.05	EL	11KV Pole damaged & Cable failed at Chittaramma Temple	Alternate Supply arranged from Crusher feeder
5		ICICI	SP-I	11KV	Medchal	8:50	10:12	1:22	EL	11KV Line AB Switch Opened at BTIC Company (Internal Problem)	No
1	RR E	Sainikpuri	Kalyan Garden	11KV	Sainikpuri	13:35	14:35	1:00		Breaker Limb Blast at SS Yard. Load Add on Tulasi Garden feeder	No