

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		4		4		4			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	6	0	6	0	6	0	0	
	Grand Total	1082	6468	0	11	0	11	0	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.02.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Marrikal	Kanmankalwa	11KV	Jadcherla	12.50	15.40	02.50		11KV Wire cut near Kanmankalwa	-
1	NLG	Palakaveedu	Nagireddigudam	11KV	Huzurnagar	10.20	12.30	02.10	E/L	11Kv line snapped	-
2		MT.Pally	MT.Pally Town	11KV	Bhongir	12.00	14.00	02.00	EL/OL	11kv Line snapped In MT.Pally Town	-
3		Datherpally	Jangampally	11KV	Bhongir	12.10	14.10	02.00	EL/OL	11kv Line snapped near Mailargadda thanda	-
4		Paladugu	Dattappagudem	11KV	Bhongir	10.30	11.00	00.30	EL/OL	11 kv Line snapped Near Nagulabanda	-
1	MDK	Patancheru -Town	Allwyn	11KV	Patancheru	12.35	13.30	00.55		B/D due to Conductor snapped	-
1	RR S	IJM	New 6th Phase	11KV	Gachibowli	13.07	14.37	01.30	BD	11kv HG Fuse's Cut and 11kv line phase to phase near HIG plot no's - 49, 50, 51.	-
1	RR N	GP Pally	Neighbourhood	11KV	Medchal	10.30	11.10	00.40	BD	11KV Line Melted at AG Side	-
2		ICICI	SP-I	11KV	Medchal	11.12	13.00	01.48	BD	RMU-I Internal Problem at SP-I	-
1	HYD N	Gymkhana	Vasavi Nagar	11KV	Bowenpally	10.45	11.50	01.05	EL,OL-Rph	Tree branches fallen on lines at Plot No.61, Vasavi Nagar	-
2		Osm. University	Ladies Hostel	11KV	Sec-Bad	11.03	12.15	01.12	OL	Brass Patti cut & 3No HG fuses burnt out at Ladies Hostel	-