

Status Report on Breakdowns (Urban / Rural)

Urban

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------|------------------------------|------|------------------------------------|------|-------------------------|------|-------------------------------------|------|--------------------------------|------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | | | | | | | | |
| 6 | RR(N) | 54 | 550 | | 1 | | 1 | | 1 | | | |
| 7 | RR(E) | 168 | 403 | | | | | | | | | |
| 8 | Hyd | 194 | 1044 | 1 | | 1 | | 1 | | | | |
| | Total | 606 | 3055 | 1 | 1 | 1 | 1 | 1 | 1 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|-------------|-------------------------------|------|------------------------------------|------|-------------------------|------|-------------------------------------|------|--------------------------------|------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | | | | | | | | | |
| 2 | NLG | 144 | 988 | | 5 | | 5 | | 5 | | | |
| 3 | MDK | 107 | 933 | | 1 | | 1 | | 1 | | | |
| 4 | SDPT | | | | 1 | | 1 | | 1 | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 0 | 7 | 0 | 7 | 0 | 7 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 1 | 8 | 1 | 8 | 1 | 8 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Date: 11.02.2020

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------------------|--|------|----------------------|-------|-------|----------|------------------|---|--|---------------------------|
| 1 | HYD C | 132KV Erragadda - Hussain Sagar | Hyd.Central, Home Town, Big Bazaar (HT Services) | 33KV | H' Sagar | 09.15 | 15.46 | 06.31 | EL,OL | O/G Lugs cut & Hyd.Central Breaker flash over | Hyd.Central, Home Town, Big Bazaar (HT Services) | No |

TSSPDCL - LMRC / Corporate office

Date: 11.02.2020

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|---------------------------|
| 1 | NLG | Nagaram | N.S Gudem | 11KV | Suryapet | 8:05 | 9:15 | 1:10 | E/L | Jumper cut | No |
| 2 | | Mattapally | Sulthanpuram | 11KV | Huzurnagar | 11.35 | 12.35 | 01.00 | O/L | 11KV Jumper cut | No |
| 3 | | Venkatapuram | Dathaipally | 11KV | Bhongir | 03.10 | 06.10 | 03.00 | E/L | 11KV Disc failed in Sub-station Yard | No |
| 4 | | Pallerla | Kurella | 11KV | Bhongir | 14.55 | 17.00 | 02.05 | E/L | 11KV Insulator failed near Kurella Village SS-1 | No |
| 5 | | Choutuppal | Thangedipally | 11KV | Choutuppal | 4:00 | 9:35 | 5:35 | E/L | 11KV Insulator failed at Golden forest near Thangedipally (V) | No |
| 1 | MDK | Patancheru Town | Kanjarla | 11KV | Patancheru | 2:10 | 3:25 | 1:15 | | Conductor snapped | No |
| 1 | SDPT | Gouravelly | Gubbadi Jangam | 11KV | Husnabad | 6:00 | 9:00 | 3:00 | | Insulator failed | No |
| 1 | RR N | Aliabad | LGM Pet | 11KV | Medchal | 10:20 | 11:00 | 0:40 | | No visible fault | No |